

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PRE-REPAIR INSPECTION REPORT

CS3/ASM21012714/T1qy3e2

Page No.:1 of 1

| | AXA INSURANCE | PTE LTD | Ref: | CS3/ASM21012714/T1qy3e2 |
|------------------------|--|---|---------------------|-------------------------|
| | 8 SHENTON WAY SINGAPORE 0688 | #24-01 AXA TOWER 311 | Date | : 27/01/2022 |
| | ATTN: TEO KITTY | , | Code | e: ASM |
| 1. | Policy Particulars :- (THIRD PARTY CLAIM) | | | |
| | Insured Veh. | SHA 7813A | Veh. Inspected | SLG 4897Z |
| | Policy No. | VFX/P2419138 | Coverage (\$) | 0.00 |
| | Claim No. | S1M03OF8 | Excess (\$) | 0.00 |
| | Assign From | TEO KITTY | Assign Date | 15/12/2021 |
| 2. | Vehicle Particulars & Condition | | | |
| | Make & Model | TOYOTA ISIS 1.8 | c.c | 1794 |
| | Engine No. | HIDDEN | Year of Reg. | 2008 |
| | Chassis No. | ZNM100054072 | Colour | GREY |
| | Odometer | 164102 KM | Steering | IN ORDER |
| | Brakes | IN ORDER | Modification | SPORTS RIM |
| | General | GOOD | | |
| 3. Conditions of Tyres | | | | |
| | | Size | Make | Balance |
| | R/H Front Tyre | 225/40 R18 | YOKOHAMA | 6 mm |
| | L/H Front Tyre | 225/40 R18 | YOKOHAMA | 6 mm |
| | R/H Rear Tyre | 225/40 R18 | YOKOHAMA | 6 mm |
| | L/H Rear Tyre | 225/40 R18 | YOKOHAMA | 6 mm |
| 4. | Description of Damages | | | |
| | THE VEHICLE SU | STAINED DAMAGES AT THE | | |
| 5. General Information | | | | |
| | Accident Date | 11/12/2021 | Inspect Date / Time | 20/12/2021 (04:30 PM) |
| | Survey held at | YAP LEE MOTOR | | |
| | | BLK 1 KAKI BUKIT AVE 6 #01-26 AUTOBAY@KAKI BUKIT SINGAPORE 417883 | | |
| 5a. | Remarks | | | |
| | A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION | | | |

B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.

THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.

C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,500-\$4,500

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 6 Working Days

Report Ref No. CS3/ASM21012714/T1qy3e2

Inspected By

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

Automotive Assessor

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.