

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG21012715/VPA3Q2**Date:** 18/01/2023**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	0999993662
Claimant Vehicle No :	SNB8217M	Insured Vehicle No :	SMG4164T
Date of Loss:	09/12/2021	Nature of Claim:	TP
		Claim No:	8190107197SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SNB8217M	Engine No:	PE10302294
Make & Model:	MAZDA 5, 2.0 5 DR WAGON (A)	Chassis No:	JM6CW1071G0123248
Reg. Date:	27/01/2016 (Man. Year: 2015)	Odometer:	159734 km
Colour:	Blue		
Engine Capacity:	1998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,677.92	2,192.72	2,485.20	53.13
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,340.00	1,380.00	960.00	41.03
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,017.92	3,572.72	3,445.20	49.09
Approved Total (Overridden) (S\$)		2,850.00		
(S\$)	7,017.92	2,850.00	4,167.92	59.39
+ GST 7.00/7.00% (S\$)	491.25	199.50	291.75	59.39
Nett Amount (S\$)	7,509.17	3,049.50	4,459.67	59.39
+ Loss of Use (4.0 x S\$80.00/day) (S\$)		320.00		
Nett Liability (S\$)		3,369.50		
Global Sum Settlement (S\$)		3,360.00		

INSPECTION

Date of Assignment:	10/12/2021	Lee Sheng Auto Pte Ltd (HQ)
Date Inspected:	10/12/2021 Inspected At:	1 Kaki Bukit Avenue 6, #01-58/60 AutoBay@Kaki Bukit
Estimated Period of Repair:	4.0 days	Singapore 417883

Adjuster: Thevan Thomas Karthikesavan**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TRUNK LID	Dented	1,350.00 FL	*1,350.00 FL
2	2		*TRUNK LID HINGES	Serviceable	91.00 FL	*- FL
3	1		*TRUNK LID LOCK	Serviceable	350.00 FL	*- FL
4	1		*TRUNK LID WEATHERSTRIP	Serviceable	186.90 FL	*- FL
5	1		*TRUNK LID INNER BOARD	Serviceable	235.00 FL	*- FL
6	1		*TRUNKLID OUTER GARNISH	Serviceable	280.00 FL	*- FL
7	2		*TRUNKLID SHOCK ABSORBER	Serviceable	410.00 FL	*- FL
8	2		*REAR NUMBER PLATE LAMP	Serviceable	103.20 FL	*- FL
9	1		*REAR WINDSCREEN MOULDING	Necessary	205.50 FL	*90.50 FL
10	1		*REAR BUMPER	Dented	825.60 FL	*825.60 FL
11	2		*REAR BUMPER BRACKET	Necessary	31.60 FL	*31.60 FL
12	2		*REAR BUMPER RETAINER	Necessary	30.40 FL	*30.40 FL
13	1		*REAR BUMPER REINFORCEMENT	Repair	103.40 FL	*- FL
14	1		*REAR LAMP LH	Serviceable	485.00 FL	*- FL
15	1		*REAR END PANEL	Repair	497.30 FL	*- FL
16	1		*REAR END PANEL TOP GARNISH	Serviceable	98.30 FL	*- FL
17	1		*REAR BUMPER TOWING COVER	Not Necessary	26.40 FL	*- FL
18	1		*REAR TRUNKLID MAZDA 5 EMBLEM	Necessary	33.40 FL	*33.40 FL
19	1		*REAR TRUNKLID SKYACTIV EMBLEM	Necessary	33.40 FL	*33.40 FL
20	1		*REAR TRUNKLID LOGO	Necessary	58.50 FL	*58.50 FL
21	1		*SET REVERSE SENSOR	Cut	250.00 FS	*200.00 FS
22	1		*REAR NUMBER PLATE & BASE	Not Necessary	50.00 FS	*- FS
23	2		*WINDSCREEN SEALANT	Necessary	30.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	5,764.90	2,683.40
- List Item Discount on L Items 20.00/20.00% (\$\$)	1,086.98	490.68
Total Parts (\$\$)	4,677.92	2,192.72

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	KNOCKING ,CUTTING ,JACKING WELDING ETC	New	1,000.00	600.00
2	SPRAY PAINTING	New	1,000.00	600.00
3	REMOVE & REFIX WINDSCREEN	New	120.00	120.00
4	TO CHECK WIRING AND SYSTEM FUNCTION	New	100.00	30.00
5	TO APPLY RUST-PROOFING ON AFFECTED AREA	New	120.00	30.00
Gross Labour Cost (S\$)			2,340.00	1,380.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >