

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG21012716/TVCE2

Date: 15/03/2022

REFERENCE

Insured/Claimant:	NG INN THENG	Policy No:	7210032440		
Date of Loss:	10/12/2021	Nature of Claim:	OD	Claim No:	3885587035SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKA9800M		
Make & Model:	AUDI A4, 2.0 TFSI S-TRONIC (A)	Engine No:	DEM028304
Reg. Date:	30/03/2021 (Man. Year: 2020)	Chassis No:	WAUZZZF47MN005701
Colour:	White	Odometer:	14080 km
Engine Capacity:	1984 cc		
Market Value/New Car Price:	S\$140,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/50 R17	Rear Tyre Size:	225/50 R17
Front Left Side:	Hankook 6 mm	Rear Left Side:	Hankook 6 mm
Front Right Side:	Hankook 6 mm	Rear Right Side:	Hankook 6 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	28,616.00	4,460.96	24,155.04	84.41
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,452.00	3,822.00	3,630.00	48.71
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	36,068.00	8,282.96	27,785.04	77.04
- Excess (S\$)	4,100.00	4,100.00	0.00	0.00
(S\$)	31,968.00	4,182.96	27,785.04	86.92
+ GST 7.00/7.00% (S\$)	2,237.76	292.81	1,944.95	86.92
Nett Amount (S\$)	34,205.76	4,475.77	29,729.99	86.92

INSPECTION

Date of Assignment:	16/12/2021		
Date Inspected:	15/12/2021	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	5.0 days		

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	2,233.00 FS	*1,786.40 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	358.00 FS	*- FS
3	2		*FRONT BUMPER SECURING STRIP	Deformed	71.00 FS	*56.32 FS
4	1		*FRONT BUMPER LOWER GRILLE - CENTER	Not Necessary	196.00 FS	*- FS
5	1		*FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	Deformed	262.00 FS	*209.20 FS
6	1		*FRONT BUMPER AIR GUIDE - LH / RH	O/S Not Necessary/ N/S Cracked	88.00 FS	*40.08 FS
7	1		*FRONT BUMPER CLOSING ELEMENT - UPPER CENTRE	Not Necessary	262.00 FS	*- FS
8	1		*FRONT BUMPER AIR GRILLE - LH / RH	N/S Missing	270.00 FS	*108.00 FS
9	2		*FRONT BUMPER AIR GRILLE TRIM - LH / RH	Not Necessary	96.00 FS	*- FS
10	1		*FRONT RADIATOR GRILLE	Not Necessary	1,580.00 FS	*- FS
11	1		*FRONT BUMPER FOAM FILLER PIECE	Not Necessary	189.00 FS	*- FS
12	1		*FRONT BUMPER CARRIER	Not Necessary	845.00 FS	*- FS
13	2		*FRONT BUMPER GUIDE SECTION - LH / RH	Deformed	72.00 FS	*57.44 FS
14	1		*FRONT BUMPER TOP COVER	Not Necessary	127.00 FS	*- FS
15	1		*CAUTION STICKER	Not Necessary	14.00 FS	*- FS
16	1		*A/C STICKER	Not Necessary	8.00 FS	*- FS
17	1		*FRONT LOCK CARRIER BRACKET	Not Necessary	137.00 FS	*- FS
18	2		*FRONT BUMPER SUPPORT - LH / RH	Not Necessary	58.00 FS	*- FS
19	4		*RIVET	Necessary	4.00 FS	*2.56 FS
20	2		*FRONT BUMPER PARKING AID SENSOR - OUTER (NPA)	Not Necessary	0.00 FS	*- FS
21	4		*FRONT PARKING AID SEAL RING	Not Necessary	9.00 FS	*- FS
22	1		*SET FRONT BUMPER WIRING	Not Necessary	577.00 FS	*- FS
23	2		*FRONT FENDER - LH / RH	Bent	2,184.00 FS	*1,747.20 FS
24	1		*FRONT FENDER ATTACHMENT PARTS	Not Necessary	202.00 FS	*- FS
25	2		*FRONT FENDER BRACKET - LH / RH	Not Necessary	70.00 FS	*- FS
26	1		*RIVET (12PCS)	Necessary	40.00 FS	*31.68 FS
27	2		*FRONT FENDER BRACE - LH / RH	Bent	236.00 FS	*188.80 FS
28	2		*FRONT WHEEL HOUSING LINER - LH / RH	Not Necessary	477.00 FS	*- FS
29	2		*FRONT WHEEL SPOILER - LH / RH	Not Necessary	146.00 FS	*- FS
30	2		*FRONT WHEEL SPOILER TRIM - LH / RH	Not Necessary	71.00 FS	*- FS
31	2		*FRONT FENDER TOP COVER - LH / RH	Necessary	62.00 FS	*49.28 FS
32	2		*FRONT HEADLIGHT TOP COVER - LH / RH	Necessary	88.00 FS	*68.96 FS
33	2		*FRONT HEADLIGHT	Not Necessary	15,370.00 FS	*- FS
34	2		*FRONT HEADLIGHT LIFT CYLINDER - LH / RH	Not Necessary	420.00 FS	*- FS
35	2		*FRONT HEADLIGHT LIFT CYLINDER BRACKET	Not Necessary	12.00 FS	*- FS
36	1		*A/C CORRUGATED PIPE (NPA)	Not Necessary	0.00 FS	*- FS
37	4		*A/C REFRIGERANT PIPE	Not Necessary	1,278.00 FS	*- FS
38	1		*FRONT NO. PLATE	Not Necessary	60.00 FS	*- FS
39	1		*SUNDRIES	Not Necessary	300.00 FS	*- FS
40	2		*FRONT FENDER CLOSING ELEMENT - LH / RH	Deformed	144.00 FS	*115.04 FS

F=Franchise part. S=SpcNett.

Total Parts (S\$) 28,616.00 4,460.96

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
2	TO REMOVE AND TRANSFER BOTH HEADLIGHTS CONTROL UNIT AND POWER MODULE	New	700.00	0.00
3	TO RENEW LHS FRONT FENDER INNER AIRCON PIPES. TO CARRY OUT VACUUM AND REGAS	New	280.00	0.00
4	TO DISMANTLE AND RENEW FRONT BUMPER, BOTH FRONT FENDER AND BOTH HEADLIGHT. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	2,800.00	1,500.00
5	TO RESPRAY FRONT BUMPER AND BOTH FRONT FENDER	New	3,000.00	1,650.00
6	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (\$\$)			7,452.00	3,822.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >