

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/TMI21012717/VQF3N2**Date:** 27/12/2021**REFERENCE**

Handling Insurer:	Tokio Marine Insurance Singapore Ltd	Policy No:	MQ003237		
Claimant Vehicle No :	SHA8666B	Insured Vehicle No :	SLE7620X		
Date of Loss:	14/12/2021	Nature of Claim:	TP	Claim No:	M2105812

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHA8666B	Engine No:	G4LEJU167088
Make & Model:	HYUNDAI IONIQ HYBRID, 1.6 GLS DCT (A)	Chassis No:	KMHC851CVKU133736
Reg. Date:	01/03/2019 (Man. Year: 2018)	Odometer:	222467 km
Colour:	Yellow		
Engine Capacity:	1580 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	Average

CONDITION OF TYRES

Front Tyre Size:	195/65R15	Rear Tyre Size:	195/65R15
Front Left Side:	West Lake 5 mm	Rear Left Side:	DURATURN 5 mm
Front Right Side:	West Lake 5 mm	Rear Right Side:	DURATURN 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	756.88	339.36	417.52	55.16
Miscellaneous Items	11.00	11.00	0.00	0.00
Labour	1,350.00	1,220.00	130.00	9.63
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	2,117.88	1,570.36	547.52	25.85
+ GST 7.00/7.00% (S\$)	148.25	109.93	38.32	25.85
Nett Amount (S\$)	2,266.13	1,680.29	585.84	25.85

INSPECTION

Date of Assignment:	16/12/2021	Present Location:	ComfortDelGro Engineering Pte Ltd (Loyang)
Date Inspected:	15/12/2021	Inspected At:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive Singapore 508969
Estimated Period of Repair:	3.0 days		

Adjuster: Thevan Thomas Karthikesavan**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 23 Dec 2021)

Parts: 192 HYUNDAI IONIQ HYBRID 1.6 GLS DCT (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SHA8666B)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Reference	Amount
1	1		*REAR BUMPER ASSY	Repair	459.40 FL	-	*- FL
2	10		*REAR BUMPER CLIPS	Necessary	22.00 FL	-	*22.00 FL
3	1		*REAR WHEEL CAP	Scratched	346.40 FL	-	*346.40 FL
4	1		*REAR BUMPER MAT	Serviceable	50.00 F	-	*- FS
5	1		*REAR BUMPER SIDE BRACKET RH	Necessary	55.80 FL	-	*55.80 FL
					Sub Total (\$\$)	933.60	424.20
					- List Item Discount on L Items 20.00/20.00% (\$\$)	176.72	84.84
					Total Parts (\$\$)	756.88	339.36

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	OD/TP Case (Insurer)	11.00	11.00
Sub Total (\$\$)			11.00	11.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	700.00	700.00
2	SPRAYPAINT	New	600.00	500.00
3	REMOVE / REFIX REVERSE SENSOR	New	50.00	20.00
Gross Labour Cost (\$\$)			1,350.00	1,220.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >