

REG BY: Thevan

CS/TMI 2612717/V9f3

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
OD/TP/WS/TP RES/OD RES/EVA/INV/MV
 To Inspect Vehicle No: _____
 at Workshop m/s _____
 of _____
 Insured: _____
 Policy No. _____
 Claims No. M2105812
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S
///	///

Bal. or Market Value: _____
 IDAC Accident Report: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs. 3 days ☒ Res.: Yes or No
 Lum Sum: _____ % ☒ 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SHA8666B ✓ Yr Rogn: 13 119
 Type: M.Car / M.Cycle / Bus / Van / Lorry / (Tax) / Prime Mover /
 Truck / Trailer or
 Make: Hyundai 1019 c.c. 1580
 Colour: 222467 AC: Insured / Std / NI / NA
 Sp. Reading 100 Yellow T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: kmHC85/cuku/33736
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Good / Jammed / Leaked / Burnt or
 Brake: Good / Jammed / Leaked / Burnt or
 Mod: Nil / (S/R) / STD A/R/m or
 Tyre Size: F: 195/65 R15
 R: 195/65 R15 duraturn
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or Westlake
 Front _____ Rear _____
 R/Bal. 5 mm R/Bal. 5 mm
 L/Bal. 5 mm L/Bal. 5 mm
 D.O.A. 14/12/21 D.O.I. 18/12/21 1645
 Survey held at CDDE
 Des. of Damages: Frl / Rea / O/S / N/S / U/C / Rooftop or
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>NO GJA given</u>
<u>17/12/21</u>	<u>@ 1.25pm revised to Pei Li via Merimen.</u>
<u>17/12/21</u>	<u>Thevan finalised with Jumani final fig \$1570.36, 3 days. (Red \$547.52, 26%)</u>

Date/Time File Pass to? ☐ : Prel. Report
22/12 Typist ☐ : Final Report
 Date/Time File Return to? _____

Days Of Repair: 3
 Resurvey No. of Trip: 1

Survey Fee:	
Transportation:	
S + P.S. SI	
Pinus	
Others	
Total	

Add Fee: ☐ : Site Insp (\$ _____)
☐ : Interview (\$ _____)
☐ : Tech. Invs (\$ _____)
☐ : Wash end (\$ _____)

Request Form: MER-TP
1570.36

Date/Time: 15.12.2021 14:31

Page : 1

am: ARC Repair TP(CFS0)1

JOB CARD Sales Order: 4152295

JC NO305498021

OMER

IS CITYCAB PTE LTD
OMER NO. 7010070
ESS 383 SIN MING DRIVE
Singapore SINGAPORE 575717
(R) 65551188 (O)
(P)

DUNT CARD NO.

REGN NO:

SHA8666B

MILEAGE

MAKE:

HYUNDAI

FUEL

E.....1/2.....F

MODEL

IONIQ(G2)

DATE/TIME IN 15.12.2021 10:15

YR OF MANU.

01.03.2019

TARGET DATE

CHASSIS CODE

KMHC851CVKU133736

COMPLETION DATE/TIME:

JOB DESCRIPTION


Accident Date: 14.12.2021

ATURE: 3P.14.12.2021/C

NO

LABOR CODE

DESCRIPTION



RECEIVED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Damage Report Slip

Exit Pass

Vehicle No.: SHA8666B

JU TOKIO

Vehicle No.:

SHA8666B

Service Advisor

Signature/Date

Name of Service Advisor

Date

Returned to Service Reception upon collection

To be kept by Security Guard

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
Miscellaneous Items			
1	1	OD/TP Case (Insurer)	11.00
Sub Total (S\$)			11.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	PANEL BEATING	New	700.00
2	SPRAYPAINT	New	500 600.00
3	REMOVE / REFIX REVERSE SENSOR	New	20 50.00
Gross Labour Cost (S\$)			1,350.00

ComfortDelGro Engineering Pte Ltd/SHA8666B/15/12/2021 14:41. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Thuvan@lkkauto.len
822 35769
15/12/21 1645
P/p ~~1/2~~ after repair photo
3 days wp ✓

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

REPAIR DETAILS**Reference****Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 15 Dec 2021)**Parts:** 192 HYUNDAI IONIQ HYBRID 1.6 GLS DCT (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** ComfortDelGro Engineering Pte Ltd/SHA8666B/15/12/2021 14:41**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*REAR BUMPER ASSY	20.00	0.00	r X *459.40 FL
2	10		*REAR BUMPER CLIPS	20.00	0.00	nec *22.00 FL
3	1		*REAR WHEEL CAP	20.00	0.00	scr *346.40 FL
4	1		*REAR BUMPER MAT	0.00	0.00	SVL X *50.00 F
5	1		*REAR BUMPER SIDE BRACKET RH	20.00	0.00	nec *55.80 FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)

933.60

- List Item Discount on L Items (\$\$)

176.72

Total Parts (\$\$)

756.88

ComfortDelGro Engineering Pte Ltd/SHA8666B/15/12/2021 14:41. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

ComfortDelGro Engineering Pte Ltd (Co.Reg.No:199506048W)

59 Loyang Drive
Singapore 508969
Tel: 6214 8300

TP INSURER:
CCPL

Tokio Marine Insurance Singapore Ltd (HQ)



Singapore

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	14/12/2021
Vehicle Reg. No.:	SHA8666B	Driveable?	YES
Party At Fault:	UNKNOWN		
Make/Model:	HYUNDAI IONIQ HYBRID, 1.6 GLS DCT (A)	Vehicle Reg. Date:	01/03/2019
Vehicle Colour:	YELLOW	Gen Condition:	GOOD
Engine No:	G4LEJU167088	Chassis No:	KMHC851CVKU133736
Odometer:	0 KM		
Paint Type:			
List Item Discount:	20.00 %		
Total Loss?	NO		
Est. Duration of Repair (day)	4		
Present Location:	COMFORTDELGRO ENGINEERING PTE LTD (LOYANG)		

COST OF CLAIMS

	Amount
Parts	756.88
Miscellaneous Items	11.00
Labour	1,350.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	2,117.88
+ GST 7.00% (S\$)	148.25
Nett Amount (S\$)	2,266.13

This claim is handled by: JUMANI BIN MASUDIN

Generated using Merimen e-Claims Internet Estimation & Adjusting System