

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #07-16
Singapore 079120

Our File No: CS4/AIG21012722/DVF3E2**Date:** 17/07/2023**REFERENCE**

Insured/Claimant:	TAN YEN SENG	Policy No:	2070144125	
Date of Loss:	21/10/2021	Nature of Claim:	OD	Claim No: 6723766784SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJG2020Z		
Make & Model:	MERCEDES-BENZ A180, 1.6 (A)	Engine No:	28291480352860
Reg. Date:	13/10/2020 (Man. Year: 2020)	Chassis No:	W1K1771842J209568
Colour:	Silver	Odometer:	0 km
Engine Capacity:	1332 cc		
Market Value/New Car Price:	S\$135,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/45 R18	Rear Tyre Size:	225/45 R18
Front Left Side:	Hankook 5 mm	Rear Left Side:	Hankook 5 mm
Front Right Side:	Hankook 5 mm	Rear Right Side:	Hankook 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	66,551.02	54,570.65	11,980.37	18.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	22,340.00	17,372.00	4,968.00	22.24
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	88,891.02	71,942.65	16,948.37	19.07
+ GST 8.00/8.00% (S\$)	7,111.28	5,755.41	1,355.87	19.07
Nett Amount (S\$)	96,002.30	77,698.06	18,304.24	19.07

INSPECTION

Date of Assignment:	16/12/2021	
Date Inspected:	15/12/2021	Inspected At: Cycle & Carriage Industries Pte Ltd (Pandan Loop) 188 Pandan Loop Singapore 128378
Estimated Period of Repair:	28.0 days	

Adjuster: BRYAN TANI**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*IU BRACKET	Necessary	26.00 FS	*26.00 FS
2	1		*THINKWARE DASHCAM F770	Necessary	900.00 FS	*900.00 FS
3	1		*FRONT W/SCREEN	Necessary	504.00 FS	*504.00 FS
4	1		*INSTRUMENT PANEL	Burnt	1,642.90 F	*1,642.90 F
5	1		*GLOVE COMPARTMENT HOUSING	Burnt	567.01 F	*567.01 F
6	1		*DASHBOARD TRIM STRIP	Damaged	697.80 F	*697.80 F
7	1		*DASHBOARD TRIM	Damaged	277.67 F	*277.67 F
8	1		*DASHBOARD TRIM STRIP	Damaged	179.50 F	*179.50 F
9	1		*DASHBOARD TRIM	Not Necessary	173.42 F	*- F
10	1		*DASHBOARD TRIM, FOOTWELL	Burnt	122.88 F	*122.88 F
11	1		*DASHBOARD TRIM, FOOTWELL	Burnt	66.53 F	*66.53 F
12	2		*INTERIOR LAMP	Burnt	145.39 F	*112.70 F
13	1		*CENTER CONSOLE	Burnt	627.11 F	*627.11 F
14	1		*CENTER CONSOLE COVER TRIM	Not Necessary	94.15 F	*- F
15	1		*CENTER CONSOLE TRIM	Burnt	528.44 F	*528.44 F
16	1		*CENTER CONSOLE ARMREST	Burnt	502.78 F	*502.78 F
17	1		*CENTER CONSOLE COVER, LID	Burnt	120.50 F	*120.50 F
18	1		*CENTER CONSOLE COVER TRIM	Not Necessary	14.08 F	*- F
19	1		*INSERT, STOWAGE CMPRT	Not Necessary	34.80 F	*- F
20	1		*BEVERAGE HOLDER	Not Necessary	71.03 F	*- F
21	1		*LINING, RIGHT FRONT FLOOR	Burnt	394.60 F	*394.60 F
22	1		*LINING, LEFT FRONT FLOOR	Burnt	394.49 F	*394.49 F
23	1		*LUGGAGE NET	Not Necessary	66.27 F	*- F
24	1		*RIGHT FRONT TRIM, FOOTWELL	Not Necessary	116.65 F	*- F
25	1		*LEFT FRONT TRIM, FOOTWELL	Not Necessary	116.62 F	*- F
26	1		*HOUSING, AIR CONDITIONER	Burnt	840.29 F	*840.29 F
27	1		*HOSE LINE	Burnt	13.18 F	*13.18 F
28	1		*HEAT EXCHANGER	Burnt	353.18 F	*353.18 F
29	1		*PARTICLE FILTER CAP	Burnt	20.66 F	*20.66 F
30	1		*FINE PARTICLE FILTER	Burnt	159.40 F	*159.40 F
31	1		*EVAPORATOR HOUSING	Burnt	930.02 F	*637.21 F
32	1		*RADIAL BLOWER, MECHANICAL	Burnt	637.21 F	*637.21 F
33	1		*STEERING WHEEL	Damaged	1,403.22 F	*1,403.22 F
34	1		*SWITCH PANEL WITH FNPAD	Damaged	460.79 F	*460.79 F
35	1		*DRIVERS AIRBAG	Damaged	1,994.60 F	*1,994.60 F
36	1		*COVER, STEERING WHEEL	Damaged	225.36 F	*225.36 F
37	1		*BATTERY 1.2 AH	Damaged	168.64 F	*168.64 F
38	1		*KNEE AIRBAG	Damaged	820.97 F	*820.97 F
39	1		*MEDIA HARD DRIVE	Not Necessary	1,108.93 F	*- F
40	1		*COMMUNICATION MODULE CONTROL UNIT	Not Necessary	1,403.93 F	*- F
41	1		*HEAD UNIT CONTROL UNIT	Damaged	5,959.04 F	*5,959.04 F
42	1		*STEERING LOCK CONTROL UNIT	Damaged	406.05 F	*406.05 F
43	1		*CHARGING CONTROL UNIT	Damaged	532.91 F	*532.91 F
44	1		*BRACKET	Not Necessary	122.73 F	*- F
45	1		*BRACKET	Not Necessary	10.68 F	*- F
46	1		*AMBIENT LIGHTING CONTROL UNIT	Not Necessary	283.24 F	*- F
47	1		*BRACKET	Not Necessary	43.42 F	*- F
48	1		*BRACKET	Not Necessary	17.78 F	*- F
49	1		*DRIVE-TRAIN CONTROL UNIT	Damaged	556.04 F	*556.04 F
50	1		*IGNITION SWITCH CONTROL UNIT	Damaged	1,591.75 F	*1,591.75 F
51	1		*PARKTRONIC CONTROL UNIT	Necessary	1,293.05 F	*1,293.05 F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
52	1		*FRONT SAM CONTROL UNIT	Damaged	693.27 F	*693.27 F
53	1		*RELAY UNIT	Necessary	259.42 F	*259.42 F
54	1		*RELAY UNIT	Necessary	25.93 F	*25.93 F
55	1		*RELAY UNIT	Necessary	25.93 F	*25.93 F
56	1		*RELAY UNIT	Necessary	25.93 F	*25.93 F
57	1		*RELAY UNIT	Necessary	25.93 F	*25.93 F
58	1		*RELAY UNIT	Necessary	25.93 F	*25.93 F
59	1		*RELAY UNIT	Necessary	25.93 F	*25.93 F
60	1		*RELAY UNIT	Necessary	25.93 F	*25.93 F
61	1		*RELAY UNIT	Necessary	25.93 F	*25.93 F
62	1		*RELAY UNIT	Necessary	25.93 F	*25.93 F
63	1		*NUT	Not Necessary	1.78 F	*- F
64	1		*RELAY UNIT	Necessary	25.93 F	*25.93 F
65	1		*RELAY UNIT	Necessary	25.93 F	*25.93 F
66	1		*RELAY	Not Necessary	40.68 F	*- F
67	1		*RELAY	Not Necessary	37.40 F	*- F
68	2		*FUSE LINK	Not Necessary	11.36 F	*- F
69	1		*INSTRUMENTAL CLUSTER CONTROL UNIT	Necessary	1,423.19 F	*1,187.45 F
70	1		*BRACKET	Necessary	145.40 F	*126.30 F
71	1		*ELECTRICAL WIRING HARNESS	Not Necessary	198.05 F	*- F
72	1		*INTERIOR LAMP (NPA)	Not Necessary	0.00 F	*- F
73	1		*ELECTRICAL WIRING HARNESS	Not Necessary	56.32 F	*- F
74	1		*ELECTRICAL WIRING HARNESS	Burnt	199.40 F	*125.16 F
75	1		*ELECTRICAL WIRING HARNESS	Burnt	9,888.17 F	*9,888.17 F
76	1		*RADIO/INSTRUMENT DISPLAY	Damaged	3,797.32 F	*3,797.32 F
77	1		*SRS CONTROL UNIT	Burnt	217.02 F	*217.02 F
78	1		*MULTIMEDIA CON. UNIT	Not Necessary	115.72 F	*- F
79	1		*TOUCH PAD CONTROL UNIT	Damaged	788.89 F	*788.89 F
80	1		*MULTIMEDIA CON. UNIT	Damaged	144.56 F	*144.56 F
81	1		*MULTIMEDIA CON. UNIT	Not Necessary	115.72 F	*- F
82	1		*MOBILE PHONE CRADLE	Damaged	16.48 F	*16.48 F
83	1		*SWITCH BLOCK	Necessary	461.41 F	*461.41 F
84	1		*SWITCH BLOCK	Not Necessary	169.18 F	*- F
85	1		*STEERING COLUMN SIGNAL CONTROL UNIT	Damaged	759.82 F	*759.82 F
86	1		*BUTTON SWITCH	Damaged	85.13 F	*85.13 F
87	1		*DAMPING MAT FIREWALL	Burnt	208.71 F	*208.71 F
88	1		*DAMPING MAT FLOOR PANEL	Not Necessary	38.00 F	*- F
89	1		*RIGHT FRONT SEAT RAIL HEIGHT ADJUSTMENT	Not Necessary	1,592.20 F	*- F
90	1		*LEFT FRONT SEAT RAIL HEIGHT ADJUSTMENT	Not Necessary	1,592.20 F	*- F
91	1		*RIGHT FRONT SEAT CONTROL UNIT, COMPLETE	Damaged	526.04 F	*526.04 F
92	1		*LEFT FRONT SEAT CONTROL UNIT, COMPLETE	Damaged	299.44 F	*299.44 F
93	1		*RIGHT FRONT SEAT LONGITUDINAL, ADJUSTMENT	Not Necessary	123.41 F	*- F
94	1		*LEFT FRONT SEAT LONGITUDINAL ADJUSTMENT	Not Necessary	123.41 F	*- F
95	1		*TPMS CONTROL UNIT	Not Necessary	474.05 F	*- F
96	1		*BRAKE PEDAL ASSEMBLY	Not Necessary	195.25 F	*- F
97	1		*BRAKE LIGHT SWITCH	Not Necessary	51.77 F	*- F
98	1		*ACCELERATOR PEDAL MODULE	Not Necessary	240.34 F	*- F
99	2		*FRONT DOOR EDGE GUARD	Not Necessary	234.61 F	*- F
100	1		*RIGHT TRIM, A-PILLAR	Not Necessary	102.57 F	*- F
101	1		*LEFT TRIM, A-PILLAR	Not Necessary	107.97 F	*- F
102	1		*LEFT TRIM, B-PILLAR	Not Necessary	114.70 F	*- F
103	1		*RIGHT TRIM, B-PILLAR	Not Necessary	108.31 F	*- F
104	1		*LEFT LOWER TRIM, B-PILLAR	Not Necessary	60.14 F	*- F
105	1		*RIGHT LOWER TRIM, B-PILLAR	Not Necessary	57.42 F	*- F
106	1		*HEADLINER	Not Necessary	1,133.05 F	*- F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
107	1		*AIR-CON CONTROL UNIT	Not Necessary	461.41 F	*- F
108	1		*AIR-CON DUCT	Burnt	17.05 F	*17.05 F
109	1		*AIR-CON DUCT	Burnt	19.79 F	*19.79 F
110	1		*AIR-CON DUCT	Not Necessary	45.21 F	*- F
111	1		*AIR-CON DUCT	Not Necessary	45.83 F	*- F
112	3		*CENTER AIR-CON AIR VENT	Damaged	541.89 F	*541.89 F
113	1		*RIGHT AIR-CON AIR VENT	Damaged	181.96 F	*181.96 F
114	1		*LEFT AIR-CON AIR VENT	Damaged	181.62 F	*181.62 F
115	1		*FRONT WINDSHIELD	Damaged	667.93 F	*667.93 F
116	1		*FRONT W/SCREEN SEALING STRIP (4PCS)	Necessary	11.30 F	*11.30 F
117	2		*DNE-COMPONENT ADHESIVE	Necessary	330.86 F	*330.86 F
118	1		*RAIN AND LIGHT SENSOR	Necessary	342.10 F	*342.10 F
119	1		*FRONT W/SCREEN SOLAR FILM	Necessary	300.00 FS	*300.00 FS
120	1		*FLOOR MAT	Burnt	184.75 FS	*184.75 FS
121	1		*HOLE PLUG (2PCS)	Necessary	2.27 FS	*2.27 FS
122	1		*STEERING COLUMN	Rusted	1,466.47 FS	*1,466.47 FS
123	1		*HEXALOBULAR BOLT (4PCS)	Rusted	11.09 FS	*11.09 FS
124	1		*SOCKET	Damaged	34.78 FS	*34.78 FS
125	1		*STOWAGE CMPRT. CENT. CONS	Damaged	10.92 FS	*10.92 FS
126	1		*LINING, REAR FLOOR	Burnt	1,323.16 FS	*1,323.16 FS
127	1		*BRACKET	Damaged	26.58 FS	*26.58 FS
128	1		*HEXAGON NUT (3PCS)	Damaged	10.10 FS	*10.10 FS
129	1		*RELAY SLOT L 40A	Necessary	25.07 FS	*25.07 FS
130	1		*INTERIOR LAMP	Damaged	89.62 FS	*89.62 FS
131	1		*HEXAGON NUT WITH FLANGE (3PCS)	Necessary	6.61 FS	*6.61 FS
132	1		*ANTENNA	Damaged	93.74 FS	*93.74 FS
133	1		*TEMPERATURE SENSOR	Damaged	282.13 FS	*282.13 FS
134	1		*HEXAGON HEAD BOLT	Necessary	1.41 FS	*1.41 FS
135	1		*HEX, HEAD BOLT W. FLANGE (5PCS)	Necessary	33.21 FS	*33.21 FS
136	1		*CROSSMEMBER BEHIND DASHBOARD	Rusted	940.63 FS	*940.63 FS
137	1		*FRONT PASSENGER AIRBAG	Contaminated	1,672.66 FS	*1,672.66 FS
138	1		*COVER, SWIVEL BEARING	Rusted	22.39 FS	*22.39 FS
139	1		*PLUG SOCKET	Damaged	5.94 FS	*5.94 FS
140	1		*SCREW	Necessary	14.59 FS	*14.59 FS
141	1		*LOCK CLIP (2PCS)	Necessary	10.91 FS	*10.91 FS
142	1		*HEXALOBULAR BOLT (4PCS)	Damaged	36.97 FS	*36.97 FS
143	1		*FILLISTER HEAD SCREW (4PCS)	Necessary	6.34 FS	*6.34 FS
144	1		*SOCKET	Damaged	2.65 FS	*2.65 FS
145	1		*SCREW (4PCS)	Necessary	24.30 FS	*24.30 FS
146	1		*SOCKET	Damaged	28.58 FS	*28.58 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) **66,551.02** **54,570.65**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE & INSTALL INSTRUMENT PANEL	New	2,688.00	2,016.00
2	RESPRAY FLOOR PANEL AND FIREWALL	New	1,800.00	1,200.00
3	USING XENTRY SYSTEM TO CHECK CONTROL UNITS, RESET SYSTEM TO STANDARD SETTINGS	New	380.00	380.00
4	REMOVE, REFIT, REPLACE A/C BLOWER, A/C COIL UNIT AND HEATER UNIT. RE-CHARGE A/C GAS	New	2,016.00	1,344.00
5	TO REMOVE BURNT DEBRIS, CHEMICAL WASH TO CLEAN UP INTERIOR CABIN	New	1,344.00	1,008.00
6	REMOVE AND REFIT FLOOR CARPETS, CENTER CONSOLE, FRONT SEATS, TRIMS AND GARNISHS	New	2,016.00	1,344.00
7	REPLACE MAIN WIRE HARNESS, FUSE BOX, CAN-LINE AND CONTROL UNITS	New	12,096.00	10,080.00
Gross Labour Cost (\$\$)			22,340.00	17,372.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >