



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SJG2020Z

AIG Asia Pacific Insurance Pte.
Ltd.
MOTOR CLAIM DEPARTMENT
78 SHENTON WAY #09-16
AIG BUILDING
SINGAPORE 079120
64191000

Vehicle & Document Information

WIP No 54030
Reg No/Reg Date SJG2020Z / 13/10/2020
Date In/Mileage / 0
Chassis No W1K1771842J2095682
Engine No 28291480352860
Make/Model MB/A 180
Colour/Trim 028 859 Mojave Silv/ 041 101 ARTICO Blac

Account No	Terms	Date/Time Printed	CSE	Operator	Description of Goods / Services	Qty	Unit Price	Disc%	Amount
WA000007	Credit	15/12/2021/ 13:03	YK	395 / Yik Chan Hoe					
Z REQUEST									
Customer Request									
M BPNSUN									
POLICY NO/ACC DATE : 2070144125 // 21/10/2021									
DRIVE IN/EXCESS : TOW IN 21/10/2021 // TBA									
DATE IN/DATE SURVEY:									
BY/AUTHORIZED ON :									
S BPNSUB					INSTALL SOLAR FILM ON FRONT W/SCREEN <i>Hec</i>				300.00 ✓
A BPILAB					REMOVE & INSTALL INSTRUMENT PANEL	30.00	2016		2688.00
A BPIRES					RESPRAY FLOOR PANEL AND FIREWALL.				1200/-1800.00
A BPILAB					USING XENTRY SYSTEM TO CHECK CONTROL UNITS, RESET SYSTEM TO STANDARD SETTINGS. NETT	0.10			380.00 ✓
A BPILAB					REMOVE AND REFIT FLOOR CARPETS, CENTER CONSOLE, FRONT SEATS, TRIMS AND GARNISHS.	30.00	1344/-		2016.00
A BPILAB					REPLACE MAIN WIRE HARNESS, FUSE BOX, CAN-LINE AND CONTROL UNITS.	30.00	10080/-		12086.00
A BPILAB					REMOVE, REFIT, REPLACE A/C BLOWER, A/C COIL UNIT AND HEATER UNIT. RE-CHARGE A/C GAS.	30.00	1344/-		2016.00
A BPILAB					TO REMOVE BURNT DEBRIS, CHEMICAL WASH TO CLEAN UP INTERIOR CABIN.	30.00	10080/-		1344.00
M BPNSUN					1 PC IU BRACKET <i>Hec</i>				26.00 ✓
D DCZF770					THINKWARE DASHCAM F770. <i>Hec</i>				900.00 ✓
A BPILAB					REPLACE FRONT W/SCREEN <i>Dash Hec</i>	30.00			352.80 ✓

Confirmed & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SJG2020Z

AIG Asia Pacific Insurance Pte.
Ltd.
MOTOR CLAIM DEPARTMENT
78 SHENTON WAY #09-16
AIG BUILDING
SINGAPORE 079120
64191000

Vehicle & Document Information

WIP No 54030
Reg No/Reg Date SJG2020Z / 13/10/2020
Date In/Mileage / 0
Chassis No W1K1771842J2095682
Engine No 28291480352860
Make/Model MB/A 180
Colour/Trim 028 859 Mojave Silv/ 041 101 ARTICO Blac

Account No	Terms	Date/Time Printed	CSE	Operator	
WA000007	Credit	15/12/2021/ 13:03	YK	395 / Yik Chan Hoe	
Description of Goods / Services		Qty	Unit Price	Disc%	Amount
M INSTRUMENT PANEL	Burnt	1.00	1825.44	10.00	1642.90
M GLOVE COMPARTMENT HOUSING	Burnt	1.00	605.50	10.00	544.95
M DASHBOARD TRIM STRIP	Dem	1.00	775.33	10.00	697.80
M DASHBOARD TRIM	Dem	1.00	308.52	10.00	277.67
M DASHBOARD TRIM STRIP	Dem	1.00	199.45	10.00	179.50
M DASHBOARD TRIM	Burnt	1.00	192.69	10.00	173.42
M DASHBOARD TRIM, FOOTWELL	Burnt	1.00	73.92	10.00	66.53
M DASHBOARD TRIM, FOOTWELL	Burnt	1.00	73.92	10.00	66.53
M INTERIOR LAMP	Burnt	2.00	80.77	10.00	145.39
M CENTER CONSOLE	Burnt	1.00	696.79	10.00	627.11
M CENTER CONSOLE COVER TRIM	Burnt	1.00	104.61	10.00	94.15
M CENTER CONSOLE TRIM	Burnt	1.00	587.16	10.00	528.44
M CENTER CONSOLE ARMREST	Burnt	1.00	558.64	10.00	502.78
M CENTER CONSOLE COVER, LID	Burnt	1.00	133.89	10.00	120.50
M CENTER CONSOLE COVER TRIM	Burnt	1.00	15.64	10.00	14.08
M INSERT, STOWAGE CMPRT.	Burnt	1.00	38.67	10.00	34.80
M BEVERAGE HOLDER	Burnt	1.00	78.92	10.00	71.03
M LINING, RIGHT FRONT FLOOR	Burnt	1.00	0.00	00.00	?
M LINING, LEFT FRONT FLOOR	Burnt	1.00	438.32	10.00	394.49
M LUGGAGE NET	Burnt	1.00	73.63	10.00	66.27
M RIGHT FRONT TRIM, FOOTWELL	Burnt	1.00	129.61	10.00	116.65
M LEFT FRONT TRIM, FOOTWELL	Burnt	1.00	129.58	10.00	116.62
M HOUSING, AIR CONDITIONER	Burnt	1.00	895.58	10.00	806.02
M HOSE LINE	Burnt	1.00	14.64	10.00	13.18
M HEAT EXCHANGER	Burnt	1.00	392.42	10.00	353.18
M PARTICLE FILTER CAP	Burnt	1.00	22.96	10.00	20.66
M FINE PARTICLE FILTER	Burnt	1.00	169.04	10.00	152.14
M EVAPORATOR HOUSING	Burnt	1.00	1033.36	10.00	930.02
M RADIAL BLOWER, MECHANICAL	Burnt	1.00	708.01	10.00	637.21
M STEERING WHEEL	Dem	1.00	1347.07	10.00	1212.36
M SWITCH PANEL WITH FNPAD	Dem	1.00	511.99	10.00	460.79
M DRIVER'S AIRBAG	Dem	1.00	1792.88	10.00	1613.59
M COVER, STEERING WHEEL	Dem	1.00	244.06	10.00	219.65

Confirmed & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8368
Fax: 6779 5383
www.mercedes-benz.com.sg



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SJG2020Z

AIG Asia Pacific Insurance Pte.
Ltd.
MOTOR CLAIM DEPARTMENT
78 SHENTON WAY #09-16
AIG BUILDING
SINGAPORE 079120
64191000

Vehicle & Document Information

WIP No 54030
Reg No/Reg Date SJG2020Z / 13/10/2020
Date In/Mileage 0
Chassis No W1K1771842J2095682
Engine No 28291480352860
Make/Model MB/A 180
Colour/Trim 028 859 Mojave Silv/ 041 101 ARTICO Blac

Account No	Terms	Date/Time Printed	CSE	Operator
WA000007	Credit	15/12/2021/ 13:03	YK	395 / Yik Chan Hoe

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M BATTERY 1.2 AH	1.00	187.38	10.00	168.64
M KNEE AIRBAG	1.00	912.19	10.00	820.97
M MEDIA HARD DRIVE	1.00	1232.14	10.00	1108.93
M COMMUNICATION MODULE CONTROL UNIT	1.00	1559.92	10.00	1403.93
M HEAD UNIT CONTROL UNIT	1.00	6621.16	10.00	5959.04
M STEERING LOCK CONTROL UNIT	1.00	451.17	10.00	406.05
M CHARGING CONTROL UNIT	1.00	592.12	10.00	532.91
M BRACKET	1.00	136.37	10.00	122.73
M BRACKET	1.00	11.87	10.00	10.68
M AMBIENT LIGHTING CONTROL UNIT	1.00	314.71	10.00	283.24
M BRACKET	1.00	48.25	10.00	43.42
M BRACKET	1.00	19.76	10.00	17.78
M DRIVE-TRAIN CONTROL UNIT	1.00	617.82	10.00	556.04
M IGNITION SWITCH CONTROL UNIT	1.00	1552.57	10.00	1397.31
M PARKTRONIC CONTROL UNIT	1.00	1436.72	10.00	1293.05
M FRONT SAM CONTROL UNIT	1.00	744.76	10.00	670.28
M RELAY UNIT	1.00	288.25	10.00	259.42
M RELAY UNIT	1.00	28.81	10.00	25.93
M RELAY UNIT	1.00	28.81	10.00	25.93
M RELAY UNIT	1.00	28.81	10.00	25.93
M RELAY UNIT	1.00	28.81	10.00	25.93
M RELAY UNIT	1.00	28.81	10.00	25.93
M RELAY UNIT	1.00	28.81	10.00	25.93
M RELAY UNIT	1.00	28.81	10.00	25.93
M RELAY UNIT	1.00	28.81	10.00	25.93
M RELAY UNIT	1.00	28.81	10.00	25.93
M NUT	1.00	1.98	10.00	1.78
M RELAY UNIT	1.00	28.81	10.00	25.93
M RELAY UNIT	1.00	28.81	10.00	25.93
M RELAY	1.00	45.20	10.00	40.68
M RELAY	1.00	41.56	10.00	37.40
M FUSE LINK	2.00	6.31	10.00	11.36
M INSTRUMENTAL CLUSTER CONTROL UNIT	1.00	1581.32	10.00	1423.19

Confirmed & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SJG2020Z

AIG Asia Pacific Insurance Pte.
Ltd.
MOTOR CLAIM DEPARTMENT
78 SHENTON WAY #09-16
AIG BUILDING
SINGAPORE 079120
64191000

Vehicle & Document Information

WIP No 54030
Reg No/Reg Date SJG2020Z / 13/10/2020
Date In/Mileage 0
Chassis No W1K1771842J2095682
Engine No 28291480352860
Make/Model MB/A 180
Colour/Trim 028 859 Mojave Silv/ 041 101 ARTICO Blac

Account No	Terms	Date/Time Printed	CSE	Operator
WA000007	Credit	15/12/2021/ 13:03	YK	395 / Yik Chan Hoe

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M BRACKET ?	1.00	161.56	10.00	145.40
M ELECTRICAL WIRING HARNESS Burnt	1.00	220.06	10.00	198.05
M INTERIOR LAMP Burnt	1.00	0.00	00.00	
M ELECTRICAL WIRING HARNESS Burnt	1.00	62.58	10.00	56.32
M ELECTRICAL WIRING HARNESS Burnt	1.00	221.56	10.00	199.40
M ELECTRICAL WIRING HARNESS Burnt	1.00	10986.86	10.00	9888.17
M RADIO/INSTRUMENT DISPLAY Down	1.00	4007.35	10.00	3606.61
M SRS CONTROL UNIT Burnt	1.00	241.13	10.00	217.02
M MULTIMEDIA CON. UNIT Burnt	1.00	128.58	10.00	115.72
M TOUCH PAD CONTROL UNIT Down	1.00	876.54	10.00	788.89
M MULTIMEDIA CON. UNIT Down	1.00	160.62	10.00	144.56
M MULTIMEDIA CON. UNIT Down	1.00	128.58	10.00	115.72
M MOBILE PHONE CRADLE Down	1.00	18.31	10.00	16.48
M SWITCH BLOCK Hec	1.00	512.68	10.00	461.41
M SWITCH BLOCK Hec	1.00	187.98	10.00	169.18
M STEERING COLUMN SIGNAL CONTROL UNIT Down	1.00	844.25	10.00	759.82
M BUTTON SWITCH Down	1.00	94.59	10.00	85.13
M DAMPING MAT FIREWALL Burnt	1.00	231.90	10.00	208.71
M DAMPING MAT FLOOR PANEL Burnt	1.00	42.22	10.00	38.00
M RIGHT FRONT SEAT RAIL HEIGHT ADJUSTMENT Burnt / Rusted	1.00	1769.11	10.00	1592.20
M LEFT FRONT SEAT RAIL HEIGHT ADJUSTMENT Burnt / Rusted	1.00	1769.11	10.00	1592.20
M RIGHT FRONT SEAT CONTROL UNIT, COMPLETE ?	1.00	584.49	10.00	526.04
M LEFT FRONT SEAT CONTROL UNIT, COMPLETE ?	1.00	332.71	10.00	299.44
M RIGHT FRONT SEAT LONGITUDINAL ADJUSTMENT ?	1.00	137.12	10.00	123.41
M LEFT FRONT SEAT LONGITUDINAL ADJUSTMENT ?	1.00	137.12	10.00	123.41
M TPMS CONTROL UNIT ?	1.00	526.72	10.00	474.05
M BRAKE PEDAL ASSEMBLY ?	1.00	216.95	10.00	195.25
M BRAKE LIGHT SWITCH ?	1.00	57.52	10.00	51.77
M ACCELERATOR PEDAL MODULE ?	1.00	267.05	10.00	240.34
M FRONT DOOR EDGE GUARD Hec	2.00	130.34	10.00	234.61
M RIGHT TRIM, A-PILLAR Hec	1.00	113.97	10.00	102.57
M LEFT TRIM, A-PILLAR Hec	1.00	119.97	10.00	107.97
M LEFT TRIM, B-PILLAR ?	1.00	127.45	10.00	114.70

Confirmed & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



Mercedes-Benz are registered trademarks of Daimler, Stuttgart, Germany



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SJG2020Z

AIG Asia Pacific Insurance Pte.
Ltd.
MOTOR CLAIM DEPARTMENT
78 SHENTON WAY #09-16
AIG BUILDING
SINGAPORE 079120
64191000

Vehicle & Document Information

WIP No 54030
Reg No/Reg Date SJG2020Z / 13/10/2020
Date In/Mileage 0
Chassis No W1K1771842J2095682
Engine No 28291480352860
Make/Model MB/A 180
Colour/Trim 028 859 Mojave Silv/ 041 101 ARTICO Blac

Account No	Terms	Date/Time Printed	CSE	Operator
WA000007	Credit	15/12/2021/ 13:03	YK	395 / Yik Chan Hoe

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M RIGHT TRIM, B-PILLAR ?	1.00	120.35	10.00	108.31 ?
M LEFT LOWER TRIM, B-PILLAR ?	1.00	66.82	10.00	60.14 ?
M RIGHT LOWER TRIM, B-PILLAR ?	1.00	63.80	10.00	57.42 ?
M HEADLINER ?	1.00	1258.95	10.00	1133.05 ?
M AIR-CON CONTROL UNIT ?	1.00	512.68	10.00	461.41 ?
M AIR-CON DUCT ?	1.00	18.94	10.00	17.05 ✓
M AIR-CON DUCT ?	1.00	21.99	10.00	19.79 ✓
M AIR-CON DUCT ?	1.00	50.23	10.00	45.21 ✓
M AIR-CON DUCT ?	1.00	50.92	10.00	45.83 ✓
M CENTER AIR-CON AIR VENT ?	3.00	200.70	10.00	541.89 ✓
M RIGHT AIR-CON AIR VENT ?	1.00	202.18	10.00	181.96 ✓
M LEFT AIR-CON AIR VENT ?	1.00	201.80	10.00	181.62 ✓
M FRONT WINDSHIELD ?	1.00	726.80	10.00	654.12 ✓
M FRONT W/SCREEN SEALING STRIP ?	4.00	2.64	10.00	9.50 ✓
M ONE-COMPONENT ADHESIVE ?	2.00	160.11	10.00	288.20 ✓
M RAIN AND LIGHT SENSOR ?	1.00	306.66	10.00	275.99 ✓

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Confirmed & accepted by

Acknowledged by Repairer
Signature:
Date:

15/12/2021 @ 1400 hrs
Not Antimal
P/Pat. 28 days.
Excess TBA.

[Signature]
LKK Auto

Nett 80,747.31
7% GST on 80747.31 5652.31
Total Payable 86,399.62

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany