

ASS. BY:

REF: CS4/AIG 21012722/DVJ3

ASSIGNMENT

From: _____ Date: _____

Estimate Cost: _____

OD / TP RES / OD RES / EVA / INV / MV

To Insp Vehicle No: _____

at Work in m/s _____

of _____

Insured _____

Policy No _____

Claims in _____

Sum Insured _____

Excess: _____

(Check record)

Make of Car: _____

(Police Condition)

Remarks: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Report _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 22% days Res.: Yes or NoLump Sum: 7/7 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SJG 2020Z Yr Regn: Oct 2020Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Mercedes Benz A180 c.c. 1332Colour: SILVER A/C: Insured / Std / N/ASp. Reading: N.A. T/Radio: Insured / Std / N/AEng/No: 28291480352860C/No: W1K17718425-209568Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orMod: N/A / STD A/Rim orTyre Size: F: 225/45 R18R: 11

BS / DUN / EXNOVA / GY / FS / LZA / MIC / OHTSU / PIR / SUZUKI

TOYO / YOKO or

Hankook

Front

Rear

R/Bal: S mmR/Bal: S mmL/Bal: S mmL/Bal: S mmD.O.A. 21/10/2021D.O.L. 15/12/2021Survey held at Cycle Pandan loop

Des. of Damages: Fnt / Rear / O/S / N/S / W/C / Rooftop or

The W/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

AIG OD

MV 1351C

LIA 613K

NL 737K

The vehicle caught fire at its centre console inside the interior compartment cause of fire due to electrical short to the wiring.

Date/Time, File Pass to?

☐ : Prel. Report

Days Of Repair: _____

1) Date/Time, File Return to?

☐ : Final Report

Resurvey No. of Trip: _____

2) _____

Add Fee: ☐ : Site Insp (\$)

Survey Fee: _____

Transportation: _____

S + RS \$

Photos _____

☐ : Interview (\$)

Report Format: _____