

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #07-16
Singapore 079120

Our File No: CS/AIG21012726/ETF3E2

Date: 08/02/2022

REFERENCE

Insured/Claimant: POH LIONG THIAM FRANCIS Policy No: 7210049283
Date of Loss: 15/12/2021 Nature of Claim: OD Claim No: 6652649970SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMZ7734D**
Make & Model: KIA CERATO, 1.6 (A) Engine No: G4FGLH713092
Reg. Date: 18/05/2021 (Man. Year: 2020) Chassis No: KNAF5416MM5102997
Colour: Grey Odometer: 9367 km
Engine Capacity: 1591 cc
Market Value/New Car Price: S\$95,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/45 R17 Rear Tyre Size: 225/45 R17
Front Left Side: Nexen 4 mm Rear Left Side: Nexen 4 mm
Front Right Side: Nexen 4 mm Rear Right Side: Nexen 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,660.00	2,428.80	1,231.20	33.64
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,220.00	3,040.00	2,180.00	41.76
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	8,880.00	5,468.80	3,411.20	38.41
+ GST 7.00/7.00% (S\$)	621.60	382.82	238.78	38.41
Nett Amount (S\$)	9,501.60	5,851.62	3,649.98	38.41

INSPECTION

Date of Assignment: 16/12/2021

Date Inspected: 16/12/2021 Inspected At:

Cycle & Carriage KIA Pte Ltd (Pandan Gardens)
209 Pandan Gardens
Singapore 609339

Estimated Period of Repair: 6.0 days

Adjuster: CHEN TSUE YEE

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	40.00 FS	*20.00 FS
2	1		*PANEL ASSY-TRUNK LID	Dented	1,297.00 FL	*1,297.00 FL
3	1		*PANEL ASSY-BACK	Dented	324.00 FL	*324.00 FL
4	1		*EMBLEM-CERATO	Necessary	28.00 FL	*28.00 FL
5	1		*EMBLEM-GT LINE	Necessary	45.00 FL	*45.00 FL
6	1		*LOGO ASSY-KIA SUB	Necessary	32.00 FL	*32.00 FL
7	1		*COVER-RR BUMPER	Broken	651.00 FL	*651.00 FL
8	1		*COVER-RR BUMPER LWR	Broken	241.00 FL	*241.00 FL
9	1		*COVER-RR BUMPER FOG LAMP, RH	Not Necessary	88.00 FL	*- FL
10	1		*LAMP ASSY-SIDE T/SIGNAL, RH	Not Necessary	181.00 FL	*- FL
11	1		*EXTN WIRING ASSY-BWS	Not Necessary	207.00 FL	*- FL
12	1		*BRACKET-RR BEAM UPR MTG, LH	Not Necessary	9.00 FL	*- FL
13	1		*BRACKET-RR BEAM UPR MTG, RH	Not Necessary	9.00 FL	*- FL
14	1		*BRACKET-RR BEAM LWR, CTR	Not Necessary	6.00 FL	*- FL
15	1		*BRACKET-RR BEAM LWR MTG	Not Necessary	6.00 FL	*- FL
16	1		*BEAM-RR BUMPER	Broken	318.00 FL	*318.00 FL
17	1		*ANTENNA ASSY-SMARTKEY	Not Necessary	46.00 FL	*- FL
18	1		*STAY-RR BUMPER LH	Not Necessary	65.00 FL	*- FL
19	1		*STAY-RR BUMPER RH	Dented	65.00 FL	*65.00 FL
20	1		*BRACKET ASSY-RR BPR SIDE UPR, L	Not Necessary	25.00 FL	*- FL
21	1		*BRACKET ASSY-RR BPR SIDE UPR, R	Not Necessary	31.00 FL	*- FL
22	1		*ULTRASONIC SENSOR ASSY-BWS	Not Necessary	163.00 FL	*- FL
23	1		*ULTRASONIC SENSOR ASSY-BWS	Not Necessary	163.00 FL	*- FL
24	1		*ULTRASONIC SENSOR ASSY-BWS	Not Necessary	163.00 FL	*- FL
25	1		*W/STRIP-TRUNK LID OPNG	Not Necessary	100.00 FL	*- FL
26	1		*TRIM ASSY-RR TRANSVERSE	Not Necessary	41.00 FL	*- FL
27	1		*MAT ASSY-LUGGAGE COVERING	Not Necessary	211.00 FL	*- FL
28	1		*CLIPS (x10) (Supplementary)	Necessary	10.00 FL	*10.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	4,565.00	3,031.00
- List Item Discount on L Items 20.00/20.00% (\$)	905.00	602.20
Total Parts (\$)	3,660.00	2,428.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REPLACE REAR BUMPER, BOOT, END PANEL & AFFECTED AREA. REPAIR ON FLOOR PANEL	New	2,000.00	600.00
2	PAINT WORK ON REAR BUMPER, BOOT, END PANEL & FLOOR PANEL	New	1,400.00	700.00
3	REMOVE & INSTALL REAR PARKING ASSIST	New	120.00	80.00
4	TO TRANSFER REAR BOOT ATTACHMENTS TO NEW PANEL	New	120.00	120.00
5	TO REMOVE & INSTALL REAR BOOT COMPARTMENT FOR FACILITATE REPAIR	New	120.00	120.00
6	TO APPLY SEALANT ON AFFECTED AREA	New	80.00	40.00
7	PERFORM RUST PREVENTION	New	40.00	40.00
8	CHECK WIRING & CHASSIS ELECTRICAL SYSTEM	New	30.00	30.00
9	TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM	New	120.00	120.00
10	TO SUPPLY C & C EMBLEM	New	40.00	40.00
11	REPLACE REAR END PANEL (Supplementary)	New	800.00	800.00
12	RESPRAY REAR END PANEL (Supplementary)	New	350.00	350.00
			Gross Labour Cost (S\$)	5,220.00
				3,040.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >