

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

India International Insurance Pte Ltd
64 Cecil Street, #04-00 IOB Building
Singapore 049711

Our File No: CS/III21012729/KQF3E2**Date:** 18/01/2023**REFERENCE**

Insured/Claimant: COMFORTDELGRO RENT-A-CAR PTE LTD Policy No: D20MFL0000326_01

Date of Loss: 28/11/2021

Nature of Claim: OD

Claim No: MFL2021D0005215

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKS5437K**
 Make & Model: MITSUBISHI OUTLANDER, 2.4 2.4 CVT AWD S/R FACE (A) Engine No: 4B12PJ5643
 Reg. Date: 23/04/2015 (Man. Year: 2015) Chassis No: JMYXTGF3WFZ001782
 Colour: Metallic Dark Blue Odometer: 78445 km
 Engine Capacity: 2360 cc
 Market Value/New Car Price: S\$50,000.00
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 225/55 R18 Rear Tyre Size: 225/55 R18
 Front Left Side: Pirelli 9 mm Rear Left Side: Pirelli 9 mm
 Front Right Side: Pirelli 9 mm Rear Right Side: Pirelli 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,641.50	2,481.30	160.20	6.06
Miscellaneous Items	11.00	11.00	0.00	0.00
Labour	1,330.00	1,050.00	280.00	21.05
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	3,982.50	3,542.30	440.20	11.05
- Excess (S\$)	0.00	750.00	-750.00	
(S\$)	3,982.50	2,792.30	1,190.20	29.89
+ GST 7.00/7.00% (S\$)	278.78	195.46	83.32	29.89
Nett Amount (S\$)	4,261.28	2,987.76	1,273.52	29.89

INSPECTION

Date of Assignment: 16/12/2021 Present Location: ComfortDelGro Engineering Pte Ltd (Braddell)
 Date Inspected: 16/12/2021 Inspected At: ComfortDelGro Engineering Pte Ltd (Braddell)
 205 Braddell Road
 Singapore 579701
 Estimated Period of Repair: 4.0 days

Adjuster: KENNETH KONG**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

(REPAIR COST NOT CONCLUDE)

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 17 Dec 2021)
Parts:	M1-SUV	MITSUBISHI OUTLANDER 2.4 2.4 CVT AWD S/R FACE (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKS5437K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT BUMPER	Cracked	1,036.00 FL	*1,036.00 FL
2	1		*FRT BUMPER SIDE RETAINER LH	Cracked	19.00 FL	*19.00 FL
3	1		*FRT BUMPER SIDE GARNISH LH	Distorted	87.00 FL	*87.00 FL
4	1		*HEADLAMP LH	Cracked	860.00 FL	*860.00 FL
5	1		*LH FRT FENDER	Bent	605.00 FL	*605.00 FL
6	1		*LH FRT FENDER INNER SHIELD	Serviceable	148.00 FL	*- FL
7	10		*LH FRT FENDER INNER SHIELD CLIPS	Not Necessary	30.00 FL	*- FL
8	1		*LH FRT FENDER INNER GARNISH	Buckled	150.00 FL	*150.00 FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	2,935.00	2,757.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	293.50	275.70
Total Parts (\$\$)	2,641.50	2,481.30

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	OD/TP Case (Insurer)	11.00	11.00
Sub Total (S\$)			11.00	11.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO KNOCK, STRAIGHTEN AND RENEW ACCIDENT AREA SUCH AS BONNET, FRT BUMPER, LH FRT FENDER, HEADLAMP LH AND ETC	New	480.00	400.00
2	TO PUTTY AND RESRPAY ACCIDENT AREA SUCH AS BONNET, FRT BUMPER, LH FRT FENDER AND ETC	New	800.00	600.00
3	TO CHECK WIRING AND LIGHTING	New	50.00	50.00
Gross Labour Cost (S\$)			1,330.00	1,050.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >