

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Page No.:1 of 1

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PRE-REPAIR INSPECTION REPORT STRIDES AUTOMOTIVE SERVICES PTE LTD CS3/SMR21012734/Gvf3e2 Ref: 60 WOODLANDS INDUSTRIAL PARK Date: 30/12/2021 E4SINGAPORE 757705 Code: SMR 1. Policy Particulars :- (THIRD PARTY CLAIM) Insured Veh. SHD 6273Z FBQ 8869U Veh. Inspected Policy No. Coverage (\$) 0.00 Claim No. TAX/11/21/2060 Excess (\$) 0.00 **HUA YEN Assign Date** 16/12/2021 Assign From **Vehicle Particulars & Condition** 2. YAMAHA MX KING T150 c.c 150 Make & Model HIDDEN 2020 Engine No. Year of Reg. MH3UG0750KK043659 **BLUE** Chassis No. Colour Odometer Steering **IN ORDER** IN ORDER NIL **Brakes** Modification GOOD General 3. **Conditions of Tyres** Size Make **Balance** R/H Front Tyre 80/90-17 PIRELLI 5 mm L/H Front Tyre mm PIRELLI 90/80-17 R/H Rear Tyre 5 mm L/H Rear Tyre mm 4. **Description of Damages** THE VEHICLE SUSTAINED DAMAGES AT THE O/S AND N/S BODY. 5. **General Information** 26/11/2021 20/12/2021 (11:15 AM) **Accident Date** Inspect Date / Time 464 MACPHERSON ROAD Survey held at Repairer MOTO 51 PTE LTD 5a. Remarks A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$1,000-\$2,000

Report Ref No. CS3/SMR21012734/Gvf3e2

Estimate Days of Repair

Inspected By

ESTIMATED NORMAL PERIOD FOR REPAIR:

5b.

XING GUO QIANG

K.K.LAU CPT(RET)

2 Working Days

M.MATAI, AMSAE-A BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

Automotive Assessor REGD Auto Consultant-SAE, Licensed Appraiser