

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21012735/BQY3N2**Date:** 22/02/2022**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNW00122282000		
Claimant Vehicle No :	SLD9395M	Insured Vehicle No :	GBE5789A		
Date of Loss:	09/12/2021	Nature of Claim:	TP	Claim No:	SNM21D207167/C02/THAMYL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLD9395M		
Make & Model:	MAZDA 6, 2.0 (A)	Engine No:	PE20785904
Reg. Date:	30/06/2016 (Man. Year: 2016)	Chassis No:	JM6GJ1072G0239365
Colour:	White	Odometer:	102874 km
Engine Capacity:	1998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/55R17	Rear Tyre Size:	225/55R17
Front Left Side:	Michelin 5 mm	Rear Left Side:	Michelin 5 mm
Front Right Side:	Michelin 5 mm	Rear Right Side:	Michelin 5 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,765.08	6,760.48	5,004.60	42.54
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,320.00	2,200.00	2,120.00	49.07
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	16,085.08	8,960.48	7,124.60	44.29
Approved Total (Overridden) (\$\$)		7,150.00		
(\$\$)	16,085.08	7,150.00	8,935.08	55.55
+ GST 7.00/7.00% (\$\$)	1,125.96	500.50	625.46	55.55
Nett Amount (\$\$)	17,211.04	7,650.50	9,560.54	55.55

INSPECTION

Date of Assignment:	19/12/2021		
Date Inspected:	16/12/2021	Inspected At:	Bifrost Auto Pte Ltd (Kaki Bukit) 8 Kaki Bukit Ave 4, #01-49, Premier @ Kaki Bukit Singapore 415875
Estimated Period of Repair:	6.0 days		

Adjuster: Lim Teow Guan**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 22 Feb 2022)
Parts:	143	MAZDA 6 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLD9395M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*RH FRONT DOOR	Dented	975.20 FL	*975.20 FL
2	1		*RH FRONT DOOR WEATHERSTRIP	Not Damaged	143.10 FL	*- FL
3	1		*RH FRONT DOOR OUTER HANDLE WITH SENSOR	Not Damaged	212.60 FL	*- FL
4	1		*SET RH REAR DOOR INNER TRIM BOARD CLIPS	Not Necessary	70.00 FL	*- FL
5	1		*RH FRONT DOOR FRAME BLACK TAPE	Necessary	32.20 FL	*32.20 FL
6	1		*RH REAR DOOR	Dented	958.60 FL	*958.60 FL
7	1		*RH REAR DOOR WEATHERSTRIP	Not Damaged	143.10 FL	*- FL
8	1		*RH REAR DOOR LOCK	Jammed	222.90 FL	*180.00 FL
9	1		*RH REAR DOOR LOCK CATCH	Not Damaged	27.50 FL	*- FL
10	1		*RH REAR DOOR INNER TRIM BOARD	Broken	2,025.90 FL	*595.00 FL
11	1		*SET RH REAR DOOR INNER TRIM BOARD CLIPS	Necessary	70.00 FL	*30.00 FL
12	1		*RH REAR DOOR GLASS REGULATOR GEAR	Bent	149.90 FL	*149.90 FL
13	1		*RH REAR DOOR GLASS REGULATOR GEAR MOTOR	Not Damaged	166.70 FL	*- FL
14	1		*RH REAR DOOR UPPER HINGE	Bent	44.80 FL	*44.80 FL
15	1		*RH REAR DOOR LOWER HINGE	Bent	44.80 FL	*44.80 FL
16	1		*RH REAR DOOR OUTER HANDLE	Repair	78.80 FL	*- FL
17	1		*RH REAR DOOR OUTER MOULDING	No such part	80.40 FL	*- FL
18	1		*RH REAR DOOR FRAME BLACK TAPE	Necessary	32.20 FL	*32.20 FL
19	1		*REAR WINDSCREEN GLASS RUBBER MOULDING	Not Damaged	117.10 FL	*- FL
20	1		*RH REAR FENDER	Dented	1,120.50 FL	*1,120.50 FL
21	1		*RH REAR FENDER SPLASH SHIELD	Broken	56.80 FL	*56.80 FL
22	1		*SET RH REAR FENDER SPLASH SHIELD CLIPS	Necessary	50.00 FL	*30.00 FL
23	1		*RH REAR FENDER QUARTER GARNISH	Broken	54.20 FL	*54.20 FL
24	1		*RH REAR FENDER INNER TRIM BOARD	Not Damaged	342.10 FL	*- FL
25	1		*RH SIDE ROCKER PANEL LOWER GARNISH	Dented	532.10 FL	*532.10 FL
26	1		*REAR BUMPER	Broken	1,129.50 FL	*1,055.20 FL
27	1		*SET REAR BUMPER CLIPS	Necessary	70.00 FL	*30.00 FL
28	1		*REAR BUMPER RH SIDE RETAINER	Necessary	45.30 FL	*45.30 FL
29	1		*REAR BUMPER LH SIDE RETAINER	Necessary	45.30 FL	*45.30 FL
30	1		*RH REAR LOWER ARM	Dented	247.70 FL	*233.60 FL
31	1		*RH REAR UPPER ARM	Dented	241.70 FL	*188.40 FL
32	1		*RH REAR KNUCKLE ARM	Dented	724.80 FL	*291.50 FL
33	1		*RH REAR WHEEL BEARING	Jammed	480.80 FL	*291.50 FL
34	1		*RH REAR SHOCK ABSORBER	Jammed	322.20 FL	*200.80 FL
35	1		*RH REAR TRAILING ARM	Dented	320.20 FL	*320.20 FL
36	1		*RH TAILLAMP ASSY	Not Damaged	1,292.30 FL	*- FL
37	1		*REAR WINDSCREEN GLASS SEALANT	Necessary	70.00 FS	*30.00 FS
38	1		*REAR WINDSCREEN GLASS INNER SEAL	Necessary	50.00 FS	*30.00 FS
39	1		*RH REAR FENDER JOINT SEALANT	Necessary	70.00 FS	*30.00 FS
40	1		*RH REAR TYRE	Not Damaged	350.00 FS	*- FS
41	1		*BRAKE FLUID	Not Necessary	55.00 FS	*- FS
42	1		*RH REAR SPORT RIM (ORIGINAL)	Cut	1,291.30 FL	*800.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	14,557.60	8,428.10
- List Item Discount on L Items 20.00/20.00% (\$\$)	2,792.52	1,667.62

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
				Total Parts (\$)	11,765.08	6,760.48
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR CHARGES TO REMOVE,CHECK,REPLACE AND REINSTALL DAMAGES BODYPART.TO PANEL BEATING,CUT/WELD AND RE-ALIGN ALL AFFECTED PANELS	New	1,400.00	800.00
2	SPRAY PAINTING ON AFFECTED PANELS	New	1,300.00	1,000.00
3	CHECK WIRING AND LIGHTING SYSTEM	New	60.00	0.00
4	APPLY RUST COATING CHEMICAL ON AFFECTED PANELS	New	120.00	0.00
5	REMOVE AND REPLACE RH FRONT DOOR INNER COMPONENTS TO ASSIST REPAIR	New	120.00	0.00
6	REMOVE AND REPLACE RH REAR DOOR INNER COMPONENTS TO ASSIST REPAIR	New	120.00	80.00
7	REMOVE.REINSTALL AND REPLACE REAR INNER TRIMS,GARNISH,ROOF LINING,SEATS,CARPET AND BOARDS TO ASSIST REPAIR	New	380.00	0.00
8	REMOVE AND REINSTALL REAR BUMPER REVERSE SENSORS TO ASSIST REPAIR	New	100.00	60.00
9	CONDUCT AND ADJUST WHEEL ALIGNMENT SYSTEM	New	120.00	60.00
10	REMOVE AND REPLACE REAR UNDERCARRIAGE PARTS TO ASSIST REPAIR	New	350.00	200.00
11	RESET AND DIAGNOSE CONTROL UNIT AFTER REPAIR	New	250.00	0.00
Gross Labour Cost (\$\$)			4,320.00	2,200.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >