

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #07-16
Singapore 079120

Our File No: CS/AIG21012737/KTF3E2

Date: 09/03/2022

REFERENCE

Insured/Claimant:	Tay Geok Eng Carol	Policy No:	1800003488-02		
Date of Loss:	06/12/2021	Nature of Claim:	OD	Claim No:	4595042732SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLV2734U	Engine No:	B4154T52319718
Make & Model:	VOLVO V40, 1.5 T2 (A)	Chassis No:	YV1MV28L0J2481184
Reg. Date:	27/12/2017 (Man. Year: 2017)	Odometer:	23707 km
Colour:	Metallic Blue		
Engine Capacity:	1498 cc		
Market Value/New Car Price:	S\$78,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Michelin 8 mm	Rear Left Side:	Michelin 8 mm
Front Right Side:	Michelin 8 mm	Rear Right Side:	Michelin 8 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,342.12	13,823.48	-481.36	-3.61
Miscellaneous Items	271.00	271.00	0.00	0.00
Labour	696.00	662.40	33.60	4.83
Paintwork Labour	940.25	1,012.25	-72.00	-7.66
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	15,249.37	15,769.13	-519.76	-3.41
- Excess (S\$)	1,000.00	1,000.00	0.00	0.00
(S\$)	14,249.37	14,769.13	-519.76	-3.65
+ GST 7.00/7.00% (S\$)	997.45	1,033.84	-36.39	-3.65
Nett Amount (S\$)	15,246.82	15,802.97	-556.15	-3.65

INSPECTION

Date of Assignment:	16/12/2021	Present Location:	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)
Date Inspected:	17/12/2021	Inspected At:	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming) 160 Sin Ming Drive #04-01, Sin Ming AutoCity Singapore 575722
Estimated Period of Repair:	7.0 days		

Adjuster: KENNETH KONG

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1	NA	*BONNET (WCP)	Bent	2,448.00 F	*2,448.00 F
2	1	NA	*ENGINE COMP INSUL (WCP)	Dented/Cut	297.00 F	*297.00 F
3	1	NA	*FRONT BUMPER (WCP)	Cracked	1,581.00 F	*1,581.00 F
4	1	NA	*FRONT PANEL (WCP)	Cracked	1,776.00 F	*1,776.00 F
5	1	NA	*FRT LOWER AIR GUIDE (WCP)	Cracked	193.00 F	*193.00 F
6	1	NA	*R/DOOR MIRROR (WCP)	Broken	606.00 F	*606.00 F
7	1	NA	*R/DOOR MIRROR GLASS (WCP)	Cut	260.00 F	*260.00 F
8	1	NA	*R/F DOOR TRIM (WCP)	Repair	183.00 F	*- F
9	1	NA	*R/F SIDE WINDOW TRIM (WCP)	Not Necessary	72.00 F	*- F
10	1	NA	*R/F WINDOW CHANNEL (WCP)	Cut	136.00 F	*136.00 F
11	1	NA	*R/F WING (WCP)	Bent	1,083.00 F	*1,083.00 F
12	1	NA	*R/R DOOR TRIM FRONT (WCP)	Not Necessary	183.00 F	*- F
13	1	NA	*R/R DOOR TRIM REAR (WCP)	Not Necessary	183.00 F	*- F
14	1	NA	*R/SILL PANEL COVER (WCP)	Cracked	530.00 F	*530.00 F
15	1	NA	*R/WINDSCREEN SEAL (WCP)	Dented/Cut	166.00 F	*166.00 F
16	1	NA	*RIGHT HEADLAMP ASSY (WCP)	Broken	1,640.00 F	*2,698.60 F
17	1	NA	*RIGHT MIRROR COVER (WCP)	Missing	298.00 F	*298.00 F
Supplementary #1						
18	1		*R/F WHEELHOUSE COVER (WCP)	Cracked	218.40 F	*218.40 F
19	1		*WASHER PUMP (WCP)	Cracked	116.70 F	*116.70 F
20	1		*R/HEADLAMP MOUNTING (WCP)	Cracked	30.20 F	*30.20 F
21	1		*R/F UPP DOOR MOULDING (WCP)	Scratched	128.90 F	*128.90 F

F=Franchise part.

Sub Total (S\$)	12,129.20	12,566.80
+ Margin on L,N Items 10.00/10.00% (S\$)	1,212.92	1,256.68
Total Parts (S\$)	13,342.12	13,823.48

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	CHK/ERASE FAULT CODES AFTER REPAIR	120.00	120.00
2	1	R/F TYRE (Punctured)	140.00	140.00
3	1	OD/TP Case (Insurer)	11.00	11.00
Sub Total (\$\$)			271.00	271.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Paintwork Labour</u>				
1	Total Paint Labour	New	633.60	705.60
2	Total Paint Materials	New	306.65	306.65
<u>Labour Items</u>				
3	Total Panel/Mechanical Labour	New	696.00	662.40
Gross Labour Cost (\$\$)			1,636.25	1,674.65

Report was unsubmitted during this print-out.

< END OF ESTIMATES >