

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21012738/KQY3Q2**Date:** 05/04/2023**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNW00139612100		
Claimant Vehicle No :	SMQ6255Z	Insured Vehicle No :	GBG8802P		
Date of Loss:	03/12/2021	Nature of Claim:	TP	Claim No:	SNM21D207029/C02/THAMYL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMQ6255Z		Engine No:	G4FGKU476263
Make & Model:	HYUNDAI AVANTE, 1.6 (A)		Chassis No:	KMHD841CMLU012640
Reg. Date:	27/11/2019 (Man. Year: 2019)		Odometer:	90276 km
Colour:	Metallic Pearl White			
Engine Capacity:	1591 cc			
Market Value/New Car Price:	N/A			
Sum Insured (S\$):	Market Value/New Car Price			

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	KAPSEN 5 mm	Rear Left Side:	Nexen 3 mm
Front Right Side:	KAPSEN 5 mm	Rear Right Side:	Nexen 3 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,718.40	450.00	2,268.40	83.45
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,820.00	920.00	900.00	49.45
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	4,538.40	1,370.00	3,168.40	69.81
+ GST 8.00/8.00% (S\$)	363.07	109.60	253.47	69.81
Nett Amount (S\$)	4,901.47	1,479.60	3,421.87	69.81

INSPECTION

Date of Assignment:	19/12/2021	Optima Werkz Pte Ltd (HQ)
Date Inspected:	21/12/2021 Inspected At:	10 Ang Mo Kio Industrial Park 2A, #01-05 AMK Autopoint
Estimated Period of Repair:	4.0 days	Singapore 568047

Adjuster: KENNETH KONG**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

THE VEHICLE HAS NOT SEND IN FOR REPAIRS.
(REPAIR COST NOT CONCLUDE)
(EXCLUDE CHECK ITEMS S\$688.00 NETT)

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 04 Apr 2023)
Parts:	143	HYUNDAI AVANTE 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMQ6255Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Repair	760.00 FL	*- FL
2	1		*REAR LOWER BUMPER	Dented / Cut	475.00 FL	*475.00 FL
3	1		*REAR LOWER DIFFUSER	No such part	435.00 FL	*- FL
4	1		*REAR BUMPER SIDE BRACKET RH	Serviceable	85.00 FL	*- FL
5	1		*REAR BUMPER REFLECTOR RH	Serviceable	188.00 FL	*- FL
6	1		*REAR REINFORCEMENT	Repair	240.00 FL	*- FL
7	1		*REAR SPONGE	Serviceable	100.00 FL	*- FL
8	1		*REAR END PANEL	Repair	395.00 FL	*- FL
9	1		*TAIL LAMP OUTER RH	Repair	445.00 FL	*- FL
10	1		*REAR DOOR RH (NPA)	Repair	0.00 FL	*- FL
11	1		*FRONT DOOR RH (NPA)	Repair	0.00 FL	*- FL
12	1		*REAR BUMPER CLIPS	*Check	80.00 FS	*- FS
13	1		*REAR LOWER BUMPER CLIPS	Necessary	70.00 FS	*70.00 FS
14	1		*REAR DIFFUSER CLIPS	Not Necessary	70.00 FS	*- FS
					Sub Total (\$\$)	3,343.00 545.00
					- List Item Discount on L Items 20.00/20.00% (\$\$)	624.60 95.00
					Total Parts (\$\$)	2,718.40 450.00

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR CHARGES TO REMOVE ,REPLACE ,REFIX & REPAIR ACCIDENT AREA	New	800.00	300.00
2	LABOUR CHARGES TO SUPPLY PAINT & FURNISHING MATERIALS AT ACCIDENT AREA	New	800.00	600.00
3	TO CHECK WIRING & ELECTRICAL SYSTEM & ETC	New	100.00	20.00
4	TO TUFF KOTE & UNDERSEAL MATERIALS	New	120.00	0.00
Gross Labour Cost (\$\$)			1,820.00	920.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >