

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT						
	INDIA INTERNATIO	DNAL INSURANCE PL		Ref:	CS3/SGK21012740/Vqf3e2	
	64 CECIL STREET SINGAPORE 0497	#05-02 IOB BUILDING 11		Date:	14/01/2022	
				Code:	III2	
1.	Policy Particulars :- THIRD PARTY CLAIM (RESURVEY INSPECTION)					
	Insured Veh.	PUBLIC LIABILITY	Veh. Inspected		FBK 6276A	
	Policy No.	SGK: P5-2021-S0011 (6007358)	Coverage (\$)		0.00	
	Claim No.	III: CAR2021D0005497	Excess (\$)		0.00	
	Assign From	DARREN TING	Assign Date		16/12/2021	
2. Vehicle Particulars & Condition						
	Make & Model	HUSQVARNA FE350	c.c		350	
	Engine No.	HIDDEN	Year of Reg.		2015	
	Chassis No.	VBKUAA40XFM242275	Colour		WHITE	
	Odometer	-	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		STANDARD ALLOY RIM	
	General	GOOD				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	160/60Z R17	PIRELLI		6 mm	
	L/H Front Tyre				mm	
	R/H Rear Tyre	160/60Z R17	PIRELLI		6 mm	
	L/H Rear Tyre				mm	
4. Description of Damages						
	THE VEHICLE SUS PORTION.	STAINED DAMAGES AT THE N/S BODY AND FRONT				
5.	General Information					
	Accident Date	26/11/2021	Inspect Date /	Time	17/12/2021 ( 12:30 PM )	
	Survey held at	LIGHTNING BIKE PTE LTD				
		257A JALAN BESAR SINGAPORE 208931				
5a. Remarks						
	A)THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.					

Report Ref No. CS3/SGK21012740/Vqf3e2

Inspected By

THEVAN THOMAS KARTHIKESAVAN

The

K.K.LAU CPT(RET)

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$ 

REGD Auto Consultant-SAE, Licensed Appraiser