

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21012741/GVY3M4**Date:** 21/02/2023**REFERENCE**Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMHCSNA00004252100

**Claimant Vehicle
No :** SJY4430R**Insured Vehicle
No :** SLR6074K

Date of Loss: 15/12/2021

Nature of Claim: TP

Claim
No: SNM21D207321/C02/LEEPG**DESCRIPTION & IDENTIFICATION OF VEHICLE**Reg No: **SJY4430R**

Make & Model: MERCEDES-BENZ C180, 1.8 CGI (A)

Engine No: 0

Reg. Date: (Man. Year:)

Chassis No: WDD2040492A399869

Colour: Black

Odometer: 148228 km

Engine Capacity: 0 cc

Market Value/New Car

Price: N/A

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/35 ZR19

Rear Tyre Size: 225/35 ZR19

Front Left Side: Tourador 6 mm

Rear Left Side: Tourador 6 mm

Front Right Side: Tourador 6 mm

Rear Right Side: Tourador 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	24,285.80	5,535.60	18,750.20	77.21
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,400.00	1,870.00	4,530.00	70.78
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	30,685.80	7,405.60	23,280.20	75.87
Approved Total (Overridden) (S\$)		5,900.00		
Nett Amount (S\$)	30,685.80	5,900.00	24,785.80	80.77

INSPECTION

Date of Assignment: 20/12/2021

Date Inspected: 16/12/2021 Inspected At:

J.E.W AUTO PTE LTD

60 JALAN LAM HUAT

#03-72 CARROS CENTRE SINGAPORE 737869

Estimated Period of Repair: 6.0 days

Adjuster: XING GUO QIANG**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 21 Feb 2023)
Parts:	143	MERCEDES-BENZ C180 1.8 CGI (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJY4430R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Repair	1,890.00 FL	*- FL
2	1		*BOOTLID LOGO - MERCEDES	Necessary	54.00 FL	*54.00 FL
3	1		*BOOTLID EMBLEM - C180	Necessary	61.00 FL	*61.00 FL
4	1		*BOOTLID EMBLEM - C&C	Necessary	45.00 FL	*45.00 FL
5	1		*BOOTLID EMBLEM - CGI	Necessary	35.00 FL	*35.00 FL
6	1		*BOOTLID CHROME	Not Necessary	156.00 FL	*- FL
7	1		*BOOTLID LOCK	Not Necessary	115.00 FL	*- FL
8	2		*BOOTLID HINGE L+R	Not Necessary	502.00 FL	*- FL
9	1		*BOOTLID INNER TRIM	Not Necessary	270.00 FL	*- FL
10	1		*BOOTLID WEATHERSTRIP	Cut	173.00 FL	*173.00 FL
11	1		*TAIL LAMP L+R	N/s Scratched/O/s NotNecessary	1,140.00 FL	*570.00 FL
12	2		*TAIL LAMP LOWER BRACKET L+R	Not Necessary	162.00 FL	*- FL
13	1		*REAR BUMPER REVERSE SENSOR 4PIECES	Damaged (1Piece Only)	768.00 FL	*192.00 FL
14	1		*REAR BUMPER CENTER BRACKET	Cracked	105.00 FL	*105.00 FL
15	2		*REAR BUMPER RETAINER L+R	Not Necessary	172.00 FL	*- FL
16	1		*REAR BUMPER REINFORCEMENT BAR	Bent	822.00 FL	*605.00 FL
17	1		*REAR WINDSCREEN MOULDING	Not Necessary	126.00 FL	*- FL
18	2		*REAR FENDER L+R	Repair	4,470.00 FL	*- FL
19	2		*REAR FENDER INNER TRIM L+R	Not Necessary	958.00 FL	*- FL
20	1		*REAR FENDER COWLING L+R	N/s Not Necessary/ O/s Torn	392.00 FL	*196.00 FL
21	1		*END PANEL	Buckled	1,470.00 FL	*1,215.00 FL
22	1		*END PANEL TOP GARNISH	Deformed	342.00 FL	*198.00 FL
23	1		*SPAREWHEEL PANEL (NPA)	Not Necessary	0.00 FL	*- FL
24	1		*SPAREWHEEL PANEL TOP BOARD	Not Necessary	543.00 FL	*- FL
25	1		*EXHAUST PIPE	Not Necessary	1,252.00 FL	*- FL
26	1		*EXHAUST HEAT SHIELD	Buckled	235.00 FL	*235.00 FL
27	2		*EXHAUST MOUNTING L+R	Not Necessary	160.00 FL	*- FL
28	2		*EXHAUST MOUNTING BRACKET L+R	Not Necessary	244.00 FL	*- FL
29	1		*BOOTLID INNER TRIM CLIPS	Not Necessary	100.00 FS	*- FS
30	1		*REAR NUMBER PLATE	Not Necessary	200.00 FS	*- FS
31	1		*TAIL LAMP CLIPS	Necessary	50.00 FS	*20.00 FS
32	1		*REAR BUMPER	Distorted	3,500.00 FS	*1,500.00 FS
33	1		*REAR BUMPER LOWER	Distorted	2,500.00 FS	*500.00 FS
34	2		*REAR BUMPER EXHAUST DIFFUSOR SET L+R	Cut	2,400.00 FS	*200.00 FS
35	1		*REAR FENDER SEALANT	Not Necessary	120.00 FS	*- FS
36	1		*REAR FENDER INNER TRIM CLIPS	Not Necessary	100.00 FS	*- FS
37	1		*REAR FENDER COWLING CLIPS	Not Necessary	100.00 FS	*- FS
38	1		*END PANEL SEALANT	Not Necessary	120.00 FS	*- FS
39	1		*END PANEL TOP GARNISH CLIPS	Not Necessary	100.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	25,952.00	5,904.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	1,666.20	368.40
Total Parts (\$\$)	24,285.80	5,535.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING ON AFFECTED AREAS	New	2,000.00	800.00
2	SPRAY PAINT ON AFFECTED AREAS	New	1,600.00	880.00
3	TO RNR REAR WINDSCREEN	New	300.00	0.00
4	TO RNR REAR EXHAUST	New	250.00	0.00
5	TO CHECK WIRING AND TAIL LAMP FUNCTION	New	150.00	30.00
6	TO RNR REAR INNER TRIM AND UPHOLSTERY	New	400.00	60.00
7	TO CHECK WATER LEAK	New	150.00	0.00
8	TO RNR FUEL TANK	New	300.00	0.00
9	TO PERFORM DIAGNOSTIC AND CLEAR FAULTS	New	600.00	0.00
10	TO RNR BOOTLID MECHANISM	New	300.00	0.00
11	TO RNR REAR REVERSE SENSOR AND CHECK FUNCTION	New	150.00	40.00
12	TO PERFORM RUST PROOFING	New	200.00	60.00
Gross Labour Cost (\$\$)			6,400.00	1,870.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >