

ASS. REC. BY:

REF:

A/G/21012746/Kr

C

ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

04

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SKV 44700

Yr Regn:

09, 15

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Mazda CX5

c.c

2488

Colour

M. Gray

A/C:

Insured / Std / NI / NA

Sp. Reading

44110

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

225/55R19

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

5

mm

R/Bal.

5

mm

L/Bal.

5

mm

L/Bal.

5

mm

D.O.A.

12/12/21

D.O.I.

3/1/2022

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rt N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

3/3 11:24 @ 61501 Carbur

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

S + RS. \$

Fees

Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120

TEL: 64193000

FAX: 64153727

ATTN: Motor Claim Department

WS Ref: TP/AIG/AMK

Claim Type: Third Party

Accident Date: 12/12/2021

TP Veh Reg No: SDW3232J

Estimate No: ES2191288/AMK

Date: 03 Jan 2022

Policy No: MP316643

Veh Reg No: SKV4470D

Make/Model: MAZDA CX-5

Chassis No: JM6KE1032G0327361

Engine No: PY30438863

Reg. Date: 18/09/2015

Estimate Repair Cost to Vehicle No :SKV4470D

Description	U/Price	Quantity	List Price	Amount
			<u>S\$</u>	<u>S\$</u>
List Price				
1 FRONT BUMPER <i>1023.40</i>	1,023.10	1 PC	<i>R</i> 1,023.10	<i>✓</i>
2 FRONT BUMPER SPONGE	108.50	1 PC	<i>CM</i> 108.50	<i>✓</i>
3 FRONT BUMPER REINFORCEMENT	543.00	1 PC	<i>R</i> 543.00	<i>✓</i>
4 FRONT BUMPER LH SIDE COVER	45.20	1 PC	<i>CM</i> 45.20	<i>✓</i>
5 FRONT BUMPER LH SIDE RETAINER	18.55	1 PC	<i>CM</i> 18.55	<i>X</i>
6 FRONT BUMPER CLIP	5.50	6 PC	<i>CM</i> 33.00	<i>✓</i>
7 FRONT GRILLE HOUSING	945.20	1 PC	<i>CM</i> 945.20	<i>✓</i>
8 FRONT GRILLE LOGO	101.20	1 PC	<i>CM</i> 101.20	<i>✓</i>
9 FRONT GRILLE OUTER CHROME	340.00	1 PC	<i>CM</i> 340.00	<i>✓</i>
10 FRONT BUMPER LH PARKING SENSOR	203.60	1 PC	<i>CM</i> 203.60	<i>X</i>
11 BONNET <i>1227.70</i>	1,227.70	1 PC	<i>R</i> 1,227.70	<i>✓</i>
12 FRONT LH FENDER WHEEL ARC GARNISH	186.70	1 PC	<i>R</i> 186.70	<i>X</i>
13 HEADLAMP LH <i>2920.60</i>	2,920.60	1 PC	<i>CM</i> 2,920.60	<i>✓</i>
14 FRONT GRILLE RIVET	8.50	7 PC	<i>CM</i> 59.50	<i>✓</i>
15 FRT SUPPORT PANEL	462.80	1 PC	<i>CM</i> 462.80	<i>✓</i>
16 FRONT SUPPORT PANEL INNER TOP GARNISH	85.50	1 PC	<i>CM</i> 85.50	<i>✓</i>
17 FRONT BUMPER INNER CENTRE GARNISH	95.80	1 PC	<i>CM</i> 95.80	<i>✓</i>
			8,399.95	
	Less 20%		1,679.99	6,719.96
Special Net				
18 FRONT NUMBER PLATE	35.00	1 PC	<i>R</i> 35.00	<i>✓</i>
			35.00	35.00
Labour				
19 REMOVE AND REFIX AIRCON,CHECK,VACUUM & REFILL GAS	100.00	1 LA	100.00	<i>✓</i>
20 REMOVE & REFIX FRT BUMPER & ATTACHMENTS,GRILLE,HEADLAMPS,BONNET & ATTACHMENTS,FRT SUPPORT PANEL & REALIGN THE SAME	800.00	1 LA	800.00	<i>600</i>
21 PUTTY & RESPRAY FRT BUMPER,REINFORCEMENT,PARKING SENSORS,BONNET,FRT LH FENDER & ALL AFFECTED AREAS	800.00	1 LA	800.00	<i>550</i>
22 RUSTPROOFING	30.00	1 LA	30.00	<i>✓</i>
			1,730.00	1,730.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120

TEL: 64193000

FAX: 64153727

ATTN: Motor Claim Department

WS Ref: TP/AIG/AMK

Claim Type: Third Party

Accident Date: 12/12/2021

TP Veh Reg No: SDW3232J

Estimate No: ES2191288/AMK

Date: 03 Jan 2022

Policy No: MP316643

Veh Reg No: **SKV4470D**

Make/Model: MAZDA CX-5

Chassis No: JM6KE1032G0327361

Engine No: PY30438863

Reg. Date: 18/09/2015

Estimate Repair Cost to Vehicle No :SKV4470D

Description	U/Price	Quantity	List Price	Amount
			<u>S\$</u>	<u>S\$</u>
			Total	S\$ 8,484.96
			Add GST @ 7%	593.95
			Total Amount Payable	<u>S\$ 9,078.91</u>

* SURVEY VEHICLE AT ANG MO KIO WORKSHOP

For Cheng Hoe Motor Pte Ltd



AUTHORISED SIGNATURE