

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT CS3/ASM21012747/Evy3e2 AXA INSURANCE PTE LTD Ref: 8 SHENTON WAY #24-01 AXA TOWER Date: 21/12/2021 SINGAPORE 068811 ATTN: WINNIE HO Code: ASM 1. Policy Particulars :- (THIRD PARTY CLAIM) Insured Veh. SJA 9916A SJX 5069A Veh. Inspected Policy No. GA463650 Coverage (\$) 0.00 Claim No. S1M03OIR Excess (\$) 0.00 WINNIE HO **Assign Date** 16/12/2021 Assign From **Vehicle Particulars & Condition** 2. HONDA CIVIC Make & Model 1339 C.C HIDDEN 2010 Engine No. Year of Reg. JHMFD36209S205325 **BLACK** Chassis No. Colour Odometer 176606 KM Steering IN ORDER **IN ORDER** SPORTS RIM **Brakes** Modification **FAIR** General 3. **Conditions of Tyres** Size Make **Balance** R/H Front Tyre 195/65 R15 MICHELIN 4 mm **MICHELIN** L/H Front Tyre 195/65 R15 4 mm 195/65 R15 **MICHELIN** R/H Rear Tyre 4 mm **MICHELIN** 4 mm L/H Rear Tyre 195/65 R15 4. **Description of Damages** THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION. 5. **General Information** 13/12/2021 Inspect Date / Time 17/12/2021 (11:09 AM) Accident Date PERFECT POWER PTE LTD Survey held at 1 BUKIT BATOK CRESCENT #05-36, WCEGA PLAZA SINGAPORE 658064 5a. Remarks A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,000-\$4,000 5b. **Estimate Days of Repair**

Report Ref No. CS3/ASM21012747/Evy3e2

Inspected By

ESTIMATED NORMAL PERIOD FOR REPAIR:

CHEN TSUE YEE

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons), B.Bus, MBA, PEng, PE, MInstAEA, MASME, MIRTE

5 Working Days

REGD Auto Consultant-SAE, Licensed Appraiser