

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/GRB21012748/EGA3Q2**Date:** 06/04/2022REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D21MFL0000447
Claimant Vehicle No : SMX498S **Insured Vehicle No :** SMV6284M
 Date of Loss: 11/12/2021 Nature of Claim: TP Claim No: MFL2021D0005379

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMX498S**
 Make & Model: VOLVO XC90, 2.0 T5 (A) Engine No: B4204T232429481
 Reg. Date: 18/04/2018 (Man. Year: 2018) Chassis No: YV1LF10ACJ1360530
 Colour: White Odometer: 69744 km
 Engine Capacity: 1969 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 235/55 R19 Rear Tyre Size: 235/55 R19
 Front Left Side: Michelin 4 mm Rear Left Side: Michelin 4 mm
 Front Right Side: Michelin 4 mm Rear Right Side: Michelin 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,891.66	2,014.11	4,877.55	70.77
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,410.00	740.00	670.00	47.52
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,301.66	2,754.11	5,547.55	66.82
Approved Total (Overridden) (S\$)		2,200.00		
(S\$)	8,301.66	2,200.00	6,101.66	73.50
+ GST 7.00/7.00% (S\$)	581.12	154.00	427.12	73.50
Nett Amount (S\$)	8,882.78	2,354.00	6,528.78	73.50
+ Car Rental (3.0 x S\$120.00/day) (S\$)		360.00		
Nett Liability (S\$)		2,714.00		

INSPECTION

Date of Assignment: 16/12/2021
 Date Inspected: 17/12/2021 Inspected At: Jin Auto Services Pte Ltd (Defu)
 Blk 14 Defu Lane 10, #01-410/412
 Singapore 539195
 Estimated Period of Repair: 3.0 days

Adjuster: CHEN TSUE YEE**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 11 Feb 2022)
Parts:	M1-SUV	VOLVO XC90 2.0 T5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMX498S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER COVER	Repair	3,345.30 FL	*- FL
2	1		*REAR BUMPER LOWER SPOILER	Deformed	1,192.30 FL	*1,192.30 FL
3	1		*REVERSE SENSOR	Serviceable	232.80 FL	*- FL
4	1		*REAR BUMPER REINFORCEMENT	Repair	1,750.60 FL	*- FL
5	10		*REAR BUMPER CLIPS	Necessary	80.00 FL	*60.00 FL
6	1		*REAR BUMPER RH RED REFLECTOR	Cracked	106.80 FL	*106.80 FL
7	1		*REAR BUMPER RH TOW COVER	Repair	70.80 FL	*- FL
8	1		*REAR BUMPER LOWER GARNISH	Deformed	878.80 FL	*878.80 FL
F=Franchise part. L=ListItemDisc.						
Sub Total (\$\$)					7,657.40	2,237.90
- List Item Discount on L Items 10.00/10.00% (\$\$)					765.74	223.79
Total Parts (\$\$)					6,891.66	2,014.11

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR CHARGE	New	580.00	320.00
2	SPRAY PAINTING	New	780.00	400.00
3	WIRING	New	50.00	20.00
Gross Labour Cost (\$)			1,410.00	740.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >