

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21012749/KPA3Q2**Date:** 12/04/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070134952
Claimant Vehicle No :	SGV926E	Insured Vehicle No :	SJS3084U
Date of Loss:	11/12/2021	Nature of Claim:	TP
		Claim No:	4321130225SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SGV926E	Engine No:	27186030031192
Make & Model:	MERCEDES-BENZ E250, 1.8 CGI (A)	Chassis No:	WDD2120472A160130
Reg. Date:	26/02/2010 (Man. Year: 2009)	Odometer:	165638 km
Colour:	Metallic Black		
Engine Capacity:	1796 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	245/45Z R17	Rear Tyre Size:	245/45Z R17
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 3 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Dunlop 3 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,217.70	274.50	943.20	77.46
Miscellaneous Items	0.00	0.00	0.00	
Labour	850.00	340.00	510.00	60.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	2,067.70	614.50	1,453.20	70.28
Approved Total (Overridden) (\$\$)		290.00		
(\$\$)	2,067.70	290.00	1,777.70	85.97
+ GST 7.00/7.00% (\$\$)	144.74	20.30	124.44	85.97
Nett Amount (\$\$)	2,212.44	310.30	1,902.14	85.97
Global Sum Settlement (\$\$)		0.00		

INSPECTION

Date of Assignment:	16/12/2021	City Auto Pte Ltd (Sin Ming) (HQ)
Date Inspected:	17/12/2021 Inspected At:	Block 8 Sin Ming Road #01-58/60/62 Sin Ming Est
Estimated Period of Repair:	1.0 days	Singapore 575643

Adjuster: KENNETH KONG**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*LH OUTER PARKING SENSOR	Scratched	305.00 FL	*305.00 FL
2	1		*FRONT LH BUMPER BRACKET	Serviceable	86.00 FL	*- FL
3	1		*LH DAYLIGHT	Serviceable	574.00 FL	*- FL
4	1		*LH DAYLIGHT COVER	Serviceable	48.00 FL	*- FL
5	1		*RH WASHER COVER	Serviceable	340.00 FL	*- FL
F=Franchise part. L=ListItemDisc.						
					Sub Total (\$)	1,353.00
					- List Item Discount on L Items 10.00/10.00% (\$)	305.00
						135.30
					Total Parts (\$)	274.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO KNOCK JACKOUT DAMAGED PARTS ,PANEL BEATING ,WELDING,ALIGN REFIX AND TO RENEW ACCIDENT PARTS	New	350.00	120.00
2	SPRAY PAINTING ON AFFECTED & REPLACE PARTS	New	500.00	220.00
Gross Labour Cost (S\$)			850.00	340.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >