

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC4/AIG21012751/KEA3Q2**Date:** 18/04/2022**REFERENCE**

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100506614-04  
**Claimant Vehicle No :** SLP2009L **Insured Vehicle No :** SLA37Y  
 Date of Loss: 15/12/2021 Nature of Claim: TP Claim No: 0134761503SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No: **SLP2009L**  
 Make & Model: TOYOTA COROLLA ALTIS, 1.6 CVT (A) Engine No: 1ZRY334230  
 Reg. Date: 29/05/2017 (Man. Year: 2016) Chassis No: MR053REH104558447  
 Colour: Metallic Brown Odometer: 72082 km  
 Engine Capacity: 1598 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (S\$): **Market Value/New Car Price**

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size: 215/45 R17 Rear Tyre Size: 215/45 R17  
 Front Left Side: Yokohama 9 mm Rear Left Side: Yokohama 9 mm  
 Front Right Side: Yokohama 9 mm Rear Right Side: Yokohama 9 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	4,624.68	2,884.31	1,740.37	37.63
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,975.00	1,480.00	495.00	25.06
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>6,599.68</b>	<b>4,364.31</b>	<b>2,235.37</b>	<b>33.87</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>3,400.00</b>		
<b>(S\$)</b>	6,599.68	3,400.00	3,199.68	48.48
<b>+ GST 7.00/7.00% (S\$)</b>	461.98	238.00	223.98	48.48
<b>Nett Amount (S\$)</b>	<b>7,061.66</b>	<b>3,638.00</b>	<b>3,423.66</b>	<b>48.48</b>
<b>+ Car Rental (8.0 x S\$100.00/day) (S\$)</b>		800.00		
<b>+ Doc/Search Fee (S\$)</b>		2.00		
<b>Nett Liability (S\$)</b>		<b>4,440.00</b>		

**INSPECTION**

Date of Assignment: 16/12/2021  
 Date Inspected: 27/12/2021 Inspected At: S & H Motor Pte Ltd (Sin Ming)  
 160 Sin Ming Drive #07-02, Sin Ming AutoCity  
 Singapore 575722  
 Estimated Period of Repair: 5.0 days

**Adjuster:** KENNETH KONG**Manager:** Asher Sng Rong Yi*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and*

*ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT	Buckled	725.00 FL	*725.00 FL
2	1		*REAR BOOT EMBLEM	Necessary	61.90 FL	*61.90 FL
3	1		*REAR BOOT CHROME MOULDING	Serviceable	352.80 FL	*- FL
4	1		*REAR BOOT BADGE COROLLA	Necessary	67.80 FL	*67.80 FL
5	1		*REAR BOOT BADGE ALTIS	Necessary	61.90 FL	*61.90 FL
6	1		*REAR BOOT INNER LOCK	Dented	352.00 FL	*281.00 FL
7	1		*REAR BOOT WEATHERSTRIP (50%)	Cut	155.68 FS	*97.30 FS
8	1		*RH REAR BOOT INNER TAIL LAMP	Serviceable	270.10 FL	*- FL
9	1		*LH REAR BOOT INNER TAIL LAMP	Serviceable	270.10 FL	*- FL
10	1		*RH REAR BOOT HINGE	Repair	70.70 FL	*- FL
11	1		*LH REAR BOOT HINGE	Repair	70.70 FL	*- FL
12	1		*REAR BUMPER	Buckled	480.50 FL	*480.50 FL
13	1		*SET REAR BUMPER CLIPS	Necessary	28.00 FL	*28.00 FL
14	1		*REAR BUMPER REINFORCEMENT	Bent	386.00 FL	*386.00 FL
15	1		*RH REAR BUMPER RETAINER	Distorted	91.70 FL	*91.70 FL
16	1		*LH REAR BUMPER RETAINER	Distorted	91.70 FL	*91.70 FL
17	1		*RH REAR BUMPER BRACKET	Repair	93.70 FL	*- FL
18	1		*LH REAR BUMPER BRACKET	Repair	93.70 FL	*- FL
19	1		*REAR END PANEL	Bent	645.30 FL	*562.10 FL
20	1		*REAR END PANEL TOP GARNISH	Dented	197.10 FL	*197.10 FL
21	1		*SET REAR END PANEL TOP GARNISH CLIPS	Necessary	35.00 FL	*35.00 FL
22	1		*RH OUTER TAIL LAMP	Cracked	379.65 FL	*379.65 FL
23	1		*LH OUTER TAIL LAMP	Serviceable	379.65 FL	*- FL
24	1		*REAR NUMBER PLATE	Serviceable	45.00 FS	*- FS
25	1		*SET REAR PARKING SENSORS	Shorted	260.00 FS	*200.00 FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (S\$)					5,665.68	3,746.65
- List Item Discount on L Items 20.00/25.00% (S\$)					1,041.00	862.34
Total Parts (S\$)					4,624.68	2,884.31

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE REAR DAMAGED PARTS ,TO JACK OUT REAR END PANEL AND REAR FLOOR PANEL AND CUT OUT BODY PANEL ,TO REWELD ,RESHAPE AND REPAIR REAR END PANEL ,REAR FLOOR PANEL,REAR BODY PANEL,RH AND LH REAR FENDER ,TO STRAIGHTEN OUT REAR CHASSIS MEMBER ,TO REPLACE DAMAGED PARTS AND ADJUST REAR BODY AND TAILGATE ALIGNMENT	New	750.00	600.00
2	TO SPRAY PAINT AFFECTED REAR AND INNER DAMAGED PORTION INCLUSIVE OF PREPARATORY WORKS AND MATERIAL	New	1,100.00	800.00
3	TO DISCONNECT WIRE HARNESS TO FACILITATE REPAIRS AND CHECK FOR DAMAGE AND RECONNECT WIRING SYSTEM AND CHECK FOR FULL FUNCTIONALITY	New	25.00	20.00
4	TO APPLY ANTI-CORROSION TUFF-KOTE	New	100.00	60.00
<b>Gross Labour Cost (\$\$)</b>			<b>1,975.00</b>	<b>1,480.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >