

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC3/AIG21012754/KPA3Q2**Date:** 27/10/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	7210020392
Claimant Vehicle No :	SHD5697R	Insured Vehicle No :	SMY4556B
Date of Loss:	13/12/2021	Nature of Claim:	TP
		Claim No:	3479309799SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHD5697R		
Make & Model:	TOYOTA PRIUS, 1.8 5DR HATCHBACK (A)	Engine No:	22R2B54796
Reg. Date:	26/10/2018 (Man. Year: 2018)	Chassis No:	JTDKB3FUX03074491
Colour:	Metallic Pearl White/Red	Odometer:	277642 km
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Sailun 7 mm	Rear Left Side:	Sailun 8 mm
Front Right Side:	Sailun 7 mm	Rear Right Side:	Sailun 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,816.67	3,811.97	6,004.70	61.17
Miscellaneous Items	0.00	0.00	0.00	
Labour	10,290.00	1,580.00	8,710.00	84.65
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	20,106.67	5,391.97	14,714.70	73.18
Approved Total (Overridden) (\$\$)		4,300.00		
(\$\$)	20,106.67	4,300.00	15,806.67	78.61
+ GST 7.00/7.00% (\$\$)	1,407.47	301.00	1,106.47	78.61
Nett Amount (\$\$)	21,514.14	4,601.00	16,913.14	78.61
+ Car Rental (6.0 x S\$96.30/day) (\$\$)		577.80		
+ Doc/Search Fee (\$\$)		7.45		
Nett Liability (\$\$)		5,186.25		

INSPECTION

Date of Assignment:	15/12/2021		
Date Inspected:	15/12/2021	Inspected At:	Trans-Cab Services Pte Ltd (HQ) 2 Ang Mo Kio Street 63 Singapore 569111
Estimated Period of Repair:	5.0 days		

Adjuster: KENNETH KONG

Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*COVER ,REAR BUMPER	Bent	442.60 FL	*442.60 FL
2	1		*REINFORCEMENT SUB-ASSY ,REAR BUMPER	Bent	332.70 FL	*332.70 FL
3	1		*COVER ,REAR BUMPER ,LOWER	Dented	15.40 FL	*15.40 FL
4	1		*GUARD ,REAR BUMPER ,CENTER	Bent	576.30 FL	*576.30 FL
5	1		*SEAL ,REAR BUMPER SIDE ,LH	Serviceable	88.50 FL	*- FL
6	1		*RETAINER ,REAR BUMPER SIDE ,LH	Serviceable	116.50 FL	*- FL
7	1		*RETAINER ,REAR BUMPER SIDE ,RH	Serviceable	117.70 FL	*- FL
8	1		*FILLER ,REAR BUMPER EXTENSION ,LH	Serviceable	123.70 FL	*- FL
9	1		*FILLER ,REAR BUMPER EXTENSION ,RH	Mtg Cracked	123.70 FL	*123.70 FL
10	1		*PANEL SUB-ASSY ,BACK DOOR	Repair	1,147.80 FL	*- FL
11	1		*PLATE ,LUGGAGE COMPARTMENT DOOR NAME NO.2	Necessary	54.60 FL	*54.60 FL
12	1		*PLATE ,BACK DOOR NAME ,NO.1	Necessary	54.60 FL	*54.60 FL
13	1		*ORNAMENT SUB-ASSY ,BACK DOOR	Necessary	47.90 FL	*47.90 FL
14	1		*LOCK ASSY ,BACK DOOR W/COURTESY LAMP SWITCH	Repair	467.00 FL	*- FL
15	1		*STAY ASSY ,BACK DOOR ,LH	Serviceable	242.50 FL	*- FL
16	1		*STAY ASSY ,BACK DOOR ,RH	Serviceable	242.50 FL	*- FL
17	1		*HINGE ASSY ,BACK DOOR ,LH	Repair	61.00 FL	*- FL
18	1		*HINGE ASSY ,BACK DOOR ,RH	Repair	61.00 FL	*- FL
19	1		*GARNISH SUB-ASSY ,BACK DOOR ,OUTSIDE	Cracked	925.60 FL	*925.60 FL
20	1		*BOARD ASSY ,BACK DOOR TRIM	Serviceable	259.20 FL	*- FL
21	1		*WEATHERSTRIP ,BACK DOOR	Serviceable	372.30 FL	*- FL
22	1		*COVER ,FLOOR UNDER ,NO.1 LH	Serviceable	175.10 FL	*- FL
23	1		*COVER ,FLOOR UNDER ,NO.2 RH	Serviceable	241.90 FL	*- FL
24	1		*COVER ,REAR FLOOR CTR	Serviceable	229.90 FL	*- FL
25	1		*PANEL SUB-ASSY ,BODY LOWER BACK	Repair	650.30 FL	*- FL
26	1		*COVER ,FRONT BUMPER	Bent	516.00 FL	*516.00 FL
27	1		*REINFORCEMENT SUB-ASSY ,FRONT BUMPER	Repair	716.60 FL	*- FL
28	1		*ABSORBER ,FRONT BUMPER ENERGY	Serviceable	79.60 FL	*- FL
29	1		*BRACKET ,FRONT BUMPER SIDE ,LH	Serviceable	59.30 FL	*- FL
30	1		*BRACKET ,FRONT BUMPER SIDE ,RH	Serviceable	59.30 FL	*- FL
31	1		*HOOD SUB-ASSY	Bent	983.10 FL	*983.10 FL
32	1		*HINGE ASSY ,HOOD ,LH	Repair	58.90 FL	*- FL
33	1		*HINGE ASSY ,HOOD ,RH	Repair	58.90 FL	*- FL
34	1		*GRILLE SUB-ASSY ,RADIATOR	Cracked	346.00 FL	*346.00 FL
35	1		*GRILLE ,RADIATOR LOWER NO.1	Serviceable	170.10 FL	*- FL
36	1		*EMBLEM ASSY ,RADIATOR GRILLE	Missing	90.80 FL	*90.80 FL
37	1		*SET PARKING AID	Dented	700.00 FS	*220.00 FS
38	1		*SET REAR BUMPER CLIP	Necessary	95.00 FS	*50.00 FS
39	2		*WINDSCREEN SEALANT	Not Necessary	150.00 FS	*- FS
40	1		*WINDSCREEN MOULDING	Not Necessary	200.00 FS	*- FS
41	1		*WINDSCREEN INNER SPONGE SEAL	Not Necessary	130.00 FS	*- FS
42	1		*REAR TAILGATE STICKER TRANS-CAB	Necessary	80.00 FS	*30.00 FS
43	1		*REAR TAILGATE STICKER 6555-3333	Necessary	80.00 FS	*30.00 FS
44	1		*REAR BUMPER PROTECTOR	Necessary	180.00 FS	*50.00 FS
45	1		*SET REAR BUMPER RETAINER CLIP	Not Necessary	85.00 FS	*- FS
46	1		*REAR NUMBER PLATE WITH HOLDER	Serviceable	140.00 FS	*- FS
47	1		*END PANEL TRIM CLIP	Not Necessary	65.00 FS	*- FS
48	1		*SET BUMPER CLIP FRT	Necessary	95.00 FS	*50.00 FS
49	1		*SET FRT BUMPER RETAINER CLIP	Not Necessary	85.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) **12,393.90** **4,939.30**

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
- List Item Discount on L Items 25.00/25.00% (S\$)					2,577.23	1,127.33
Total Parts (S\$)					9,816.67	3,811.97

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND REFIT REAR BIG AND SMALL W/SCREEN GLASS TO FACILITATE BODYWORK REPAIR	New	300.00	0.00
2	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH,FITTINGS AND OTHER ,TO ENABLE REPAIR	New	380.00	0.00
3	PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME.	New	2,200.00	600.00
4	TO TRANSFER OF REAR END PANEL FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	380.00	0.00
5	TO TRANSFER OF TAILGATE FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	New	180.00	0.00
6	TO REMOVE AND REFIT ELECTRICAL WIRING BATTERY AND OTHER NECESSARY ITEMS TO FACILITATE BODYWORK REPAIR	New	480.00	0.00
7	TO TRANSFER OF FENDER FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	480.00	0.00
8	TO DISMANTLE AND REFIT AIRCON ASSY AND ATTACHMENT VACUUM AND CHARGE-IN-GAS	New	380.00	0.00
9	LABOUR CHARGE TO MOUNT AND DISMOUNT VEHICLE ON JIG BENCH TO FACILITATE REPAIR	New	380.00	0.00
10	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	0.00
11	TO RUST-PROOFING AND APPLY UNDERCOAT OF THE AFFECTED AREAS	New	250.00	30.00
12	TOWING FEES	New	150.00	0.00
13	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	2,200.00	880.00
14	TO REINSTALL REAR BUMPER PARKING SENSOR	New	170.00	50.00
15	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	20.00
16	TO TRANSFER OF LUGGAGE FLOOR PANEL FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	380.00	0.00
17	TO TRANSFER OF TIRE ,RIM AND ON WHEEL BALANCING	New	220.00	0.00
18	TO REPLACE ,REFIX AND TOP UP COOLANT FOR RADIATOR	New	170.00	0.00
19	TO LIFT -UP/ OUT ENGINE WITH GEAR BOX AND REFIT	New	440.00	0.00
20	TO REMOVE AND REFIT RADIATOR SUPPORT CROSS -MEMBER AND OTHER NECESSARY ITEMS TO ENABLE BODYWORK REPAIR	New	380.00	0.00
21	TO CONDUCT AND PERFORM A COMPREHENSIVE VEHICLE DIAGNOSTIC CHECK AND RESET VEHICLE WARNING INDICATORS	New	380.00	0.00
Gross Labour Cost (\$\$)			10,290.00	1,580.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >