4/8/22, 12:40 PM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III21012756/GPA3Q2

Date: 08/04/2022

REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D19MFL0005549_02

Claimant Vehicle SMS2915T Insured Vehicle No: GBG1949X

Date of Loss: 14/12/2021 Nature of Claim: TP Claim No: MFL2021D0005479

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SMS2915T

 Make & Model:
 MITSUBISHI OUTLANDER, 2.0 (A)
 Engine No:
 4J11BD7811

 Reg. Date:
 20/02/2020 (Man. Year: 2019)
 Chassis No:
 GF7W0601711

 Colour:
 Red
 Odometer:
 25120 km

Engine Capacity: 1998 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/55 R18 Rear Tyre Size: 225/55 R18
Front Left Side: Toyo 6 mm
Front Right Side: Toyo 6 mm
Rear Rear Right Side: Toyo 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		2,130.00	1,439.00	691.00	32.44
Miscellaneous Items		0.00	0.00	0.00	
Labour		4,760.00	2,710.00	2,050.00	43.07
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Gross Total (S\$)	6,890.00	4,149.00	2,741.00	39.78
	+ GST 7.00/7.00% (S\$)	482.30	290.43	191.87	39.78
	Nett Amount (S\$)	7,372.30	4,439.43	2,932.87	39.78

+ Car Rental (3.0 x S\$150.00/day + 7.00% GST) (S\$) 481.50 + Doc/Search Fee (S\$) 7.45

Nett Liability (S\$) 4,928.38

INSPECTION

Date of Assignment: 15/12/2021

Cycle & Carriage Fulco Motor Dealer Pte Ltd (HQ)

Date Inspected: 20/12/2021 Inspected At: 330 Ubi Road 3

Singapore 408650

Estimated Period of Repair: 4.0 days

Adjuster: XING GUO QIANG Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

 \sim	-	re	_	_	$\overline{}$

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 14 Mar 2022)

Parts: M1-SUV MITSUBISHI OUTLANDER 2.0 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SMS2915T)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER PLATE PROTECTOR (OWNER PURCHASED)	Necessary	150.00 FS	*150.00 FS
2	1		*REVERSE SENSOR (ITEMS & INSTALLATION INCUDED)	Not Necessary	280.00 FS	*-FS
3	1		*FACE ,RR BUMPER	Scratched	799.00 FS	*799.00 FS
4	10		*CLIP, BUMPER	Necessary	40.00 FS	*40.00 FS
5	1		*LH SIDE BRACKET ,RR B	Not Necessary	12.00 FS	*-FS
6	1		*RH SIDE BRACKET ,RR B	Not Necessary	12.00 FS	*-FS
7	1		*EXTENSION ,RR BUMPER	Deformed	360.00 FS	*360.00 FS
8	1		*LH REFLECTOR ,TAIL LA	Not Necessary	100.00 FS	*-FS
9	1		*RH REFLECTOR ,TAIL LA	Not Necessary	100.00 FS	*-FS
10	1		*ANTENNA ,KEYLESS OPER	Not Necessary	96.00 FS	*-FS
11	1		*BUZZER ,KEYLESS OPERA	Not Necessary	91.00 FS	*-FS
12	1		*PROVIDE NANONIX C7 CERAMIC COATING @ REAR BUMPER (OWNER PURCHASED)	Necessary	90.00 FS	*90.00 FS
F=Fr	nchise	part. S=	SpcNett.			
				Total Parts (S\$)	2,130.00	1,439.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Lab</u>	our Items			
1	DIAGNOSTIC /SCANNING	New	250.00	250.00
2	TO CHECK ALL LIGHTING /WIRING SYSTEM ON REAR ACCIDENT AFFECTED AREAS	New	100.00	80.00
3	TO REMOVE & REINSTALL ALL CARPETS /TRIMMING TO FACILITATE REPAIR ON REAR ACCIDENT AFFECTED AREAS	New	640.00	0.00
4	TO APPLY SEALANT KIT ON NEW & REPAIR PANELS	New	200.00	0.00
5	TO REPLACE REAR BUMPER CLIPS ,BRACKETS ,EXTENSION BUMPER REFLECTOR LAMP ,ANTENNA BUZZER ETC TO REPAIR REAR END PANEL STRAIGHTEN ,REFORM ,ALIGN ON REAR ACCIDENT AFFECTED AREAS	New	1,920.00	1,280.00
6	SPRAY PAINTING ON REAR ACCIDENT AFFECTED AREAS	New	1,650.00	1,100.00
	Gross Labour Cost (S\$)		4,760.00	2,710.00
	Report was unsubmitted during this	orint-out.		

< END OF ESTIMATES >