



CYCLE & CARRIAGE

CYCLE & CARRIAGE·FULCO MOTOR DEALER PTE LTD
EUNOS LINK SERVICE CENTRE

330 Ubi Road 3 Singapore 408650 Tel: 67461000 Fax: 64875857

**ESTIMATE**

Invoice Name & Address	Owner Name & Vehicle Info	
INDIA INTERNATIONAL INSURANCE SINGA 64 CECIL STREET #04-05 IOU BUILDING SINGAPORE 049711 Contact No	Cust No/Name	KCV15414/Mr Leow Yu Lung(Liao Yulong)
	Reg No/Reg Date	SMS2915T / 20/02/2020
	Date In/Mileage	03/01/2022/ 25735
	Chassis No	GF7W0601711
	Engine No	4J11BD7811
	Make/Model	MIT/19MY OUTLANDER 2.0 ELEG (995)
	Colour/Trim	P02 / BK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
F0000036	Credit	05/01/2022/ 16:02	DS	303 / Renemer	23672

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
Z NOTES ACCIDENT ON 14/12/2021 ALONG PUNGGOL CENTRAL ROAD OWNER CLAIMING THIRD PARTY LOSS OF RENTAL TP#: GBG1949X TP INS: INDIA INT'L INS				
S MIPNT88088 DIAGNOSTIC/SCANNING				250.00
S MIPNT88088 TO CHECK ALL LIGHTING/WIRING SYSTEM ON REAR ACCIDENT AFFECTED AREAS				80.00
S MIPNT88088 TO REPLACE REAR BUMPER,CLIPS,EXTENSION BUMPER,REAR BUMPER PLATE. -TO REPAIR REAR END PANEL				1280.00
S MIPNT98088 STRAIGHTEN,REFORM,ALIGN ON REAR ACCIDENT AFFECTED AREAS				1100.00
S MIPNT88088 SPRAY PAINTING ON REAR ACCIDENT AFFECTED AREAS (REAR BUMPER,REAR END PANEL)				150.00
S MIPNT88088 REAR BUMPER PLATE PROTECTOR				90.00
S MIPNT88088 PROVIDE NANONIX C7 CERAMIC COATING @ REAR BUMPER (OWNER PURCHASED)				
M JJ6410F219 FACE,RR BUMPER	1.00	799.00	0.00	799.00
M JJMR200300 CLIP,BUMPER	10.00	4.00	0.00	40.00
X JJ85010W001P EXTENSION,RR BUMPER	1.00	360.00	0.00	360.00
Z NOTES FINALIZATION (NO. OF TOTAL REPAIR DAYS - 4 DAYS) ATTENTION TO: MR. GUO QIANG				

Confirm & accepted by

Parts	1,199.00
Labour	0.00
Standard Menu	0.00
Specialist Job	2,950.00
Others(Lub,etc)	0.00
Sundry	0.00
Total(w/o GST)	4,149.00

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.