

CYCLE & CARRIAGE-FULCO MOTOR DEALER PTE LTD **EUNOS LINK SERVICE CENTRE**



330 Ubi Road 3 Singapore 408650 Tel: 67461000 Fax: 64875857

ESTIMATE

Invoice Name & Address	Owner Name & Vehicle Info		
INDIA INTERNATIONAL INSURANCE SINGA 64 CECIL STREET #04-05	Reg No/Reg Date		
IOU BUILDING SINGAPORE 049711	Date In/Mileage Chassis No	15/12/2021/ 24911 GF7W0601711	
	Engine No	4J11BD7811	
Contact No	Make/Model	MIT/19MY OUTLANDER 2.0 ELEG (995)	
	Colour/Trim	P02 / BK	

Account No	Terms	Date/Time Printed	CSE	Operator		WIP No	100	
F0000036	Credit		DS	303 / Renemer		23672		
F0000036	Credit	Description of Goods		ARE THE TAX	Qty	Unit Price	Disc%	Amount
Z NOTES		Bescription of Coope						
ACCIDENT	ON 14/12	2/2021 ALONG PUNGGOL	CENTRAL RO	DAD				
		HIRD PARTY						
REQUIRED								
TP#: GBG		TP INS: INDIA	INT'L INS					250.00
S MIPNT8808	38							250.00
DIAGNOST	IC/SCANN	ING						& 100.00
S MIPNT8808	38			ASSESTED	ADEAC			200.00
TO CHECK	ALL LIGH	HTING/WIRING SYSTEM C	ON REAR ACC	CIDENT AFFECTED	AKEAS			/× 640.00
S MIPNT8808	38						4.50	
TO REMOVE	& RE-IN	NSTALL ALL CARPETS/TE	SIMMING	HACILITATE			NΜ	1
		CCIDENT AFFECTED AREA	8-774	110015	2175/0)		\ X 200.00
S MIPNT8808	38	WIT ON NEW PERAID	Ja IGIAO	(c	71146	7		///
		KIT ON NEW & REPAIR	PANELS		700			640 1920.00
S MIPNT8808	38 SE DEAD D	BUMPER, CLIPS, BRACKETS	FXTENSION	BUMPER.				
10 KEPLAC	L KEAK B	TENNA, BUZZER, ETC	, LATERISTO	, , , , , , , , , , , , , , , , , , , ,				
-TO REPAI	C LAMP, AN	IND DANFI						
- TO KEPAI	N DEFORM	ALIGN ON REAR ACCID	ENT AFFECT	ED AREAS				5501650.00
S MIPNT9808	IN, KLI OKI	, ALIGN ON KEAN AGES						\$ \$ 650.00
CDDAY PAT	NTING ON	REAR ACCIDENT AFFEC	TED AREAS					280.00
MIDNIAROR	38			X NN.				200.00
REVERSE S	ENSOR (I	TEMS & INSTALLATION	INLCUDED)	\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \				150.00
. MITCHITCOCC	0.0			/ NCC				150.00
REAR BUMP	ER PLATE	PROTECTOR (OWNER PU	RCHASED)	Ser	1.00	799.00	10.00	719.10
1 JJ6410D73	8	FACE RR BUMP			10.00		10.00	36.00
JJMR20030		CLIP, BUMPER	/ NO. 0	X (NN	1.00		10.00	10.80
JJ6410D33	6	LH SIDE BRAC	KEI, KK B	× /	1.00		10.00	10.80
JJ6410D33		RH SIDE BRAC	REI,KK B	Dre.	1.00	360.00	10.00	324.00
1 JJ6415A09		EXTENSION,RR LH REFLECTOR	TATI IA	× 1 al	1.00	100.00	10.00	90.00
1 JJ8336A15		RH REFLECTOR	TATE LA	3 LMN	1.00	100.00	10.00	90.00
	4	ANTENNA, KEYL	FSS OPER	\times	1.00	96.00	10.00	86.40
4 JJ8336A15 4 JJ8637B11		ANIENNA KETI						

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include Estimated costs quoted are excluding doll ne models mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered any additional parts or labour whiteh may be required after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a after work has started and needed for repairs or replacement, nowever, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing cheques and on other requiring the removal of the windscreen. the rubber seal or other repair requiring the removal of the windscreen.

Page 1 of 2



CYCLE & CARRIAGE-FULCO MOTOR DEALER PTE LTD **EUNOS LINK SERVICE CENTRE**



330 Ubi Road 3 Singapore 408650 Tel: 67461000 Fax: 64875857

ESTIMATE

Invoice Name & Address	Owner Name & Vehicle Info		
INDIA INTERNATIONAL INSURANCE SINGA 64 CECIL STREET #04-05 IOU BUILDING SINGAPORE 049711	Reg No/Reg Date Date In/Mileage	KCV15414/Mr Leow Yu Lung(Liao Yulong) SMS2915T / 20/02/2020 15/12/2021/ 24911 GF7W0601711	
	Engine No	4J11BD7811	
Contact No	Make/Model Colour/Trim	MIT/19MY OUTLANDER 2.0 ELEG (995) PO2 / BK	

				Overstor	SERVICE OF	WIP No	
Account No	Terms	Date/Time Printed	CSE	Operator		23672	
F0000036				303 / Renemer	Qty	Unit Price Disc%	Amount
1000000	Mar.	Description of Good	s / Service	95	1.00	91.00 10.00	
M JJ8637A	176	BUZZER,KEYL	ESS OPERA	$\times NV$.	2.00		



LKK Auto Consultants hence notify

the Repairer of the following:

To resurvey before/after spray painting

To display damaged part(s) during resurvey

Parts prices are subject to confirmation

Acknowledged by Repairer Signature:

Date:

hefue pant phres. Guo Qian - 8288 0282 20/12/21

	Parts	1,449.00
	Labour Standard Menu Specialist Job Others(Lub,etc) Sundry Total(w/o GST)	0.00 0.00 5,190.00 0.00 0.00 6,639.00
Authorized Signatory and Sample		rad

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include estimated costs quoted are excluding our including the required after repair work has commenced. Occasionally worn or damaged parts are discovered any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered any additional parts or labour which may be required after legal, work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen. Page 2 of 2