

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/GRB21011668/UQF3E2-1

Date: 07/01/2022

REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D21MFL0000447
Claimant Vehicle No : SKH5535T **Insured Vehicle No :** SLQ2153Y
Date of Loss: 15/11/2021 Nature of Claim: TP Claim No: MFL2021D0004939

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKH5535T**
Make & Model: HONDA CIVIC, 1.3 EC8 (M) Engine No: K20Z23501386
Reg. Date: 28/08/2008 (Man. Year: 2008) Chassis No: JHMFD26408S201378
Colour: Beige/White Odometer: 341438 km
Engine Capacity: 1998 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/45 R17 Rear Tyre Size: 225/45 R17
Front Left Side: Toyo 6 mm Rear Left Side: Toyo 6 mm
Front Right Side: Toyo 6 mm Rear Right Side: Toyo 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,244.24	2,134.84	3,109.40	59.29
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,800.00	1,720.00	1,080.00	38.57
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,044.24	3,854.84	4,189.40	52.08
Approved Total (Overridden) (S\$)		3,100.00		
Nett Amount (S\$)	8,044.24	3,100.00	4,944.24	61.46

INSPECTION

Date of Assignment: 17/12/2021
Date Inspected: 16/11/2021 Inspected At: Freesion Autodrive (Kaki Bukit)
25 Kaki Bukit Rd 4, Synergy @KB #03-33
Singapore 417800
Estimated Period of Repair: 5.0 days

Adjuster: MARCUS CHUA

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 07 Jan 2022)
Parts:	144	HONDA CIVIC 1.3 EC8 (M) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKH5535T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Torn	645.50 FL	*645.50 FL
2	1		*REAR BUMPER SIDE RETAINER LH	Cracked	22.80 FL	*22.80 FL
3	1		*REAR FENDER LH	Repair	895.40 FL	*- FL
4	1		*REAR WINDSCREEN GLASS MOULDING	Not Necessary	112.80 FL	*- FL
5	1		*REAR DOOR LH	Repair	865.40 FL	*- FL
6	1		*REAR DOOR INNER LOCK LH (NO DAMAGED)	Not Necessary	205.40 FL	*- FL
7	1		*REAR DOOR OUTER PROTECTOR LH	Warped	124.80 FL	*124.80 FL
8	1		*REAR DOOR OUTER HANDLE COVER LH	Not Necessary	96.80 FL	*- FL
9	1		*REAR DOOR WEATHERSTRIP	Not Necessary	175.80 FL	*- FL
10	1		*ROCKER PANEL LH	Repair	552.00 FL	*- FL
11	1		*TAIL LAMP LH	Serviceable	225.90 FL	*- FL
12	1		*REAR WHEEL BEARING LH	Damaged	166.00 FL	*166.00 FL
13	1		*REAR WHEEL BEARING HUB LH	Damaged	198.70 FL	*198.70 FL
14	1		*REAR SHOCK ABSORBER LH	Serviceable	301.00 FL	*- FL
15	1		*ROCKER PANEL SIDE SKIRT LH	Deformed	628.80 FS	*628.80 FS
16	1		*REAR TYRE RIM LH	Cut	559.80 FS	*559.80 FS
17	1		*REAR WINDSCREEN SEALANT	Not Necessary	50.00 FS	*- FS
18	1		*SET REAR BUMPER CLIPS	Necessary	45.00 FS	*20.00 FS
19	1		*REAR FENDER SEALANT	Not Necessary	40.00 FS	*- FS
20	1		*REVERSE SENSOR	Not Necessary	250.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	6,161.90	2,366.40
- List Item Discount on L Items 20.00/20.00% (\$\$)	917.66	231.56
Total Parts (\$\$)	5,244.24	2,134.84

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE, REPLACE, CUT, WELD, KNOCK OUT DENTS TO STRAIGHTEN ACCIDENT PARTS AS-MENTIONED ON THE PARTS REPAIR COLUMN INCLUSIVE OF REPLACEMENT PARTS	New	1,035.00	600.00
2	PUTTY & SPRAY PAINTING TO ADJACENT PANELS. JOB ALLOWANCE. PAINT / MATERIAL (5 PANELS)	New	1,100.00	900.00
3	APPLY RUST PROOFING ON THE ADJACENT PANELS	New	80.00	0.00
4	WIRING AND BULB CHECKING	New	36.00	20.00
5	REMOVE AND REFIX REAR WINDSCREEN GLASS (2-MAN JOB)	New	157.50	0.00
6	CONDUCT WATER LEAK TEST FOR REAR PORTION ASSOCIATED REPAIR WORKS	New	45.00	0.00
7	TRANSFER OF EXISTING REAR DOOR MECHANISM TO NEW DOOR LH	New	90.00	0.00
8	REMOVE AND REFIX REAR BUMPER REVERSE SENSOR & CONDUCT DISTANCE SAFETY SETTING	New	76.50	50.00
9	REMOVE AND REPLACE REAR UNDERCARRIAGE WORK LH	New	180.00	150.00
Gross Labour Cost (\$\$)			2,800.00	1,720.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >