

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG21012764/UPS3Q2**Date:** 07/03/2022REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

Claimant Vehicle No : FBN1159Y**Insured Vehicle No :** SKD8768P

Date of Loss: 11/12/2021

Nature of Claim: TP

Claim No: 7353857423SG

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **FBN1159Y**

Make & Model: YAMAHA NMAX155, 155cc ABS CVT

Engine No: G3H6E0014548

Reg. Date: 10/09/2019 (Man. Year: 2019)

Chassis No: MH3SG431000011694

Colour: White

Odometer: 0 km

Engine Capacity: 155 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 110/70-13

Rear Tyre Size: 130/70-13

Front Left Side: Timsun 6 mm

Rear Left Side: Timsun 6 mm

Front Right Side: 0 mm

Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,026.00	3,079.75	946.25	23.50
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,564.00	995.00	569.00	36.38
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,590.00	4,074.75	1,515.25	27.11
Approved Total (Overridden) (S\$)		3,250.00		
(S\$)	5,590.00	3,250.00	2,340.00	41.86
+ GST 7.00/7.00% (S\$)	391.30	227.50	163.80	41.86
Nett Amount (S\$)	5,981.30	3,477.50	2,503.80	41.86
+ Loss of Use (4.0 x S\$20.00/day) (S\$)		80.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		3,559.50		

INSPECTION

Date of Assignment: 17/12/2021

Date Inspected: 17/12/2021

Inspected At:

Ban Hock Hin Co. Pte Ltd (HQ)

No. 6 Defu Lane 4

Singapore 539410

Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA**Manager:** CHEW HSIAO TONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and*

ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*AXLE FRONT WHEEL	Cut	14.00 F	*14.00 FL
2	2		*BEARING 6300 LLU (NTN)	Necessary	32.00 F	*32.00 FL
3	1		*BELLY PAN	Cut	35.00 F	*35.00 FL
4	1		*BOARD FOOTREST LH	Cut	55.00 F	*55.00 FL
5	1		*BOARD FOOTREST RH	Cut	55.00 F	*55.00 FL
6	4		*BOLT MUDGUARD	Necessary	46.00 F	*46.00 FL
7	1		*BOOT CALIPER	Not Necessary	11.50 F	*- FL
8	1		*BOX FILTER AIR OUTER FRONT	Grazed	10.50 F	*10.50 FL
9	1		*BOX REAR (GIVI) E450N BLACK W/O STOP LIGHT	Crumpled	222.00 F	*200.00 FL
10	1		*BRACKET CALIPER FRONT	Not Necessary	37.00 F	*- FL
11	1		*CALIPER BOOT 2	Not Necessary	9.00 F	*- FL
12	1		*CAMERA (V-SYS) M6 (WIFI VERSION)	Damaged	362.00 F	*362.00 FL
13	10		*CLIP NUT SPRING	Necessary	15.00 F	*15.00 FL
14	1		*COLLAR RIM FRONT	Necessary	20.00 F	*20.00 FL
15	1		*COVER REAR HANDLE LOWER	Cut	16.00 F	*16.00 FL
16	1		*COVER CLUTCH OUTER	Not Necessary	28.00 F	*- FL
17	1		*COVER CLUTC OUTER DAMPER 1	Not Necessary	12.00 F	*- FL
18	1		*COVER CLUTC OUTER DAMPER 2	Not Necessary	7.00 F	*- FL
19	1		*COVER CLUTC OUTER DAMPER 3	Not Necessary	7.00 F	*- FL
20	1		*COVER CLUTC OUTER DAMPER 4	Not Necessary	12.00 F	*- FL
21	1		*COVER FRONT LOWER (WHITE)	Broken	22.00 F	*22.00 FL
22	1		*COVER FRONT UPPER (WHITE)	Broken	38.00 F	*38.00 FL
23	1		*COVER LEG SHIELD	Cut	16.00 F	*16.00 FL
24	1		*COVER SIDE LH (GREY)	Cracked	38.00 F	*38.00 FL
25	1		*COVER SIDE LOWER LH (WHITE)	Distorted	22.00 F	*22.00 FL
26	1		*COVER SIDE LOWER RH (WHITE)	Cut	22.00 F	*22.00 FL
27	1		*COVER UPPER HANDLE	Not Necessary	16.00 F	*- FL
28	1		*COWLING FRONT LH (WHITE)	Broken	35.00 F	*35.00 FL
29	1		*COWLING FRONT RH (WHITE)	Broken	35.00 F	*35.00 FL
30	1		*DAMPER PLATE	Necessary	3.00 F	*3.00 FL
31	1		*EMBLEM	Necessary	9.00 F	*9.00 FL
32	2		*EMBLEM (YAMAHA) LOGO	Necessary	30.00 F	*30.00 FL
33	1		*FENDER INNER	Cracked	30.00 F	*30.00 FL
34	1		*FORK FRONT ASSY	Bent / Twisted	763.00 F	*763.00 FL
35	1		*GROMMET	Necessary	6.00 F	*6.00 FL
36	1		*HEADLAMP ASSY	Broken	308.00 F	*308.00 FL
37	1		*HORN	Damaged	30.00 F	*30.00 FL
38	1		*LAMP SIGNAL FRONT LH	Cut	35.00 F	*35.00 FL
39	1		*LAMP SIGNAL FRONT RH	Cracked	35.00 F	*35.00 FL
40	1		*LEG SHIELD ASSY	Distorted	34.00 F	*34.00 FL
41	1		*LEVER BRAKE LH	Cut	18.00 F	*18.00 FL
42	1		*LEVER BRAKE RH	Not Necessary	18.00 F	*- FL
43	1		*MIRROR LH	Cut	37.00 F	*37.00 FL
44	1		*MIRROR RH	Not Necessary	37.00 F	*- FL
45	1		*MUDGUARD FRONT (WHITE)	Broken	48.00 F	*48.00 FL
46	4		*NUT (WINDSCREEN)	Necessary	10.00 F	*10.00 FL
47	10		*NUT SPRING	Necessary	35.00 F	*35.00 FL
48	1		*PAD DISC BRAKE FRONT	Not Necessary	30.00 F	*- FL
49	1		*PANEL 1 (GRAY) LH	Cracked	22.00 F	*22.00 FL
50	1		*PANEL 2 (GRAY) RH	Cracked	22.00 F	*22.00 FL
51	1		*PANEL CONSOLE 1	Deformed	37.00 F	*37.00 FL
52	1		*PANEL METER	Cracked	16.00 F	*16.00 FL
53	1		*PIPE OVERFLOW	Not Necessary	17.00 F	*- FL
54	1		*PLATE DISC BRAKE FRONT	Bent	80.00 F	*80.00 FL
55	1		*RIM SPORT FRONT (SILVER)	Bent	250.00 F	*250.00 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
56	17		*RIVET	Necessary	51.00 F	*51.00 FL
57	1		*ROTOR SENSOR	Not Necessary	30.00 F	*- FL
58	4		*SCREW (VISOR)	Not Necessary	12.00 F	*- FL
59	2		*SEAL OIL FRONT RIM 20X35X7	Necessary	9.00 F	*9.00 FL
60	1		*STAND MAIN	Repair	65.00 F	*- FL
61	1		*STAND SIDE	Repair	23.00 F	*- FL
62	1		*STAY FRONT HEADLAMP	Bent	93.00 F	*93.00 FL
63	1		*STICKER(CERTIS CISCO) WINDSHIELD NEW MODEL	Necessary	58.00 FS	*58.00 FS
64	1		*STICKER (CISCO) COVER CENTRE LH	Necessary	40.00 FS	*40.00 FS
65	1		*STICKER (CISCO) COWLING FRONT LH	Necessary	40.00 FS	*40.00 FS
66	1		*STICKER (CISCO) COWLING FRONT RH	Necessary	40.00 FS	*40.00 FS
67	1		*STICKER (CISCO)MUDGUARD FRONT	Necessary	40.00 FS	*40.00 FS
68	1		*STICKER LABEL WARNING	Necessary	10.00 FS	*10.00 FS
69	1		*STICKER NUMBER PLATE FRONT (BLACK)	Missing	20.00 FS	*10.00 FS
70	1		*STOPPER MAINSTAND	Not Necessary	7.00 F	*- FL
71	1		*TANK FUEL COMP	Not Necessary	220.00 F	*- FL
72	1		*WINDSHIELD	Cracked	58.00 F	*58.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	4,026.00	3,395.50
- List Item Discount on L Items 0.00/10.00% (S\$)	0.00	315.75
Total Parts (S\$)	4,026.00	3,079.75

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REPAIR ON BODY ALIGNMENT FRONT	New	700.00	350.00
2	SPRAY LACQUER ON COVER CENTRE LH }	New	90.00	250.00
3	SPRAY LACQUER ON COWLING FRONT LH }	New	90.00	0.00
4	SPRAY LACQUER ON COWLING FRONT RH }	New	90.00	0.00
5	SPRAY LACQUER ON MUDGUARD FRONT }	New	45.00	0.00
6	TRANSPORT CHARGES	New	45.00	35.00
7	LABOUR	New	504.00	360.00
Gross Labour Cost (\$\$)			1,564.00	995.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >