

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/EG121012768/KTF3N2**Date:** 13/01/2022REFERENCE

Handling Insurer: ERGO Insurance Pte. Ltd.

Policy No:

Claimant Vehicle No : SHD5302E**Insured Vehicle No :** GBF281A

Date of Loss: 15/12/2021

Nature of Claim:

TP

Claim No: CDMCG21002432

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SHD5302E**

Make & Model: TOYOTA PRIUS, 1.8 5DR HATCHBACK (A)

Engine No: 2ZR2B74048

Reg. Date: 15/11/2018 (Man. Year: 2018)

Chassis No: JTDKB3FU203076719

Colour: Metallic Pearl White/Red

Odometer: 411910 km

Engine Capacity: 1798 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65R15

Rear Tyre Size:

195/65R15

Front Left Side: Sailun 9 mm

Rear Left Side:

Sailun 3 mm

Front Right Side: Sailun 9 mm

Rear Right Side:

Sailun 3 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,730.85	2,328.30	5,402.55	69.88
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,590.00	1,460.00	2,130.00	59.33
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	11,320.85	3,788.30	7,532.55	66.54
Approved Total (Overridden) (S\$)		3,050.00		
(S\$)	11,320.85	3,050.00	8,270.85	73.06
+ GST 7.00/7.00% (S\$)	792.46	213.50	578.96	73.06
Nett Amount (S\$)	12,113.31	3,263.50	8,849.81	73.06

INSPECTION

Date of Assignment: 17/12/2021

Date Inspected: 20/12/2021

Inspected At:

Trans-Cab Services Pte Ltd (HQ)

2 Ang Mo Kio Street 63

Singapore 569111

Estimated Period of Repair: 4.0 days

Adjuster: KENNETH KONG**Manager:** DENISE TAY KWEE CHENG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 13 Jan 2022)

Parts: 144 TOYOTA PRIUS 1.8 5DR HATCHBACK (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SHD5302E)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*PANEL SUB-ASSY,FRONT DOOR,LH	Bent	1,300.70 FL	*1,300.70 FL
2	1		*FRAME SUB-ASSY,FRONT DOOR OUTSIDE HANDLE,LH	Dented/Cut	193.50 FL	*193.50 FL
3	1		*COVER,FRONT DOOR OUTSIDE HANDLE,LH	Serviceable	17.90 FL	*- FL
4	1		*WEATHERSTRIP,FRONT DOOR,LH	Serviceable	231.30 FL	*- FL
5	1		*HINGE ASSY,FRONT DOOR,LOWER LH	Repair	110.60 FL	*- FL
6	1		*HINGE ASSY,FRONT DOOR,UPPER LH	Repair	97.50 FL	*- FL
7	1		*TAPE,BLACK OUT,NO 1 FRT LH	Necessary	13.30 FL	*13.30 FL
8	1		*TAPE,BLACK OUT,NO 2 FRT LH	Necessary	43.50 FL	*43.50 FL
9	1		*TAPE,BLACK OUT,NO 3 FRT LH	Necessary	26.30 FL	*26.30 FL
10	1		*MOTOR ASSY,POWER WINDOW REGULATOR,FRT LH	Serviceable	926.00 FL	*- FL
11	1		*REGULATOR SUB-ASSY,FRONT DOOR WINDOW,LH	Serviceable	238.30 FL	*- FL
12	1		*MIRROR ASSY,OUTER REAR VIEW,LH	Repair	1,339.30 FL	*- FL
13	1		*PANEL SUB-ASSY,REAR DOOR,LH	Warped/Bent	1,294.90 FL	*1,294.90 FL
14	1		*FRAME SUB-ASSY,REAR DOOR OUTSIDE HANDLE,LH	Serviceable	193.50 FL	*- FL
15	1		*COVER,REAR DOOR OUTSIDE HANDLE,LH	Serviceable	17.90 FL	*- FL
16	1		*HINGE ASSY,REAR DOOR,LOWER LH	Repair	87.10 FL	*- FL
17	1		*HINGE ASSY,REAR DOOR,UPPER LH	Repair	98.90 FL	*- FL
18	1		*TAPE,BLACK OUT,NO 1 REAR LH	Necessary	21.90 FL	*21.90 FL
19	1		*TAPE,BLACK OUT,NO 2 REAR LH	Necessary	34.90 FL	*34.90 FL
20	1		*TAPE,BLACK OUT,NO 3 REAR LH	Necessary	15.40 FL	*15.40 FL
21	1		*MOTOR ASSY,POWER WINDOW REGULATOR,REAR LH	Serviceable	926.00 FL	*- FL
22	1		*REGULATOR SUB-ASSY,REAR DOOR WINDOW,LH	Serviceable	206.70 FL	*- FL
23	1		*MOULDING ASSY,BODY ROCKER PANEL LH	Serviceable	594.80 FL	*- FL
24	1		*COVER,REAR BUMPER	Repair	442.60 FL	*- FL
25	1		*FILLER,REAR BUMPER EXTENSION,LH	Serviceable	123.70 FL	*- FL
26	1		*PANEL SUB-ASSY,QUARTER,LH	Repair	871.50 FL	*- FL
27	1		*LINER,REAR WHEEL HOUSE,LH	Serviceable	139.80 FL	*- FL
28	1		*FENDER CLIP	Not Necessary	65.00 FS	*- FS
29	1		*FENDER LINER CLIP	Not Necessary	65.00 FS	*- FS
30	1		*SET DOOR WEATHERSTRIP CLIP	Not Necessary	65.00 FS	*- FS
31	1		*REAR BUMPER CLIP	Not Necessary	65.00 FS	*- FS
32	1		*FRT DOOR STICKER TRANSCAB	Necessary	100.00 FS	*60.00 FS
33	1		*REAR DOOR STICKER TEL NO	Necessary	100.00 FS	*60.00 FS
34	1		*SET CLIP,ROCKER PANEL MOULDING	Not Necessary	65.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	10,132.80	3,064.40
- List Item Discount on L Items 25.00/25.00% (\$\$)	2,401.95	736.10
Total Parts (\$\$)	7,730.85	2,328.30

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH, FITTINGS AND OTHER,TO ENABLE REPAIR	New	380.00	0.00
2	PANEL BEATING,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS,ADJUST AND REALIGN THE SAME	New	1,400.00	500.00
3	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	1,400.00	880.00
4	TO RUST-PROOFING AND APPLY UNDERCOAT OF THE AFFECTED AREAS	New	240.00	60.00
5	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	20.00
Gross Labour Cost (\$)			3,590.00	1,460.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >