

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT						
	AXA INSURANCE	PTE LTD		Ref:	CS3/ASM21012772/Evy3e2	
	8 SHENTON WAY SINGAPORE 0688	C	Date:	22/12/2021		
	ATTN: TEO KITTY		C	Code:	ASM	
1.		Policy Particulars :- (THIRD PARTY CLAIM)				
	Insured Veh.	SMC 9408D	Veh. Inspected		FBG 8179E	
	Policy No.	P2157992	Coverage (\$)		0.00	
	Claim No.	S1M03O1D	Excess (\$)		0.00	
	Assign From	TEO KITTY	Assign Date		17/12/2021	
2.	Vehicle Particulars & Condition					
	Make & Model	YAMAHA JUPITER	c.c		134	
	Engine No.	HIDDEN	Year of Reg.		2012	
	Chassis No.	MH350C002CK433244	Colour		RED	
	Odometer	29223 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	FAIR				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	80/90-17	BRIDGESTONE		4 mm	
	L/H Front Tyre				mm	
	R/H Rear Tyre	90/80-17	BRIDGESTONE		4 mm	
	L/H Rear Tyre				mm	
4.	Description of Damages					
	THE VEHICLE SUPPORTION.	ICLE SUSTAINED DAMAGES AT THE O/S BODY AND FRONT I.				
5.	General Information					
	Accident Date	10/12/2021	Inspect Date / Ti	me	17/12/2021 (11:31 AM)	
	Survey held at	RWAVE PTE LTD	•			
	50 BUKIT BATOK STREET 23 #02-25 MIDVIEW BUILDING SINGAPORE 659578					
5a.	Remarks					
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$1,000-\$2,000					
5b. Estimate Days of Repair						
	ESTIMATED NORI	ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days				

Report Ref No. CS3/ASM21012772/Evy3e2

Inspected By

CHEN TSUE YEE

K.K.LAU CPT(RET)

Automotive Assessor

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$

REGD Auto Consultant-SAE, Licensed Appraiser