

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

|                        |   |   | Affiliated to Federation Internationale Des Experts En Automobile |                       |  |  |  |
|------------------------|---|---|---|-----------------------|--|--|--|
|                        | SOMPO INSURAN   | CE SINGAPORE PL   | Ref:  | CS/SMO21012775/Atf3n2 |  |  |  |
|                        | 50 RAFFLES PLAC<br>SINGAPORE LAND   | CE #03-03<br>O TOWERSINGAPORE 048623                                | Date:   | 18/04/2022            |  |  |  |
|                        |   |   | Code:   | SMO                   |  |  |  |
| 1.                     | Policy Particulars :- THIRD PARTY CLAIM   |   |   |                       |  |  |  |
|                        | Insured Veh.  | SKG 5932K   | Veh. Inspected  | GZ 5311A              |  |  |  |
|                        | Policy No.  |   | Coverage (\$)   | 0.00                  |  |  |  |
|                        | Claim No.   | CMTD2103727/LOR   | Excess (\$)   | 0.00                  |  |  |  |
| 4                      | Assign From   | GRACE TEO   | Assign Date   | 17/12/2021            |  |  |  |
| 2.                     | 2. Vehicle Particulars & Condition  |   |   |                       |  |  |  |
|                        | Make & Model  | TOYOTA HIACE  | c.c   | 2982                  |  |  |  |
| I                      | Engine No.  | HIDDEN  | Year of Reg.  | 2019                  |  |  |  |
|                        | Chassis No.   | JTFHT02P500247011   | Colour  | SILVER                |  |  |  |
|                        | Odometer  | 95210 KM  | Steering  | IN ORDER              |  |  |  |
| I                      | Brakes  | IN ORDER  | Modification  | NIL                   |  |  |  |
|                        | General   | GOOD  |   |                       |  |  |  |
| 3. Conditions of Tyres |   |   |   |                       |  |  |  |
|                        |   | Size  | Make  | Balance               |  |  |  |
|                        | R/H Front Tyre  | 195 R15C  | BRIDGESTONE   | 6 mm                  |  |  |  |
|                        | L/H Front Tyre  | 195 R15C  | BRIDGESTONE   | 6 mm                  |  |  |  |
|                        | R/H Rear Tyre   | 195 R15C  | BRIDGESTONE   | 6 mm                  |  |  |  |
|                        | L/H Rear Tyre   | 195 R15C  | BRIDGESTONE   | 6 mm                  |  |  |  |
| 4.                     | Description of Damages  |   |   |                       |  |  |  |
| -                      | THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.  |   |   |                       |  |  |  |
|                        | DAMAGES SEE DETAILS.  |   |   |                       |  |  |  |
| 5.                     | General Information   |   |   |                       |  |  |  |
| 1                      | Accident Date   | 16/12/2021  | Inspection Date   | 17/12/2021            |  |  |  |
| !                      | Survey held at  | ZERO GRAVITY  |   |                       |  |  |  |
|                        |   | 2 KAKI BUKIT AVE 2<br>#01-25 KAKI BUKIT AUTOHUB<br>SINGAPORE 417921 |   |                       |  |  |  |
| 5a.                    | n. Remarks  |   |   |                       |  |  |  |
|                        | A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |   |   |                       |  |  |  |
|                        | Estimate Days of Repair   |   |   |                       |  |  |  |
| 5b.                    |   | Estimate  | Days of Repair  |                       |  |  |  |