

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC4/AIG21012777/KGA3Q2**Date:** 18/04/2022REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:  
**Claimant Vehicle No :** SLU1680C **Insured Vehicle No :** SJR2355A  
 Date of Loss: 15/12/2021 Nature of Claim: TP Claim No: 9865366208SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLU1680C**  
 Make & Model: MITSUBISHI ATTRAGE, 1.2 CVT (A) Engine No: 3A92UGM1796  
 Reg. Date: 14/11/2017 (Man. Year: 2017) Chassis No: MMBSTA13AJH000639  
 Colour: Metallic Pearl White Odometer: 76701 km  
 Engine Capacity: 1193 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/55 R15 Rear Tyre Size: 185/55 R15  
 Front Left Side: Yokohama 7 mm Rear Left Side: Yokohama 7 mm  
 Front Right Side: Yokohama 7 mm Rear Right Side: Yokohama 7 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	7,701.50	2,832.97	4,868.53	63.22
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,070.00	1,780.00	2,290.00	56.27
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>11,771.50</b>	<b>4,612.97</b>	<b>7,158.53</b>	<b>60.81</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>3,650.00</b>		
<b>Nett Amount (S\$)</b>	<b>11,771.50</b>	<b>3,650.00</b>	<b>8,121.50</b>	<b>68.99</b>
<b>+ Car Rental (7.0 x S\$100.00/day) (S\$)</b>		700.00		
<b>Nett Liability (S\$)</b>		<b>4,350.00</b>		

INSPECTION

Date of Assignment: 17/12/2021  
 Date Inspected: 17/12/2021 Inspected At: Ja Autocare Pte Ltd  
 8 KAKI BUKIT AVE 4, #02-37 PREMIER@KAKI BUKIT  
 Singapore 415875  
 Estimated Period of Repair: 6.0 days

**Adjuster:** KENNETH KONG**Manager:** Chong Pui Lin

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

# REPAIR DETAILS

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOT LID	Bent	850.00 FL	*791.00 FL
2	1		*BOOT LID LOCK ASSY	Repair	450.00 FL	*- FL
3	1		*BOOT LID RUBBER (50%)	Dented / Distorted	198.00 FS	*110.00 FS
4	1		*BOOT LID INNER TRIM BOARD	No such part	350.00 FL	*- FL
5	1		*BOOT LID SPOILER	Necessary	280.00 FL	*280.00 FL
6	1		*BOOT LID CENTRE GARNISH (BLACK)	Serviceable	150.00 FL	*- FL
7	1		*MIT EMBLEM	Necessary	75.00 FL	*45.00 FL
8	2		*BOOT LID HINGES	Repair	260.00 FL	*- FL
9	1		*BOOT LID CENTRE GARNISH	Serviceable	180.00 FL	*- FL
10	1		*REAR PANEL	Bent	950.00 FL	*425.00 FL
11	1		*REAR BUMPER	Bent	750.00 FL	*708.00 FL
12	1		*REAR BUMPER REINFORCEMENT	No such part	450.00 FL	*- FL
13	1		*REAR BUMPER BRACKET	O/S Bent	180.00 FL	*34.50 FL
14	1		*REAR BUMPER RETAINER	O/S Cracked	240.00 FL	*59.80 FL
15	1		*REAR BUMPER LOWER REFLECTOR	O/S Scratched	180.00 FL	*38.00 FL
16	1		*REAR BUMPER CLIPS	Necessary	60.00 FL	*60.00 FL
17	1		*REAR EXHAUST	Repair	850.00 FL	*- FL
18	1		*REAR EXHAUST CHROME PIPE	Serviceable	250.00 FL	*- FL
19	1		*TAILLAMP ASSY	O/S Cracked	1,300.00 FL	*332.00 FL
20	1		*TAIL LAMP CLIPS	Necessary	60.00 FL	*30.00 FL
21	1		*REVERSE SENSOR	Shorted	350.00 FS	*200.00 FS
22	1		*REAR NUMBER PLATE WITH CASING	Serviceable	75.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (S\$)</b>	<b>8,488.00</b>	<b>3,113.30</b>
<b>- List Item Discount on L Items 10.00/10.00% (S\$)</b>	786.50	280.33
<b>Total Parts (S\$)</b>	<b>7,701.50</b>	<b>2,832.97</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO CHECKING WIRING	New	120.00	20.00
2	TO APPLY ANTI RUST CHEMICAL	New	100.00	60.00
3	TO DISMANTLE AND REFIX EXHAUST	New	250.00	0.00
4	TO KNOCK OUT DENTS ON AFFECTED AREASAND RENEW PARTS	New	1,800.00	800.00
5	TO PUTTY & RESPRAY PAINTING	New	1,800.00	900.00
			<b>Gross Labour Cost (\$)</b>	<b>1,780.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >