ASS. REC. BY: Taudim REF: CS/SMR7	10/2781/71953
	CIATA CERTON
From: Date:	1 . 27-
Estimated Cost:	Veh No: SJN 32260. Yr Regn: 2009, Feb.
OD (TP / WS / TP RES / OD RES / EVA / INV / MV	Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxl / Prime Mover / Truck / Trailer or
To Inspect Vehicle No:	
at Workshop m/s	Máke: flonta Armave. c.c 1496
of	Colour White A/C: Insured/Std/NI/NA
Insured:	Sp.Reading 128099 T/Radio: Insured / Std / NI / NA
Deliau Na	Eng/No:
Claims No.	C/No: 6 J 1/304850 =  Gen. Cond: Good/Fair/Poor/Burnt
Sum Insured: Excess:	Steering: Inorder / Jammed / Leaked / Burnt or
(Client's Record)	Brake: Inorden/Jammed/Leaked/Burnt or
Make of Veh;	Modi: Nil /S/Rim / STD A/Rim or
	Tyre Size: F: (95/55/7/5
(Policy Condition)	ryle Size: F: Cr)/5///
Remark: The veh had commenced Its N/S O/S	BS / DUN / EXNOVA / GY / FS / LIZA (MIC / OHTSU / PIR / SUM! /
repair at the time of inspection.	TOYO / YOKO or
Bal. or Market Value: . ALTK.	Front . Rear
IDAC Accident Rport: Consistent? : Yes or No	R/Bal, R/Bal. 6 mm
GIA / PR Seen: Consistent? : Yes or No	L/Bal. L mm UBal mm
Est. Repairs: days Res.: Yes or No	D.O.A. D.O.I. 20/12/21
Lum Sum: % 3 Val.: Yes or No	Survey held at Car Pro Anto.
CA / REV / REP. / 24 HRS	Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
. Vehicle: IN / OU	The U/C / Chassis frame / Body Structure affected due to collision.
	The U/C/I Chassis frame I Body Structure affected due to comport.
Date / Time   Action / Instruction	
Date/Time, File Pass to? Preli Report	David Of Family
1. 10/11/10/01	Days Of Repair:  Resurvey No. of Trip: Survey Fee:
Date/Time, File Return to?	Resurvey No. of Trip: Survey Fee: Transportation:
2) Add F	Canada
	:Interview (\$ ) Photos
Represent:	: Tech. Invs (\$ ) Others
Lump Sum / L.C. t. Ci )	: Weel and OF
	TOTAL
•	

## Adjustment of Spare Parts Costs for Repairs SJN 3226D HONDA AIRWAVE

Iten	ı Qty	Vehicle parts description	Estimate by
		****	workshop
		List Items	
1	1	rear bumper	\$680.00 de
2	2	rear bumper side retainer	\$55.00 7
3	2	rear bumper bracket	\$44.00
4	1 set	rear bumper clips	\$35.00 your
5	2	tail lamp LH & RH	\$720.00?
6	2 sets	tail lamp clips	\$42.00 ?
7	1	tail gate	\$1,030.00 bt
8	1	tail gate inner lock	\$165.00
9	1	tail gate lock striker	\$35.00
10	1	tail gate wiper arm	\$60.00
11	1	tail gate wiper blade	\$55.00 and
12	1	tail gate wiper motor	\$288.00
13	1	tail gate weatherstrip	\$185.00?
14	1	tail gate honda logo	\$80.00 1
15	1	tail gate airwave logo	\$85.00 nd
16	2	tail gate shock absorber LH & RH	\$300.00 🖔
17	1	tail gate stopper	\$10.20 000
18	1	tail gate inner trim board	\$220.00 7
19	1	tail gate lower pull handle	\$55.00⋉
20	1	tailgate center chrome garnish	\$185.00
20	1	tail gate centre garnish	\$125.00 de
21	2	tail gate lamp LH & RH	\$580.00 ?
22	2	tail gate car plate lamp LH & RH	\$110.00 ×
23	1	rear end panel	\$355.00
24	1	rear end panel top garnish	\$155.00 He
25	1	rear end panel top garnish clips	\$20.00 24
26	1	rear spare tyre panel	\$680.00 ×
27	1	rear spare tyre panel board	\$400.00
28	2	rear windscreen glass moulding	\$105.00
29	2	rear wind screen inner seal	\$55.00 2
30	1	rear windscreen	\$980.00%
31	1	rear exhaust muffler	\$680.00 ×
32	1	rear fender inner trim LH & RH	\$600.00 × LH ay / RMX
33	2 set	rear fender inner trim clips LH & RH	\$48.00 × 20 m
			, -

\$9,222.20

		Less 20%	\$1,844.44 \$7,377.76
		Special nett item	
1	1	windscreen sealant	\$60.00 ~~ \$60.00 ? 40
2	1	rear end panel sealant	\$60.00 7.40
3	1	rear spare tyre panel sealant	\$60.00 ℃
4	1	reverse camera	\$250.00 ?
5	4	reverse sensor	\$200.00 ~~~
6	2	number plate w casing	\$50.00 4 5
		Total parts	\$680.00
		stment of Labour Costs for Repairs ring of affected areas	\$800.00 700
Carry out body cavity preservation		out body cavity preservation	\$100.00 30
		move and replaced damaged parts including straige positioning replacement parts & panel beat	ghtening \$1,000.00 700

Check wiring Remove & reinstall rear windscreen Remove & refix bootlid componets Remove & reinstall reverse sensor Remove & reinstall rear boot upholstery

> Total labour \$2,330.00

> > Tanfilm 97415+45
> >
> > 'WP' 2012/718 1400
> >
> > 2/5 Resum affr upoly
> >
> > tanfilm Chhanto.com
> >
> > 6 dogs

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

\$50.00 30

\$120.00 12 -

\$80.00 60

\$80.00 30

\$100.00 60