

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBF 569X

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	SLIDING DOOR N/S (CONSISTENT)	DENTED / BENT	1,655.10	1,545.10
1	SLIDING DOOR INNER LOCK N/S (CONSISTENT)	NOT NECESSARY	425.80	-
1	REAR FENDER N/S (CONSISTENT)	TO REPAIR SEE LABOUR	1,971.10	-
1	REAR FENDER RAILING N/S (CONSISTENT)	NOT NECESSARY	366.50	-
1	REAR WHEEL HUB CAP N/S (CONSISTENT)	WARPED	198.00	160.00
1	REAR WHEEL HUB BEARING N/S (CONSISTENT)	DAMAGED	650.00	545.10
1	REAR WHEEL HUB SHAFT N/S (CONSISTENT)	DAMAGED	725.10	725.10
1	REAR BUMPER (CONSISTENT)	CUT	685.20	631.10
1	REAR BUMPER SIDE RETAINER N/S (CONSISTENT)	NECESSARY	105.00	105.00
1	SET REAR BUMPER CLIPS (CONSISTENT)	NECESSARY	50.00	50.00
1	TAILLAMP N/S (CONSISTENT)	NOT NECESSARY	398.20	-
	LESS 50% DISCOUNT		-	-1,880.70
			7,230.00	1,880.70
	<u>LABOUR</u>			
	TO TRANSFER SLIDING DOOR N/S .		80.00	50.00
	TO SPRAY RUST PROOFING.		80.00	50.00
	TO CONDUCT WHEEL ALIGNMENT.		120.00	80.00
	TO DISMANTLE & REPLACED REAR WHEEL HUB BEATING.		180.00	150.00
	LABOUR FOR PANEL BEATING & REPLACED PARTS.INCLUSIVE OF THE REPAIR OF REAR FENDER N/S .		980.00	600.00
	TO PUTTY & SPRAY PAINTING.		900.00	500.00
			2,340.00	1,430.00
	GRAND TOTAL		9,570.00	3,310.70

RECOMMENDED COST OF LUMP SUM REPAIRS		3,300.00
(TO ITS PRE-ACCIDENT CONDITION)		

Report Ref No. CC4/ASM21012782/Upa3q2





Report Ref No. CC4/ASM21012782/Upa3q2

CHUA KANG SENG

Licensed Appraiser