



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. AJ 890H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT FENDER (CONSISTENT)	TO REPAIR SEE LABOUR	65.00	-
1	TOP COWLING (CUT) (CONSISTENT)	NOT CONSISTENT WITH THE IMPACT / OLD DAMAGED	158.00	-
2	TOP COWLING INNER COVER - BLACK (CONSISTENT)	NOT NECESSARY	110.00	-
1	WINDSHIELD (SCRATCHED) (CONSISTENT)	NOT CONSISTENT WITH THE IMPACT	55.00	-
1	HEADLAMP (CUT) (CONSISTENT)	NOT CONSISTENT WITH THE IMPACT	105.00	-
1	LAMPSTAY (CONSISTENT)	NOT NECESSARY	180.00	-
2	FORK INNER TUBER (CONSISTENT)	SERVICEABLE	270.00	-
2	FORK OUTER TUBES (CONSISTENT)	NOT NECESSARY	290.00	-
1	FORK UNDER BRACKET (CONSISTENT)	NOT NECESSARY	145.00	-
1	FRONT BRAKE DISC (CONSISTENT)	NOT NECESSARY	155.00	-
1	FRONT RIM SHAFT (CONSISTENT)	NOT NECESSARY	45.00	-
1	FRONT RIM BEARING (CONSISTENT)	NOT NECESSARY	52.00	-
1	FRONT SPORT RIM (CONSISTENT)	NOT NECESSARY	320.00	-
2	FRONT SIGNALS (CONSISTENT)	N/S CRACKED	116.00	52.00
1	HANDLE-BAR (CONSISTENT)	BENT	95.00	95.00
1	SET HANDLE-BAR END (CONSISTENT)	MISSING	86.00	45.00
1	HAND GRIP (CONSISTENT)	NOT NECESSARY	68.00	-
1	CLUTCH LEVER (CONSISTENT)	CRACKED	50.00	50.00
2	SIDE MIRRORS (CONSISTENT)	NOT NECESSARY	100.00	-
1	SET FRONT FOOTREST (CONSISTENT) }	BENT	108.00	108.00
1	FRONT FOOTREST BRACKET (CONSISTENT) }		160.00	-
1	FRONT FOOTREST RUBBER (CONSISTENT)	NOT NECESSARY	56.00	-
1	GEAR PEDAL (CONSISTENT)	SERVICEABLE	48.00	-
1	SIDE BOARD (CONSISTENT)	NOT NECESSARY	45.00	-
1	SET REAR FOOTREST (CONSISTENT)	NOT NECESSARY	76.00	-
1	REAR FOOTREST BRACKET (CONSISTENT)	NOT NECESSARY	160.00	-
1	REAR TAILBOARD (CONSISTENT)	NOT NECESSARY	198.00	-
1	SET REAR SIGNAL (CONSISTENT)	NOT NECESSARY	150.00	-

Report Ref No. CS/ASM21012784/Uvy3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LESS 10% DISCOUNT		-346.60	-35.00
			3,119.40	315.00
	<u>SPECIAL NETT ITEMS</u>			
1	SET NUMBER PLATE (SN) (CONSISTENT)	NOT NECESSARY	38.00	-
2	FORK OILS (SN) (CONSISTENT)	NECESSARY	30.00	30.00
2	FORK OIL SEALS (SN) (CONSISTENT)	NECESSARY	56.00	56.00
1	SET STEERING CONE BEARING (SN) (CONSISTENT)	NOT NECESSARY	98.00	-
1	REAR BOX (SN) (CONSISTENT)	SERVICEABLE	380.00	-
1	REAR BOX BRACKET (SN) (CONSISTENT)	NOT NECESSARY	180.00	-
			782.00	86.00
	<u>LABOUR</u>			
	TO CHECK WIRING AND RESET HEADLAMP FOCUSING.	NOT NECESSARY	80.00	-
	TO REPAIR BODY FRAME.	NOT NECESSARY	480.00	-
	TO PROVIDE LABOUR. INCLUSIVE OF THE REPAIR OF FRONT FENDER.		380.00	250.00
			940.00	250.00
GRAND TOTAL			4,841.40	651.00
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				500.00

Report Ref No. CS/ASM21012784/Uvy3e2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.