



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKD 6906X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BUMPER	DEFORMED	811.20	811.20
1	FRONT BUMPER SIDE HOLDER LH	DAMAGED	99.10	99.10
1	FRONT BUMPER SIDE GARNISH LH	NOT NECESSARY	75.40	-
1	FRONT BUMPER LOWER GARNISH	NOT NECESSARY	340.20	-
1	FRONT BUMPER REINFORCEMENT	NOT NECESSARY	521.70	-
1	FRONT BUMPER SPONGE	NOT NECESSARY	172.40	-
1	HEADLAMP LH	CRACKED	3,303.10	3,303.10
1	HEADLAMP LOWER BRACKET	NOT NECESSARY	127.40	-
1	HEADLAMP LOWER SPONGE	CRACKED	112.20	112.20
1	FRONT LH WHEEL RIM	NOT NECESSARY	1,569.00	-
	LESS 25% DISCOUNT		-	-1,081.40
			7,131.70	3,244.20
	<u>SPECIAL NETT ITEMS</u>			
1	FRONT BUMPER CLIPS (SN)	NECESSARY	30.00	30.00
			30.00	30.00
	<u>LABOUR</u>			
	PANEL BEATING.		600.00	300.00
	SPRAY PAINTING.		600.00	400.00
	WIRING.		50.00	30.00
	TO PERFORM WHEEL ALIGNMENT.	NOT NECESSARY	150.00	-
			1,400.00	730.00
	GRAND TOTAL		8,561.70	4,004.20
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			3,200.00

Report Ref No. CS/AGI21012786/Aqf3n2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.