

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21012793/KPA3Q2**Date:** 12/01/2023REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070132421
Claimant Vehicle No :	SKU715E	Insured Vehicle No :	GBH7835X
Date of Loss:	16/12/2021	Nature of Claim:	TP
		Claim No:	0424110770SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKU715E		
Make & Model:	MAZDA CX-5, 2.0 SKYACTIV-G SP.6EAT 2WD LED (A)	Engine No:	PE30771486
Reg. Date:	29/06/2015 (Man. Year: 2015)	Chassis No:	JM6KE1072G0318833
Colour:	Metallic Black	Odometer:	96723 km
Engine Capacity:	1998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/65 R17	Rear Tyre Size:	225/65 R17
Front Left Side:	Continental 9 mm	Rear Left Side:	Continental 9 mm
Front Right Side:	Continental 9 mm	Rear Right Side:	Continental 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,130.80	4,692.52	3,438.28	42.29
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,895.00	1,270.00	625.00	32.98
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	10,025.80	5,962.52	4,063.28	40.53
Approved Total (Overridden) (\$\$)		4,750.00		
(\$\$)	10,025.80	4,750.00	5,275.80	52.62
+ GST 7.00/7.00% (\$\$)	701.81	332.50	369.31	52.62
Nett Amount (\$\$)	10,727.61	5,082.50	5,645.11	52.62
+ Car Rental (6.0 x S\$100.00/day) (\$\$)		600.00		
+ Doc/Search Fee (\$\$)		2.00		
Nett Liability (\$\$)		5,684.50		

INSPECTION

Date of Assignment:	17/12/2021	
Date Inspected:	20/12/2021	Inspected At: S & H Motor Pte Ltd (Sin Ming) 160 Sin Ming Drive #07-02, Sin Ming AutoCity Singapore 575722
Estimated Period of Repair:	4.0 days	

Adjuster: KENNETH KONG**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Bent	1,387.50 F	*1,387.50 FL
2	1		*TAILGATE EMBLEM	Necessary	54.30 F	*54.30 FL
3	1		*TAILGATE BADGE CX-5	Necessary	47.60 F	*47.60 FL
4	1		*TAILGATE BADGE SKYACTIV TECHNOLOGY	Necessary	75.20 F	*75.20 FL
5	1		*TAILGATE WIPER ARM	Broken	163.00 F	*163.00 FL
6	1		*TAILGATE WIPER MOTOR	Serviceable	320.10 F	*- FL
7	1		*TAILGATE INNER MOULDING	Warped	396.90 F	*382.00 FL
8	1		*TAILGATE INNER LOCK	Dented	269.30 F	*250.80 FL
9	1		*TAILGATE WEATHERSTRIP	Serviceable	183.30 F	*- FL
10	1		*TAILGATE INNER TRIM BOARD	Serviceable	280.50 F	*- FL
11	1		*LH TAILGATE INNER TAIL LAMP	Serviceable	490.00 F	*- FL
12	1		*REAR BUMPER	Buckled	1,278.90 F	*1,218.00 FL
13	1		*REAR BUMPER REINFORCEMENT	Bent	614.00 F	*543.00 FL
14	1		*RH REAR BUMPER PARKING SENSOR INNER	Shorted	189.00 F	*189.00 FL
15	1		*LH REAR BUMPER PARKING SENSOR INNER	Shorted	189.00 F	*189.00 FL
16	1		*REAR BUMPER LOWER MOULDING (NPA)	No such part	0.00 F	*- FL
17	1		*REAR WINDSCREEN	Cracked	1,075.00 F	*1,075.00 FL
18	1		*REAR WINDSCREEN MOULDING (NPA)	Not Necessary	0.00 F	*- FL
19	1		*REAR END PANEL	Repair	586.00 F	*- FL
20	1		*REAR END PANEL TOP GARNISH	Serviceable	98.20 F	*- FL
21	1		*REAR WINDSCREEN SEALANT	Necessary	80.00 FS	*40.00 FS
22	1		*REAR WINDSCREEN INNER RUBBER SEAL	Necessary	28.00 FS	*28.00 FS
23	1		*REAR NUMBER PLATE	Bent	45.00 FS	*45.00 FS
24	1		*REAR WINDSCREEN SOLAR FILM	Necessary	280.00 FS	*120.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	8,130.80	5,807.40
- List Item Discount on L Items 0.00/20.00% (S\$)	0.00	1,114.88
Total Parts (S\$)	8,130.80	4,692.52

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND REINSTALL REAR WINDSCREEN AND CONDUCT WATER LEAK TEST	New	120.00	120.00
2	TO REMOVE REAR DAMAGED PARTS ,TO JACK OUT REAR END PANEL AND REAR FLOOR PANEL AND CUT OUT BODY PANEL,TO RESHAPE AND REPAIR REAR END PANEL ,REAR FLOOR PANEL ,REAR BODY PANEL ,TO STRAIGHTEN OUT REAR CHASSIS MEMBER ,TO REPLACE TAILGATE AND ADJUST REAR BODY AND TAILGATE ALIGNMENT	New	750.00	500.00
3	TO SPRAY PAINT AFFECTED REAR AND INNER DAMAGED PORTION INCLUSIVE OF PREPARATORY WORKS AND MATERIAL	New	750.00	600.00
4	TO APPLY ANTI-CORROSION TUFF-KOTE	New	100.00	30.00
5	TO DISCONNECT WIRE HARNESS TO FACILITATE REPAIRS AND CHECK FOR DAMAGE AND RECONNECT WIRING SYSTEM AND CHECK FOR FULL FUNCTIONALITY	New	25.00	20.00
6	TO PERFORM COMPUTER DIAGNOSTIC ON DRIVETRAIN ABS SYSTEMS PARKING SYSTEM HEADLAMP SYSTEMS AND CLEAR FAULT CODES	New	150.00	0.00
Gross Labour Cost (\$\$)			1,895.00	1,270.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >