

ASS. REC. F

From:

Not Notch  
11 Bay @ 4750/-  
Prep. After Paint  
4 day



Ng Yong Li France  
25 Seraya Lane Seraya Ville  
Singapore 437292

File No : SH/2021/108/12/011/TP  
Date : 17-December-2021

Estimated cost of repair for vehicle no : SKU715E Mazda CX-5  
Accident involving vehicle no: SKU715E & GBH7835X on 16.12.2021

| Description                          | Quantity | Cost Price |
|--------------------------------------|----------|------------|
| Tailgate                             | 1        | 1387.50    |
| Tailgate emblem                      | 1        | 54.30      |
| Tailgate badge "CX-5"                | 1        | 47.60      |
| Tailgate badge "Skyactiv Technology" | 1        | 75.20      |
| Tailgate wiper arm                   | 1        | 163.00     |
| Tailgate wiper motor                 | 1        | 320.10     |
| Tailgate centre moulding             | 1        | 396.80     |
| Tailgate inner lock                  | 1        | 269.30     |
| Tailgate weatherstrip                | 1        | 183.30     |
| Tailgate inner trim board            | 1        | 280.50     |
| LH Tailgate inner tail lamp          | 1        | 490.00     |
| Rear bumper                          | 1        | 1278.90    |
| Rear bumper reinforcement            | 1        | 614.00     |
| RH Rear bumper parking sensors inner | 1        | 189.00     |
| LH Rear bumper parking sensors inner | 1        | 189.00     |
| Rear bumper lower moulding           | 1        | 1075.00    |
| Rear windscreen                      | 1        | 586.00     |
| Rear windscreen moulding             | 1        | 98.20      |
| Rear end panel                       | 1        |            |
| Rear end panel top garnish           | 1        |            |

|   |   |         |    |        |
|---|---|---------|----|--------|
| Rear windscreen sealant   | 1 | S. nett | \$ | 80.00  |
| Rear windscreen inner rubber seal   | 1 | S. nett | \$ | 28.00  |
| Rear number plate   | 1 | S. nett | \$ | 45.00  |
| Rear windscreen solar film  | 1 | S. nett | \$ | 280.00 |
| To remove and reinstall rear windscreen and conduct water leak test.  |   |         | \$ | 120.00 |
| To remove rear damaged parts, to jack out rear end panel and rear floor panel and cut out body panel, to reshape and repair rear end panel, rear floor panel, rear body panel, to straighten out rear chassis member, to replace tailgate and adjust rear body and tailgate alignment |   |         | \$ | 750.00 |
| To spray paint affected rear and inner damaged portion inclusive of preparatory works and material  |   |         | \$ | 750.00 |



To apply anti-corrosion Tuff-Kote

\$ 100.00 30/

To disconnect wire harness to facilitate repairs and check for damage and reconnect wiring system and check for full functionality

\$ 25.00 20/

To perform computer diagnostic on drivetrain, ABS systems, parking system, headlamp systems, and clear fault codes

\$ 150.00 X

\$ -

T/Party: AIG Asia Pacific Insurance Pte Ltd

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: