

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG21012794/UEA3Q2**Date:** 30/06/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	7210074260
Claimant Vehicle No :	SMF7261G	Insured Vehicle No :	SMU8161B
Date of Loss:	16/12/2021	Nature of Claim:	TP
		Claim No:	0480152224SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMF7261G	Engine No:	2ZR0C59292
Make & Model:	TOYOTA PRIUS PLUS, 1.8 (A)	Chassis No:	JTDZS3EU60J034338
Reg. Date:	22/11/2018 (Man. Year: 2018)	Odometer:	37167 km
Colour:	Blue		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	Yokohama 7 mm	Rear Left Side:	Yokohama 7 mm
Front Right Side:	Yokohama 7 mm	Rear Right Side:	Yokohama 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	896.20	0.00	896.20	100.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	850.00	540.00	310.00	36.47
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	1,746.20	540.00	1,206.20	69.08
+ GST 7.00/7.00% (S\$)	122.23	37.80	84.43	69.07
Nett Amount (S\$)	1,868.43	577.80	1,290.63	69.08
+ Car Rental (2.0 x S\$120.00/day) (S\$)		240.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		819.80		

INSPECTION

Date of Assignment:	02/03/2022	Hock Wah Motor Workshop Pte Ltd (Bedok)
Date Inspected:	02/03/2022 Inspected At:	Blk 3011, Bedok Industrial Park E., #01-2008/2010/2012
Estimated Period of Repair:	2.0 days	Singapore 489977

Adjuster: MARCUS CHUA**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Recommended Parts

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR TO REMOVE & REFIT NECESSARY PARTS	New	350.00	200.00
2	SPRAY PAINT ON THE AFFECTED AREAS	New	300.00	300.00
3	ANTI-RUST COATING	New	50.00	0.00
4	TO REMOVE & REFIT REVERSE SENSOR	New	150.00	40.00
Gross Labour Cost (\$\$)			850.00	540.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >