

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG21012798/KEA3Q2**Date:** 13/04/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800008157
Claimant Vehicle No :	SMW8522H	Insured Vehicle No :	SLA8808L
Date of Loss:	16/12/2021	Nature of Claim:	TP
		Claim No:	2501911767SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMW8522H	Engine No:	4J11AR7672
Make & Model:	MITSUBISHI OUTLANDER, 2.0 (A)	Chassis No:	GF7W0601251
Reg. Date:	16/05/2019 (Man. Year: 2019)	Odometer:	70654 km
Colour:	Metallic Grey		
Engine Capacity:	1998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/55 R18	Rear Tyre Size:	225/55 R18
Front Left Side:	Yokohama 9 mm	Rear Left Side:	Yokohama 9 mm
Front Right Side:	Yokohama 9 mm	Rear Right Side:	Yokohama 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,235.50	4,251.20	2,984.30	41.25
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,920.00	1,510.00	1,410.00	48.29
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,155.50	5,761.20	4,394.30	43.27
Approved Total (Overridden) (S\$)		4,350.00		
(S\$)	10,155.50	4,350.00	5,805.50	57.17
+ GST 7.00/7.00% (S\$)	710.89	304.50	406.39	57.17
Nett Amount (S\$)	10,866.39	4,654.50	6,211.89	57.17
+ Car Rental (7.0 x S\$130.00/day + 7.00% GST) (S\$)		973.70		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		5,630.20		
Global Sum Settlement (S\$)		5,630.00		

INSPECTION

Date of Assignment:	17/12/2021		
Date Inspected:	17/12/2021	Inspected At:	Optima Werkz Pte Ltd (HQ) 6 Kung Chong Road Singapore 159143
Estimated Period of Repair:	5.0 days		

Adjuster: KENNETH KONG**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Bent	1,350.00 FL	*989.00 FL
2	1		*TAILGATE INNER TRIM BOARD	Serviceable	350.00 FL	*- FL
3	1		*REAR TAILGATE OUTLANDER EMBLEM	Necessary	95.00 FL	*95.00 FL
4	1		*REAR TAILGATE MIVEC EMBLEM	Necessary	75.00 FL	*75.00 FL
5	1		*REAR TAILGATE LOCK	Repair	220.00 FL	*- FL
6	1		*REAR WEATHERSTRIP	Dented / Distorted	300.00 FL	*213.00 FL
7	1		*REAR WINDSCREEN MOULDING	Necessary	150.00 FL	*150.00 FL
8	1		*REAR BUMPER	Buckled / Cracked	1,160.00 FL	*811.00 FL
9	1		*REAR BUMPER SIDE BRACKET RH	Repair	100.00 FL	*- FL
10	1		*REAR BUMPER REFLECTOR RH	Serviceable	145.00 FL	*- FL
11	1		*REAR LOWER BUMPER	Dented / Cut	820.00 FL	*420.00 FL
12	1		*REAR DIFFUSER	Cracked	1,600.00 FL	*1,250.00 FL
13	1		*END PANEL	Bent	365.00 FL	*365.00 FL
14	1		*END PANEL TOP COVER	Serviceable	165.00 FL	*- FL
15	1		*TAILGATE INNER TRIM CLIPS	Not Necessary	120.00 FS	*- FS
16	1		*REAR WINDSCREEN SEALANT	Necessary	100.00 FS	*40.00 FS
17	1		*END PANEL JOINT SEALANT	Necessary	80.00 FS	*30.00 FS
18	1		*REVERSE SENSOR	Shorted	280.00 FS	*200.00 FS
19	1		*REVERSE CAMERA	Serviceable	200.00 FS	*- FS
20	1		*REAR BUMPER CLIPS	Necessary	100.00 FS	*50.00 FS
21	1		*REAR BUMPER CLIPS	Repeated	100.00 FS	*- FS
22	1		*END PANEL TOP COVER CLIPS	Not Necessary	50.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	7,925.00	4,688.00
- List Item Discount on L Items 10.00/10.00% (\$)	689.50	436.80
Total Parts (\$)	7,235.50	4,251.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR CHARGES TO REMOVE ,REPLACE ,REFIX & REPAIR REAR ACCIDENT AREA	New	1,200.00	600.00
2	LABOUR CHARGES TO SUPPLY PAINT & FURNISHING MATERIALS AT REAR ACCIDENT AREA	New	1,000.00	600.00
3	LABOUR CHARGES TO REMOVE & REFIX REAR WINDSCREEN GLASS	New	150.00	120.00
4	LABOUR CHARGES TO REMOVE & REINSTALLED REAR TAILGATE INNER MECHANISM	New	120.00	60.00
5	LABOUR CHARGES TO REMOVE & REPLACE REVERSE SENSOR	New	100.00	50.00
6	TO CONDUCT DIAGNOSTIC RESET FAULT CODE & MEMORY	New	150.00	0.00
7	TO CHECK WIRING & CENTRAL LOCKING SYSTEM	New	100.00	20.00
8	TO TUFF COAT AND UNDERSEAL MATERIAL	New	100.00	60.00
Gross Labour Cost (\$\$)			2,920.00	1,510.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >