

ASS. REQ. BY:

REF:

AG/ 21012798/ku

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

-3

days

Res.: Yes or No

Lum Sum:

1-B.1 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

BMW 852211

Yr Regn:

05, 19

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

M7

Outlander

c.c

1998

Colour

M. Grey

A/C:

Insured / Std / NI / NA

Sp. Reading

70634

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

GFWW - 0801251

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: NII / S/Rim / STD / RIM or

Tyre Size:

F:

225/55R18

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal.

9

mm

R/Bal.

9

mm

L/Bal.

9

mm

L/Bal.

9

mm

D.O.A.

16/12/21

D.O.A.

17/12/2021

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear O/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

1 GIA not ready

27/12/11 Day @ 43501 Carhu

Date/Time, File Pass to?



: Prell. Report

1)



: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Add Fee:



: Site Insp (\$



: Interview (\$



Tech Invs (\$



Weekend (\$

Survey Fee:

Transportation:

S + RS. SI

Fees:

Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$

Not Notch in
Rear B4 paint
1/18mp @ 4350/p
5 days

Date: 16.12.2021
Vehicle No: SMW8522H
Model: MITSUBISHI OUTLANDER 2.0 ELEGANCE
Chassis: GF7W-0601251
Reg.Year: 2019

Third Party Insurer: AIG
Third Party Veh No: SLA8808L
Date of Accident: 16.12.2021
Estimator: Victor
Surveyor: Kenneth

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	TAILGATE <i>989</i>	1	<i>Bu</i>	\$1,350.00
2	TAILGATE INNER TRIM BOARD	1		<i>Bu</i> \$350.00
3	REAR TAILGATE "OUTLANDER" EMBLEM	1		<i>na</i> \$95.00
4	REAR TAILGATE "MIVEC" EMBLEM	1		<i>na</i> \$75.00
5	REAR TAILGATE LOCK	1		<i>na</i> \$220.00
6	REAR WEATHERSTRIP <i>213</i>	1		<i>add 10.00</i> \$300.00
7	REAR WINDSCREEN MOULDING	1		<i>na</i> \$150.00
8	REAR BUMPER <i>811</i>	1	<i>Bu / cut</i>	\$1,160.00
9	REAR BUMPER SIDE BRACKET RH	1		<i>na</i> \$100.00
10	REAR BUMPER REFLECTOR RH	1		<i>na</i> \$145.00
11	REAR LOWER BUMPER <i>420</i>	1	<i>cut / cut</i>	\$820.00
12	REAR DIFFUSER <i>1050</i>	1	<i>cut</i>	\$1,600.00
13	END PANEL	1		<i>Bu</i> \$365.00
14	END PANEL TOP COVER	1		<i>na</i> \$165.00
SUB TOTAL				\$6,895.00
LESS 10%				-\$689.50
PARTS TOTAL				\$6,205.50

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
1	TAILGATE INNER TRIM CLIPS	1		<i>na</i> \$120.00
2	REAR WINDSCREEN SEALANT	1		<i>na</i> \$100.00
3	END PANEL JOINT SEALANT	1		<i>na</i> \$80.00
4	REVERSE SENSOR	1		<i>short</i> \$280.00
5	REVERSE CAMERA	1		<i>na</i> \$200.00
6	REAR BUMPER CLIPS	1		<i>na</i> \$100.00
7	REAR BUMPER CLIPS	1		<i>na</i> \$100.00
8	END PANEL TOP COVER CLIPS	1		<i>na</i> \$50.00
S/N TOTAL				\$1,030.00

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REFIX & REPAIR REAR ACCIDENT AREA.

\$1,200.00 *600*

LABOUR CHARGES TO SUPPLY PAINT & FURNISHING MATERIALS AT REAR ACCIDENT AREA.

\$1,000.00 *600*

Head office

6 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047
Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011



Date: 16.12.2021
Vehicle No: SMW8522H
Model: MITSUBISHI OUTLANDER 2.0 ELEGANCE
Chassis: GF7W-0601251
Reg.Year: 2019

Third Party Insurer: AIG
Third Party Veh No: SLA8808L
Date of Accident: 16.12.2021
Estimator: Victor
Surveyor: Kenneth

LABOUR CHARGES TO REMOVE & REFIX REAR WINDSCREEN GLASS.	\$150.00	120/
LABOUR CHARGES TO REMOVE & REINSTALLED REAR TAILGATE INNER MECHANISM.	\$120.00	60/
LABOUR CHARGES TO REMOVE & REPLACE REVERSE SENSOR.	\$100.00	50/
TO CONDUCT DIAGNOSTIC, RESET FAULT CODE & MEMORY.	\$150.00	7/
TO CHECK WIRING & CENTRAL LOCKING SYSTEM.	\$100.00	20/
TO TUFF COAT AND UNDERSEAL MATERIAL.	\$100.00	60/

LABOUR TOTAL \$2,920.00

TOTAL \$10,155.50

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Head office

6 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047
Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011

