

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC4/III21012799/AEA3Q2**Date:** 13/06/2022**REFERENCE**

Handling Insurer: India International Insurance Pte Ltd Policy No: D19MFL0005549\_02

**Claimant Vehicle No :** SLA3020A **Insured Vehicle No :** GBJ8817G

Date of Loss: 15/12/2021 Nature of Claim: TP Claim No: MFL2021D0005500

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No: **SLA3020A**  
 Make & Model: MAZDA 3, 1.5 SEDAN L SP.6EAT (A) Engine No: P520336377  
 Reg. Date: 26/02/2016 (Man. Year: 2015) Chassis No: JM6BM42A8G0327965  
 Colour: White Odometer: 126164 km  
 Engine Capacity: 1496 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (S\$): **Market Value/New Car Price**

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size: 205/60 R16 Rear Tyre Size: 205/60 R16  
 Front Left Side: Falken 6 mm Rear Left Side: Falken 6 mm  
 Front Right Side: Falken 6 mm Rear Right Side: Falken 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	2,105.92	867.84	1,238.08	58.79
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,700.00	1,040.00	660.00	38.82
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>3,805.92</b>	<b>1,907.84</b>	<b>1,898.08</b>	<b>49.87</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>1,500.00</b>		
<b>(S\$)</b>	3,805.92	1,500.00	2,305.92	60.59
<b>+ GST 7.00/7.00% (S\$)</b>	266.41	105.00	161.41	60.59
<b>Nett Amount (S\$)</b>	<b>4,072.33</b>	<b>1,605.00</b>	<b>2,467.33</b>	<b>60.59</b>
<b>+ Car Rental (3.0 x S\$100.00/day) (S\$)</b>		300.00		
<b>+ Doc/Search Fee (S\$)</b>		7.45		
<b>Nett Liability (S\$)</b>		<b>1,912.45</b>		
<b>Global Sum Settlement (S\$)</b>		<b>1,910.00</b>		

**INSPECTION**

Date of Assignment: 17/12/2021

Date Inspected: 17/12/2021 Inspected At:

Modern Automotive Pte Ltd (HQ)  
 Blk 3023A Ubi Road 1, #01-61 & #01-58  
 Singapore 408717

Estimated Period of Repair: 3.0 days

**Adjuster:** ADRIAN LING**Manager:** Asher Sng Rong Yi

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 24 May 2022)
<b>Parts:</b>	143	MAZDA 3 1.5 SEDAN L SP.6EAT (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SLA3020A)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Distorted	1,047.30 FL	*1,047.30 FL
2	1		*REAR BUMPER REFLECTOR -RH	Not Necessary	54.90 FL	*- FL
3	1		*REAR BUMPER REINFORCEMENT	Not Necessary	537.30 FL	*- FL
4	1		*REAR END PANEL	Repair	530.40 FL	*- FL
5	1		*REAR BUMPER CLIPS	Necessary	30.00 FS	*30.00 FS
6	1		*REVERSE SENSOR	Not Necessary	280.00 FS	*- FS
7	1		*REAR END PANEL SEALANT	Not Necessary	60.00 FS	*- FS
					<b>Sub Total (\$\$)</b>	<b>2,539.90</b>
					<b>- List Item Discount on L Items 20.00/20.00% (\$\$)</b>	<b>433.98</b>
					<b>Total Parts (\$\$)</b>	<b>2,105.92</b>
						<b>867.84</b>

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO KNOCKING & PULL OUT REAR PORTION & RENEW ABOVE PARTS	New	600.00	400.00
2	TO PUTTY & SPRAY UP PAINT WORKS	New	800.00	500.00
3	TO CHECK WIRING	New	50.00	30.00
4	TO REMOVE REVERSE SENSOR	New	100.00	50.00
5	TO SPRAY TUFF COAT	New	150.00	60.00
<b>Gross Labour Cost (\$\$)</b>			<b>1,700.00</b>	<b>1,040.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >