



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

LONPAC INSURANCE BHD

300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555

INV No. AC2202047

INV Date 08/04/2022

Reference CC4/LPC21012800/Rga3q2

Code LPC2

PROFESSIONAL SERVICE FEE

Vehicle No. XE 1328M
Insured Veh. YN 2104B
Claim No. 20/21/22/VC00/025262
Policy No. Z/20/VC00/109328
Accident Date 04/12/2021
Inspection Date 21/12/2021

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555			Ref: CC4/LPC21012800/Rga3q2 Date: 08/04/2022 Code: LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	YN 2104B	Veh. Inspected	XE 1328M	
Policy No.	Z/20/VC00/109328	Coverage (\$)	0.00	
Claim No.	20/21/22/VC00/025262	Excess (\$)	0.00	
Assign From	GERALD	Assign Date	17/12/2021	
2. Vehicle Particulars & Condition				
Make & Model	IVECO TRAKKER AUTO	c.c	12882	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	WJME2NSS40C283329	Colour	BLUE	
Odometer	473001 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	315/80 R22.5	KINBLI	8 mm	
L/H Front Tyre	315/80 R22.5	KINBLI	8 mm	
R/H Rear Tyre	315/80 R22.5 (D)	KINBLI	8/8 mm	
L/H Rear Tyre	315/80 R22.5 (D)	KINBLI	8/8 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	04/12/2021	Inspection Date	21/12/2021	
Survey held at	SIN SHENG AUTO WORKSHOP PTE LTD 5 TUAS AVENUE 3, SINGAPORE 639405			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			6 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. XE 1328M

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	BUMPER ,LH	BENT	1,178.08	1,178.08
1	BUMPER BRACKET	BENT	65.04	65.04
1	BUMPER CENTER	BENT	2,105.79	2,105.79
1	HEADLAMP LH	CRACKED	2,115.50	2,115.50
1	BUMPER SIGNAL LAMP	CRACKED	106.65	106.65
1	BUMPER SPORT LAMP	CRACKED	141.94	141.94
1	HEADLAMP COVER	MISSING	27.81	27.81
1	CORNER PANEL ,LH	CRACKED	2,220.05	2,220.05
1	UPPER FENDER	CRACKED	1,399.85	1,399.85
1	FENDER GARNISH	SCRATCHED	104.94	104.94
1	FENDER PROTECTOR	SCRATCHED	185.50	185.50
1	FENDER EXTENSION	NOT NECESSARY	397.46	-
1	FENDER LOWER	CRACKED	1,017.18	1,017.18
1	FENDER LOWER GARNISH	NOT NECESSARY	141.04	-
1	FENDER BRACKET	NOT NECESSARY	576.96	-
1	LOWER STEP	DEFORMED	604.45	604.45
1	LOWER STEP GARNISH	NOT NECESSARY	71.77	-
1	MIRROR ASSY ,LH	CRACKED	1,493.30	1,493.30
1	DOOR GLASS ,LH	TO REPAIR SEE LABOUR	495.50	-
1	TRAKKER 410 ES LOGO	NECESSARY	169.50	169.50
	LESS 10% DISCOUNT		-1,461.83	-1,293.56
			13,156.48	11,642.02
<u>SPECIAL NETT ITEMS</u>				
1	SEALANT (SN)	NOT NECESSARY	40.00	-
1	BLACK AND YELLOW STICKER (SN)	NECESSARY	30.00	30.00
			70.00	30.00

Report Ref No. CC4/LPC21012800/Rga3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>LABOUR</u>			
	TO REMOVE AND REPLACE DOOR GLASS TO PANEL BEAT/REPAIR LHS BODY TO DISMANTLE /REPLACE ABOVE -MENTIONED PARTS .INCLUSIVE OF THE REPAIR OF DOOR GLASS ,LH .		950.00	750.00
	TO SPRAY PAINTING ON AFFECTED AREAS .		1,000.00	700.00
			1,950.00	1,450.00
GRAND TOTAL			15,176.48	13,122.02
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				10,500.00

Report Ref No. CC4/LPC21012800/Rga3q2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. XE 1328M

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. XE 1328M

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

