

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CS/AIG21012802/EVF3E2

Date: 28/01/2022

REFERENCE

Insured/Claimant: ERWIN WANG JUNYONG Policy No: 7210109907
Date of Loss: 17/12/2021 Nature of Claim: OD Claim No: 0045954361SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMK4991B**
Make & Model: KIA STONIC, 998cc (A) Engine No: G3LCKP008081
Reg. Date: 12/04/2019 (Man. Year: 2018) Chassis No: KNAD6811VK6279473
Colour: White Odometer: 58580 km
Engine Capacity: 998 cc
Market Value/New Car Price: S\$75,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/50 R17 Rear Tyre Size: 215/50 R17
Front Left Side: Goodyear 5 mm Rear Left Side: Goodyear 5 mm
Front Right Side: Goodyear 5 mm Rear Right Side: Goodyear 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,199.60	1,997.20	2,202.40	52.44
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,900.00	1,530.00	1,370.00	47.24
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,099.60	3,527.20	3,572.40	50.32
- Excess (S\$)	300.00	300.00	0.00	0.00
(S\$)	6,799.60	3,227.20	3,572.40	52.54
+ GST 7.00/7.00% (S\$)	475.97	225.90	250.07	52.54
Nett Amount (S\$)	7,275.57	3,453.10	3,822.47	52.54

INSPECTION

Date of Assignment: 20/12/2021
Date Inspected: 20/12/2021 Inspected At: Cycle & Carriage KIA Pte Ltd (Pandan Gardens)
209 Pandan Gardens
Singapore 609339
Estimated Period of Repair: 4.0 days

Adjuster: CHEN TSUE YEE

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FR NUMBER PLATE WITH CASING	Cut	50.00 FS	*50.00 FS
2	1		*SUNDRIES	Necessary	20.00 FS	*20.00 FS
3	1		*LAMP ASSY-HEAD, RH	Not Necessary	1,845.00 FL	*- FL
4	1		*PANEL ASSY-HOOD	Dented	904.00 FL	*904.00 FL
5	1		*HINGE ASSY-HOOD, LH	Not Necessary	43.00 FL	*- FL
6	1		*HINGE ASSY-HOOD, RH	Not Necessary	43.00 FL	*- FL
7	1		*LATCH ASSY-HOOD	Not Necessary	101.00 FL	*- FL
8	13		*CLIP-HOOD INSULATING PAD MTG	Not Necessary	13.00 FL	*- FL
9	1		*COVER-FR BUMPER UPR	Broken	476.00 FL	*476.00 FL
10	1		*CAP-FRONT HOOK	Crushed	5.00 FL	*5.00 FL
11	1		*GRILLE-FRONT BUMPER	Broken	96.00 FL	*96.00 FL
12	1		*COVER-FR BUMPER, LWR	Broken	367.00 FL	*367.00 FL
13	1		*SKID PLATE-FR BUMPER	Not Necessary	55.00 FL	*- FL
14	1		*LIP ASSY-FRONT BUMPER	Not Necessary	32.00 FL	*- FL
15	1		*BRACKET-FR BUMPER SIDE, RH	Not Necessary	13.00 FL	*- FL
16	1		*MOULDING-FRONT BUMPER A/INTAKE	Broken	61.00 FL	*61.00 FL
17	1		*ABSORBER-FRONT BUMPER ENERGY	Broken	98.00 FL	*98.00 FL
18	1		*COVER-FR BUMPER FOG LAMP, RH	Not Necessary	64.00 FL	*- FL
19	1		*GRILLE ASSY-RADIATOR	Broken	324.00 FL	*324.00 FL
20	1		*BEAM COMPLETE-FR BUMPER	Not Necessary	544.00 FL	*- FL
21	1		*ORNAMENT-KIA NO.115	Necessary	32.00 FL	*32.00 FL
22	1		*COVER-RADIATOR GRILLE UPR	Broken	46.00 FL	*46.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	5,232.00	2,479.00
- List Item Discount on L Items 20.00/20.00% (S\$)	1,032.40	481.80
Total Parts (S\$)	4,199.60	1,997.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	RENEW BONNET & FR BUMPER. REPAIR RHF FENDER	New	1,600.00	600.00
2	RESPRAY BONNET, FR BUMPER & RHF FENDER	New	1,050.00	700.00
3	CHECK WIRING ELECTRICAL SYSTEM	New	30.00	30.00
4	TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM	New	120.00	120.00
5	APPLY ANTI CORROSION ON AFFECTED AREAS	New	40.00	40.00
6	SUPPLY BODY PNL SEALANT	New	60.00	40.00
Gross Labour Cost (\$)			2,900.00	1,530.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >