

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CS/AIG21012804/EQF3N2**Date:** 03/03/2022**REFERENCE**

Insured/Claimant: ANG SOON WAH Policy No:
Date of Loss: 17/12/2021 Nature of Claim: OD Claim No: 2294025503SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLM2236M**
Make & Model: MITSUBISHI ATTRAGE, 1.2 (A) Engine No: 3A92UDP8238
Reg. Date: 24/03/2017 (Man. Year: 2016) Chassis No: MMBSTA13AHH004183
Colour: Red Odometer: 57586 km
Engine Capacity: 1193 cc
Market Value/New Car Price: S\$43,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/55R15 Rear Tyre Size: 185/55R15
Front Left Side: Yokohama 4 mm Rear Left Side: Yokohama 4 mm
Front Right Side: Yokohama 4 mm Rear Right Side: Yokohama 4 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,800.91	3,489.64	1,311.27	27.31
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,410.00	3,305.00	1,105.00	25.06
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,210.91	6,794.64	2,416.27	26.23
- Excess (S\$)	600.00	600.00	0.00	0.00
(S\$)	8,610.91	6,194.64	2,416.27	28.06
+ GST 7.00/7.00% (S\$)	602.76	433.62	169.14	28.06
Nett Amount (S\$)	9,213.67	6,628.26	2,585.41	28.06

INSPECTION

Date of Assignment: 20/12/2021
Date Inspected: 20/12/2021 Inspected At: Cycle & Carriage Automotive Pte Ltd (Pandan Gardens)
209 Pandan Gardens
Singapore 609339
Estimated Period of Repair: 6.0 days

Adjuster: CHEN TSUE YEE**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FACE,FR BUMPER	Dented	706.00 FL	*706.00 FL
2	1		*COVER,FR BUMPER	Not Necessary	12.00 FL	*- FL
3	1		*COVER,HEADLAMP SUPT PANEL	Not Necessary	62.00 FL	*- FL
4	1		*GRILLE,FR UNDER	Not Necessary	165.00 FL	*- FL
5	1		*GARNISH,FR BUMPER,RH	Missing	127.00 FL	*127.00 FL
6	1		*BRACKET,FR BUMPER,LH	Not Necessary	13.00 FL	*- FL
7	1		*BRACKET,FR BUMPER,RH	Broken	13.00 FL	*13.00 FL
8	1		*MARK,THREE-DIA	Not Necessary	70.00 FL	*- FL
9	1		*GRILLE,RADIATOR	Not Necessary	557.00 FL	*- FL
10	1		*HOOD	Dented	737.00 FL	*737.00 FL
11	1		*HINGE,HOOD,LH	Not Necessary	56.00 FL	*- FL
12	1		*HINGE,HOOD,RH	Not Necessary	56.00 FL	*- FL
13	1		*LATCH,HOOD	Not Necessary	69.00 FL	*- FL
14	1		*FENDER,FR RH	Dented	500.00 FL	*500.00 FL
15	1		*SHIELD,FR WHEELHOUSE RH	Not Necessary	98.00 FL	*- FL
16	6		*CLIP,INNERSHIELD	Not Necessary	24.00 FL	*- FL
17	1		*REINFORCEMENT,FR BUMPER	Not Necessary	469.00 FL	*- FL
18	1		*HEADLAMP ASSY,RH	Broken	663.00 FL	*663.00 FL
19	1		*LAMP ASSY,FOG,FR LH	Broken	305.00 FL	*305.00 FL
20	5		*CLIP,FR BUMPER	Necessary	20.00 FL	*20.00 FL
21	1		*INSULATOR,HOOD	Torn	177.00 FL	*177.00 FL
22	8		*CLIP,HOOD INSULATOR	Necessary	24.00 FL	*24.00 FL
23	1		*SUNDRIES	Necessary	20.00 FS	*20.00 FS
24	1		*BODY PNL SEALANT	Necessary	80.00 FS	*40.00 FS
25	1		*PANEL ASSY,FR END (Supplementary)	Dented	1,055.00 FL	*1,055.00 FL
26	1		*TANK,WINDSHIELD WASHER (Supplementary)	Crushed	75.00 FL	*75.00 FL
27	1		*CLIP,HOOD LOCKING (Supplementary)	Necessary	4.00 FL	*4.00 FL
28	1		*LLC (4L) (Supplementary)	Necessary	26.00 FL	*26.00 FL
29	1		*EMBLEM ECO (Supplementary)	Necessary	17.00 FS	*17.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	6,200.00	4,509.00
- List Item Discount on L Items 23.00/23.00% (\$\$)	1,399.09	1,019.36
Total Parts (\$\$)	4,800.91	3,489.64

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	*OD/TP Case (Insurer)	-	0.00
Sub Total (\$\$)			0.00	0.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	RENEW FR BUMPER,BONNET & RHF FENDER,REPAIR FR SUPPORT PNL	New	1,800.00	1,125.00
2	RESPRAY FR BUMPER,BONNET,RHF FENDER & FR SUPPORT	New	1,400.00	1,050.00
3	CHECK WIRING ELECTRICAL WIRING	New	30.00	30.00
4	TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM	New	120.00	120.00
5	APPLY ANTI CORROSION ON AFFECTED AREAS	New	80.00	0.00
6	REPLACE FRONT SUPPORT PANEL (Supplementary)	New	450.00	450.00
7	REMOVE & REFIT AIRCON CONDENSER & RADIATOR ASSY (Supplementary)	New	100.00	100.00
8	SPRAY PAINT FRONT SUPPORT PANEL (Supplementary)	New	350.00	350.00
9	VACUUM & TOP UP AIRCON GAS (Supplementary)	New	80.00	80.00
Gross Labour Cost (\$\$)			4,410.00	3,305.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >