

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG21012807/ATCE2

Date: 25/02/2022

REFERENCE

Insured/Claimant: LIEW SHUE CHING CAROL Policy No: 2100498703-04
Date of Loss: 14/12/2021 Nature of Claim: OD Claim No: 8501360246SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLK6084T**
Make & Model: AUDI A4, 1.4 TFSI S TRONIC (A) Engine No: CVN024435
Reg. Date: 20/01/2017 (Man. Year: 2016) Chassis No: WAUZZZF49HA067453
Colour: White Odometer: 54859 km
Engine Capacity: 1395 cc
Market Value/New Car Price: S\$80,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/60 R16 Rear Tyre Size: 205/60 R16
Front Left Side: Pirelli 6 mm Rear Left Side: Pirelli 6 mm
Front Right Side: Pirelli 6 mm Rear Right Side: Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,956.00	3,692.72	6,263.28	62.91
Miscellaneous Items	0.00	0.00	0.00	
Labour	13,162.00	5,142.00	8,020.00	60.93
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	23,118.00	8,834.72	14,283.28	61.78
- Excess (S\$)	600.00	600.00	0.00	0.00
(S\$)	22,518.00	8,234.72	14,283.28	63.43
+ GST 7.00/7.00% (S\$)	1,576.26	576.43	999.83	63.43
Nett Amount (S\$)	24,094.26	8,811.15	15,283.11	63.43

INSPECTION

Date of Assignment: 20/12/2021
Date Inspected: 17/12/2021 Inspected At: Premium Automobiles Pte Ltd (UBI)
55 Ubi Road 1
Singapore 408699
Estimated Period of Repair: 6.0 days

Adjuster: ADRIAN LING

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR SIDE PANEL TRIM - RH	Repair	3,034.00 FS	*- FS
2	1		*REAR DOOR	Dented	3,192.00 FS	*2,553.60 FS
3	1		*BONDING AGENT	Not Necessary	49.00 FS	*- FS
4	1		*CLEANING SOLUTION	Not Necessary	68.00 FS	*- FS
5	1		*APPLICATOR	Not Necessary	8.00 FS	*- FS
6	1		*REAR DOOR SEALING STRIP	Not Necessary	17.00 FS	*- FS
7	1		*REAR DOOR ATTACHEMENT PARTS	Not Necessary	860.00 FS	*- FS
8	1		*REAR DOOR CATCH - RH	Not Necessary	120.00 FS	*- FS
9	1		*REAR WHEEL HOUSING LINER - RH	Not Necessary	240.00 FS	*- FS
10	1		*REAR WHEEL HOUSING LINER ATTACHEMENT PARTS (NPA)	Not Necessary	0.00 FS	*- FS
11	1		*ALUMINIUM RIM	Cut	983.00 FS	*786.40 FS
12	1		*ACRYLIC SEALANT	Not Necessary	180.00 FS	*- FS
13	1		*CAVITY WAX	Not Necessary	140.00 FS	*- FS
14	1		*STONE CHIP	Necessary	180.00 FS	*180.00 FS
15	1		*METAL FILLER POWDER	Not Necessary	280.00 FS	*- FS
16	1		*SUNDRIES	Necessary	400.00 FS	*8.72 FS
17	1		*REAR OUTER DOOR SEAL - RH	Necessary	205.00 FS	*164.00 FS
F=Franchise part. S=SpcNett.						
Total Parts (S\$)					9,956.00	3,692.72

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND REINSTALL REAR PARKING AID AND REAR LID KICK SENSOR. CHECK FUNCTION	New	360.00	360.00
2	TO REMOVE AND TRANSFER RHS REAR DOORS MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES	New	350.00	280.00
3	TO REMOVE AND REINSTALL RHS FRONT DOOR PANEL TRIM. TO REMOVE AND REINSTALL RHS WING MIRROR ASSY TO FACILITATE RESPRAY OF RHS FRONT DOOR	New	280.00	280.00
4	TO RMEOVE AND REINSTALL REAR SEAT ASSY, ABCD PILLAR TRIMS, SILL TRIMS, FLOOR CARPET, ELECTRONIC COMPONENTS AND FUSE TRAYS. DISENGAGE RHS SEAT BELT AND HEAD AIRBAG	New	1,800.00	0.00
5	TO DISMANTLE AND REINSTALL REAR BUMPER. TO RENEW RHS DOOR. TO CUT OUT AND WELD RHS SILL PANEL. TO REPAIR RHS REAR FENDER AND RHS FRONT DOOR. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	4,900.00	1,000.00
6	TO RESPRAY REAR BUMPER, DOOR HANDLE, RHS REAR DOOR, RHS FRONT DOOR, RHS REAR FENDER, RHS SILL PANEL AND DOOR ENTRANCE	New	5,000.00	2,750.00
7	TO RENEW RHS REAR RIM AND CARRY OUT WHEEL ALIGNMENT	New	280.00	280.00
8	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (\$\$)			13,162.00	5,142.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >