



# National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHA 7726T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	FRT BUMPER COVER	DENTED	430.90	430.90
10	FRT BUMPER CLIPS	NECESSARY	22.00	22.00
1	FRT BUMPER SIDE BRACKET RH	NECESSARY	28.00	28.00
1	HEADLAMP RH	SERVICEABLE	1,993.65	-
1	FRT FENDER SHIELD RH	SERVICEABLE	164.70	-
1	FRT FENDER RH	DENTED	588.80	588.80
1	EMBLEM BLUE-DRIVE RH	NECESSARY	26.60	26.60
1	FRT WHEEL HUB CAP RH	SERVICEABLE	346.40	-
1	FRT BUMPER SIDE MOULDING RH	SERVICEABLE	186.90	-
	LESS 20% DISCOUNT		-757.59	-219.26
			3,030.36	877.04
<b><u>SPECIAL NETT ITEMS</u></b>				
1	FRT TYRE RH (SN)	SERVICEABLE	216.00	-
1	FRT FENDER ADVERTISEMENT LOGO RH (SN)	NECESSARY	100.00	100.00
			316.00	100.00
<b><u>LABOUR</u></b>				
	PANEL BEATING.		1,050.00	700.00
	SPRAY PAINTING CHARGE.		600.00	500.00
	FRT WHEEL ALIGNMENT.	NOT NECESSARY	120.00	-
	CHECK ALL LIGHTING.		60.00	20.00
			1,830.00	1,220.00
<b>GRAND TOTAL</b>			<b>5,176.36</b>	<b>2,197.04</b>
<b>RECOMMENDED COST OF REPAIRS (CONFIRMED)</b>				<b>2,197.04</b>

Report Ref No. NS/INC21012811/Vqcn2

THEVAN THOMAS KARTHIKESAVAN

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,  
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.