

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS3/AIG21012812/EVF3E2**Date:** 27/12/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070152652
Claimant Vehicle No :	SMT2230E	Insured Vehicle No :	SMV9866P
Date of Loss:	16/12/2021	Nature of Claim:	TP
		Claim No:	1079154909SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMT2230E		
Make & Model:	HONDA VEZEL, 1.5 (A)	Engine No:	LEB6744067
Reg. Date:	01/04/2020 (Man. Year: 2018)	Chassis No:	RU31324057
Colour:	Black	Odometer:	52826 km
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Michelin 4 mm	Rear Left Side:	Michelin 4 mm
Front Right Side:	Michelin 4 mm	Rear Right Side:	Michelin 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	20/12/2021	Car Laboratories Pte Ltd (HQ)
Date Inspected:	20/12/2021 Inspected At:	1 BUKIT BATOK CRESCENT, #04-56 WCEGA PLAZA
Estimated Period of Repair:	7.0 days	Singapore 658064

Adjuster: CHEN TSUE YEE**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

MARKET VALUE: \$97,000.00 (EST)

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR NUMBER PLATE GARNISH	Cut	0.00 F	*- F
2	1		*REAR BUMPER	Dented	0.00 F	*- F
3	2		*REAR BUMPER SIDE	* Check	0.00 F	*- F
4	1		*REAR BUMPER CLIPS	Necessary	0.00 F	*- F
5	2		*REAR BUMPER SIDE RETAINER	Broken	0.00 F	*- F
6	1		*REAR BUMPER REFLECTOR	* Check	0.00 F	*- F
7	1		*REAR BUMPER LOWER SPOILER	* Check	0.00 F	*- F
8	1		*REVERSE SENSOR	Broken	0.00 F	*- F
9	1		*REAR END PANEL	Dented	0.00 F	*- F
10	1		*REAR END PANEL TOP GARNISH	* Check	0.00 F	*- F
11	1		*TAILGATE	Dented	0.00 F	*- F
12	2		*TAILGATE EMBLEM	Necessary	0.00 F	*- F
13	1		*TAILGATE MOULDING	Necessary	0.00 F	*- F
14	1		*TAILGATE GARNISH	* Check	0.00 F	*- F
15	2		*TAILGATE LAMP	* Check	0.00 F	*- F
16	1		*TAILGATE TRIM BOARD	* Check	0.00 F	*- F
17	1		*TAILGATE GLASS SEALANT	Necessary	0.00 F	*- F
18	1		*TAILGATE LOCK	Bent	0.00 F	*- F
19	1		*TAILGATE RUBBER	Torn	0.00 F	*- F
20	1		*SPARE TYRE BOARD	* Check	0.00 F	*- F
21	1		*SPARE TYRE PANEL	Repair	0.00 F	*- F
22	1		*SPARE TYRE TRAY	* Check	0.00 F	*- F

F=Franchise part.

Total Parts (S\$)
0.00
0.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >