12/27/21, 9:20 AM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/TMI21012821/KVF3N2

27/12/2021 Date:

REFERENCE

Handling Insurer: Tokio Marine Insurance Singapore Ltd Policy No: MS009738 **Claimant Vehicle**

SMZ6960Z Insured Vehicle No: SMD8697L No:

Date of Loss: 17/12/2021 Nature of Claim: ΤP Claim No: M2105856

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SMZ6960Z

TOYOTA PRIUS, 1.5 (A) Make & Model: 2ZR2G83266 Engine No:

Reg. Date: Chassis No: 12/05/2021 (Man. Year: 2020) JTDKB3FU103091616

Colour: Metallic Pearl White/Red Odometer: 55817 km

Engine Capacity: 1798 cc Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Engine Modification: Pre-accident Condition: Yes No

CONDITION OF TYRES

Rear Tyre Size: Front Tyre Size: 195/65R15 195/65R15 Front Left Side: Rear Left Side: Sailun 9 mm Dunlop 2 mm Front Right Side: Sailun 9 mm Rear Right Side: Dunlop 2 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		2,813.27	944.60	1,868.67	66.42
Miscellaneous Items		0.00	0.00	0.00	
Labour		4,440.00	470.00	3,970.00	89.41
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
Gros	ss Total (S\$)	7,253.27	1,414.60	5,838.67	80.50
+ GST 7.00	0/7.00% (S\$)	507.73	99.02	408.71	80.50
Nett A	Amount (S\$)	7,761.00	1,513.62	6,247.38	80.50

INSPECTION

Date of Assignment: 20/12/2021

Trans-Cab Services Pte Ltd (HQ) Date Inspected: 20/12/2021 Inspected At:

2 Ang Mo Kio Street 63

Singapore 569111

Estimated Period of Repair: 2.0 days

Adjuster: KENNETH KONG Manager: **VERON CHEN**

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 24 Dec 2021)

Parts: 144 TOYOTA PRIUS 1.5 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SMZ6960Z)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Reference	Amount
1	1		*COVER,REAR BUMPER	Buckled	485.60 FL	_	*485.60 FL
2	1		*REINFORCEMENT SUB-ASSY,REAR BUMPER	Bent	332.70 FL	-	*332.70 FL
3	1		*GUARD,REAR BUMPER,CENTER	Dented/Cut	374.50 FL	-	*374.50 FL
4	1		*COVER,REAR BUMPER,LOWER	Serviceable	22.00 FL	-	*- FL
5	1		*RETAINER,REAR BUMPER SIDE,LH	Serviceable	132.60 FL	-	*- FL
6	1		*RETAINER,REAR BUMPER SIDE,RH	Serviceable	132.60 FL	-	*- FL
7	1		*PANEL SUB-ASSY,BODY LOWER BACK	Repair	651.00 FL	-	*- FL
8	1		*COVER,DECK TRIM,REAR	Serviceable	126.70 FL	-	*- FL
9	1		*SET PARKING AID	Serviceable	700.00 FS	-	*- FS
10	1		*SET REAR BUMPER CLIP	Necessary	85.00 FS	-	*50.00 FS
11	1		*BUMPER CENTRE GUARD CLIP	Not Necessary	80.00 FS	-	*- FS
12	1		*REAR BUMPER PROTECTOR	Not Necessary	180.00 FS	-	*- FS
13	1		*REAR BUMPER RETAINER CLIP	Not Necessary	75.00 FS	-	*- FS
F=Fra	anchise	part. S=Spc	Nett. L=ListItemDisc.				
				Sub Total (S\$)	3,377.70	1,242.80	
			- List Item Discount on L Items 2	25.00/25.00% (S\$)	564.43	298.20	
				Total Parts (S\$)	2,813.27		944.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	TO RUST-PROOFING AND APPLY UNDERCOAT OF THE AFFECTED AREAS	New	240.00	0.00
2	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH, FITTINGS AND OTHER,TO ENABLE REPAIR	New	380.00	0.00
3	PANEL BEATING,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS,ADJUST AND REALIGN THE SAME	New	1,400.00	200.00
4	TO TRANSFER OF REAR END PANEL FITTINGS,ATTACHMENT TO FACILITATE BODYWORK REPAIR	New	380.00	0.00
5	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	1,400.00	220.00
6	TO REMOVE AND REFIT REAR BIG & SMALL W/SCREEN GLASS TO FACILITATE BODYWORK REPAIR	New	300.00	0.00
7	TO REINSTALL REAR BUMPER PARKING SENSOR	New	170.00	50.00
8	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	0.00
	Gross Labou	r Cost (S\$)	4,440.00	470.00
	Report was unsubmitted during this	print-out.		

< END OF ESTIMATES >