

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #07-16
Singapore 079120

Our File No: CS/AIG21012822/ETF3E2**Date:** 16/03/2022**REFERENCE**

Insured/Claimant:	CHOY KIN MAN	Policy No:	7210020823	
Date of Loss:	18/12/2021	Nature of Claim:	OD	Claim No: 2261970621SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMY4741H		
Make & Model:	CITROEN C4, 1.2 PURETECH EAT6 (A)	Engine No:	10TMA30041489
Reg. Date:	10/03/2021 (Man. Year: 2020)	Chassis No:	VF73AHNS4LJ595358
Colour:	Silver	Odometer:	14982 km
Engine Capacity:	1199 cc		
Market Value/New Car Price:	S\$125,000.00		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	Yokohama 5 mm	Rear Left Side:	Yokohama 5 mm
Front Right Side:	Yokohama 5 mm	Rear Right Side:	Yokohama 5 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,322.40	8,080.40	3,242.00	28.63
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,585.00	4,025.00	1,560.00	27.93
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	16,907.40	12,105.40	4,802.00	28.40
- Excess (\$\$)	300.00	300.00	0.00	0.00
(\$\$)	16,607.40	11,805.40	4,802.00	28.91
+ GST 7.00/7.00% (\$\$)	1,162.52	826.38	336.14	28.91
Nett Amount (\$\$)	17,769.92	12,631.78	5,138.14	28.91

INSPECTION

Date of Assignment:	20/12/2021	
Date Inspected:	20/12/2021 Inspected At:	Cycle & Carriage France Pte Ltd (Pandan Gardens) (HQ) 209 PANDAN GARDENS Singapore 609339
Estimated Period of Repair:	5.0 days	

Adjuster: CHEN TSUE YEE**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FR NUMBER PLATE WITH CASING	Cut	50.00 FS	*50.00 FS
2	1		*SUNDRIES	Necessary	30.00 FS	*20.00 FS
3	1		*FRONT BUMPER	Broken	1,074.00 FL	*1,074.00 FL
4	1		*BUMPER BRACKET	Broken	330.00 FL	*330.00 FL
5	1		*BUMPER MOULDING	Broken	207.00 FL	*207.00 FL
6	1		*BUMPER MOULDING	Broken	227.00 FL	*227.00 FL
7	1		*BMPR RUBBR BOOT	Broken	363.00 FL	*363.00 FL
8	1		*GUARD GRILLE INFERIEUR	Broken	311.00 FL	*311.00 FL
9	1		*BADGE SUPPORT	Broken	205.00 FL	*205.00 FL
10	1		*CHEVRON EMBLEM SUPERIEUR	Broken	161.00 FL	*161.00 FL
11	1		*CHEVRON EMBLEM INFERIEUR	Broken	161.00 FL	*161.00 FL
12	1		*BRACKET SET	Broken	125.00 FL	*125.00 FL
13	1		*BUMPER MOULDING	Not Necessary	173.00 FL	*- FL
14	1		*BRACKET SET LAT	Broken	125.00 FL	*125.00 FL
15	1		*ABSORBERS SET	Not Necessary	92.00 FL	*- FL
16	1		*BUMPER BRACKET	Dented	516.00 FL	*516.00 FL
17	1		*BUMPER BRACKET	Not Necessary	224.00 FL	*- FL
18	1		*PLUG LH	Not Necessary	96.00 FL	*- FL
19	1		*REAR DUCT RH	Broken	119.00 FL	*119.00 FL
20	1		*REPAIR SET	Not Necessary	92.00 FL	*- FL
21	1		*FACE CROSSMEMBER SUP	Broken	226.00 FL	*226.00 FL
22	1		*FACE CROSSMEMBER INF	Not Necessary	91.00 FL	*- FL
23	1		*AIR BULKHEAD LH	Not Necessary	108.00 FL	*- FL
24	1		*AIR BULKHEAD RH	Broken	108.00 FL	*108.00 FL
25	1		*AIR BULKHEAD	Broken	154.00 FL	*154.00 FL
26	1		*BRACKET CROSSME RH ASS	Not Necessary	197.00 FL	*- FL
27	1		*FACING SUPPORT RH ASS	Not Necessary	202.00 FL	*- FL
28	1		*FR MIN BPR FIX	Not Necessary	252.00 FL	*- FL
29	1		*FRONG WING RH ASS	Dented	571.00 FL	*571.00 FL
30	1		*MUDGUARD RH ASS	Not Necessary	159.00 FL	*- FL
31	1		*ENGINE BONNET ASS	Dented	1,042.00 FL	*1,042.00 FL
32	1		*BONNET HINGE LH	Not Necessary	178.00 FL	*- FL
33	1		*BONNET HINGE RH	Not Necessary	178.00 FL	*- FL
34	1		*SOUND PROOFING	Crushed	235.00 FL	*235.00 FL
35	1		*BONNET LOCK	Not Necessary	54.00 FL	*- FL
36	1		*DISTRIB CHAMBER	Not Necessary	840.00 FL	*- FL
37	1		*DIST CHB BRACKT	Not Necessary	43.00 FL	*- FL
38	1		*DIST CHB BRACKT	Not Necessary	43.00 FL	*- FL
39	1		*DIST CHB BRACKT	Not Necessary	43.00 FL	*- FL
40	1		*RADIATOR NEW	Dented	642.00 FL	*663.00 FL
41	1		*CONDENSER	Dented	1,175.00 FL	*1,175.00 FL
42	1		*CONDENS BRACKET	Not Necessary	58.00 FL	*- FL
43	1		*COND DEFLECTOR	Not Necessary	72.00 FL	*- FL
44	1		*SENSOR-CTR	Not Necessary	192.00 FL	*- FL
45	1		*SENSOR-OUTER	Not Necessary	273.00 FL	*- FL
46	1		*SENSOR-SIDE	Not Necessary	273.00 FL	*- FL
47	1		*FRONT LIGHT RH	Broken	409.00 FL	*409.00 FL
48	1		*FOG HEADLIGHT - RH	Not Necessary	128.00 FL	*- FL
49	1		*HEADLIGHT ASSY RH	Broken	718.00 FL	*718.00 FL
50	1		*BUMPER MOULDING (Supplementary)	Broken	328.00 FL	*328.00 FL
51	1		*LOW FR PAN FIX (Supplementary)	Broken	158.00 FL	*158.00 FL
52	1		*BUMPER BRACKET (Supplementary)	Broken	194.00 FL	*194.00 FL
53	1		*COOLING LIQUID DRUM 2L PAE-35 (2 PCS) (Supplementary)	Necessary	50.00 FL	*50.00 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
54	1		*HEAT SHIELD (Supplementary)	Dented	58.00 FL	*58.00 FL
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (S\$)					14,133.00	10,083.00
- List Item Discount on L Items 20.00/20.00% (S\$)					2,810.60	2,002.60
Total Parts (S\$)					11,322.40	8,080.40

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	RENEW FR BUMPER, BONNET, RHF FENDER & FR SUPPORT	New	2,500.00	1,250.00
2	RESPRAY FR BUMPER, BONNET, FR SUPPORT & RHF FENDER	New	1,520.00	1,520.00
3	REMOVE & REFIT AC COND & RADIATOR	New	100.00	100.00
4	TOP UP AC GAS	New	500.00	500.00
5	REMOVE & REFIT AIR DISTRIBUTOR CHAMBER	New	250.00	0.00
6	CHECK WIRING ELECTRICAL SYSTEM	New	50.00	50.00
7	TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM	New	225.00	225.00
8	REMOVE & REFIT FR PARKING ASSIST SENSOR	New	50.00	50.00
9	APPLY ANTI CORROSION ON AFFECTED AREAS	New	60.00	40.00
10	SUPPLY BODY PNL SEALANT	New	80.00	40.00
11	REPAIR FRONT SUPPORT PANEL (Supplementary)	New	250.00	250.00
Gross Labour Cost (\$\$)			5,585.00	4,025.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >