1/14/22, 2:43 PM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI21012823/EVY3N2

14/01/2022 Date:

REFERENCE

China Taiping Insurance Handling Insurer:

(Singapore) Pte. Ltd.

Policy No:

DMCVSNW00033832103

Claimant Vehicle

GBJ7339B

Insured

GBE8593C

No:

Vehicle No:

Date of Loss:

08/12/2021

Nature of Claim: TP

Claim

Odometer:

SNM21D207144/C02/LEEPG

25507 km

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBJ7339B**

PEUGEOT PARTNER, 1.5 (A) 10Q3BN0006512 Make & Model: Engine No: Reg. Date: 25/07/2019 (Man. Year: 2019) Chassis No: VR3EFYHZRKJ662041

Colour: Black

Engine Capacity: 1499 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): **Engine Modification:** Pre-accident Condition: Yes Nο

CONDITION OF TYRES

Front Tyre Size: 205/60R16 Rear Tyre Size: 205/60R16 Front Left Side: Rear Left Side: Goodvear 4 mm Goodvear 4 mm Front Right Side: Goodyear 4 mm Rear Right Side: Goodyear 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,995.30	1,433.70	561.60	28.15
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,080.00	830.00	250.00	23.15
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	3,075.30	2,263.70	811.60	26.39
Approved Total (Overridden) (S\$)		1,800.00		
Nett Amount (S\$)	3,075.30	1,800.00	1,275.30	41.47

INSPECTION

Date of Assignment: 20/12/2021

Xinya Auto Services Pte Ltd (HQ) Date Inspected: 20/12/2021 Inspected At:

Blk 1002, #01-75, Bukit Merah Lane 3

Singapore 159719

Estimated Period of Repair: 4.0 days

Adjuster: **CHEN TSUE YEE** Manager: **VERON CHEN**

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 14 Jan 2022)

Parts: N/A PEUGEOT PARTNER 1.5 (A) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for GBJ7339B)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Broken	367.00 FL	*367.00 FL
2	1		*FRONT RH FENDER	Dented	967.00 FL	*430.00 FL
3	1		*FRONT RH RETAINER	Broken	98.00 FL	*98.00 FL
4	1		*FRONT RH HEADLAMP	Broken	637.00 FL	*550.00 FL
5	1		*FRONT RH SPLASHGUARD	Torn	148.00 FL	*148.00 FL
F=Fra	anchise	part. L=ListItemD	isc.			
				Sub Total (S\$)	2,217.00	1,593.00
			- List Item Discount on L Item	s 10.00/10.00% (S\$)	221.70	159.30
				Total Parts (S\$)	1,995.30	1,433.70
			Report was unsubmitted duri	ng this print-out.		

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Lab</u>	our Items			
1	TO REMOVE & REPLACE FRONT BUMPER, FENDER, HEADLAMP & PANEL BEAT & ALIGN	New	600.00	400.00
2	TO PUTTY & SPRAY PAINT FRONT RH FENDER	New	400.00	400.00
3	TO CHECK & RECTIFY WIRING	New	80.00	30.00
	Gross Labou	ır Cost (S\$)	1,080.00	830.00
	Report was unsubmitted during this	print-out.		

< END OF ESTIMATES >